

Underground Storage Tank System Evaluation Final Report

Red Hill Bulk Fuel Storage Facility Joint Base Pearl Harbor-Hickam

June 2017

Submitted to:

U.S. ENVIRONMENTAL PROTECTION AGENCY

REGION 9

75 Hawthorne Street

San Francisco, CA 94105



Submitted by:

Atlas Geotechnical

Eastern Research Group, Inc.

PEMY Consulting

Powers Engineering and Inspection, Inc.

Date of Report: June 13, 2017

Date of Evaluation: May 9 to 12, 2016

Weather: Sunny, Approximately 75° Fahrenheit

Facility Owner: Department of the Navy

Facility Address: Red Hill Bulk Fuel Storage Facility
Building 1757 (Administrative Office)
Joint Base Pearl Harbor-Hickam
Pearl Harbor, HI 96860

Facility Phone: (808) 473-7801 (John Floyd, Deputy Director)

Inspector(s): Jade Geronimo, Powers Engineering and Inspection, Inc.
Ryan Hubbard, Aspen Controls
Christopher Krejci, Eastern Research Group, Inc.
Steven Linder, U.S. EPA
Phil Myers, PEMY Consulting
Bobby Ojha, U.S. EPA
Gary Powers, Powers Engineering and Inspection, Inc.
Omer Shalev, U.S. EPA
Doug Schwarm, Atlas Geotechnical
Roy Ilaga, Hawaii Department of Health
George Tabil, Hawaii Department of Health

TABLE OF CONTENTS

I.	OBJECTIVE	1
II.	GENERAL FINDINGS	1
III.	REGULATORY BACKGROUND AND INDUSTRY STANDARDS	1
IV.	RED HILL INFRASTRUCTURE	3
V.	FACILITY OPERATIONS	10

ATTACHMENTS

ATTACHMENT A: RED HILL FACILITY EPA AND HDOH SITE VISIT AGENDA
ATTACHMENT B: ERG PHOTOGRAPH LOG
ATTACHMENT C: RELEASE DETECTION RECORDS
ATTACHMENT D: RECENT CATHODIC PROTECTION SYSTEM RECTIFIER READINGS

I. OBJECTIVE

The United States Environmental Protection Agency (EPA) Region 9 requested that a team of subject matter experts including ERG conduct a baseline evaluation of the underground storage tank (UST) system and peripheral equipment at the Red Hill Bulk Fuel Storage Facility (Red Hill Facility) under EPA's Contract Number EP-W-15-006, Work Assignment ERG-1-11. The purpose of the baseline evaluation was to provide an overall assessment of the Facility's ability to be operated in a manner that prevents release of fuel into the environment.

II. GENERAL FINDINGS

To achieve the objective of the baseline assessment, the evaluation team undertook to verify the operational status of the UST system with respect to industry standards, UST requirements of Resource Conservation and Recovery Act (RCRA) Subtitle I under 40 CFR Part 280, and Hawaii's state-specific regulations.

ERG has 15 years of experience supporting EPA in analyzing aboveground storage tanks (ASTs) and USTs and assessing compliance with tank regulations. ERG supported the assessment by evaluating the facility's operations against existing and likely forthcoming state and federal UST requirements for field-constructed tanks. To augment ERG's experience, ERG collaborated with Aspen Controls (AC), Atlas Geotechnical (AG), PEMY Consulting (PEMY), and Powers Engineering and Inspection (PEI). AC has more than 30 years of specialized experience focusing on tank gauging systems as well as automation and control systems. AC was tasked with evaluating the control systems used in the facility to handle all fuel transfer and storage operations. Their primary focus was to review the level gauging system and overfill alarm system for the storage tanks and compare them to systems found in typical petroleum industry terminals. PEMY has more than 30 years of experience specializing in tanks and piping ownership issues, including environmental analyses, reliability, and risk management. AG has more than 40 years of experience specializing in geomechanics and geotechnical risk management. PEMY and AG evaluated the facility's tanks and piping from a reliability and risk management perspective. PEI has more than 28 years of experience inspecting and managing fuel systems, including tanks, pipes, and pressure vessels. PEI was tasked with evaluating the facility's tank and piping inspections, as specified in API Standards 579, 650, and 653.

The assessment occurred on May 9 through 12, 2016. On the morning of May 9, the evaluation team first met with Mr. Steve Turnbull, Red Hill Facility Regional Program Director, at the facility's security gate and proceeded to enter the facility. Upon arrival at the facility, the Navy provided an introductory presentation on the facility's operations and the evaluation team proceeded according to the schedule summarized in Attachment A. Over the first three days of the assessment, the evaluation team viewed the main areas of the facility associated with the UST system, including the Hotel Pier, control room, pumphouse, Surge Tunnel, Upper and Lower Tank Galleries, Tank 5 (inside view), Harbor Tunnel, Upper Tank Farm (AST farm), and truck loading rack. On May 12, 2016, the assessment closed with an exit conference that included representatives from the Navy and Hawaii Department of Health (HDOH). Mr. Jade Geronimo, PEI, and Mr. Christopher Krejci, ERG, took photographs during the assessment. Attachment B contains ERG's photographs. PEI's photographs were provided separately to EPA Region 9 staff by Secure Digital (SD) card.

The evaluation team did not identify areas of noncompliance with current state or federal regulations; however, most of the regulations for UST systems were not yet in effect at the Red Hill Facility, due to EPA's deferral of regulations for field constructed tanks. The evaluation team generally found that systems and management practices in place at the Red Hill Facility meet or exceed best practices for petroleum terminals and bulk fuel storage facilities.

III. REGULATORY BACKGROUND AND INDUSTRY STANDARDS

In 2015, EPA revised the UST regulations and added new requirements for field constructed tanks. EPA's summary of the new regulations can be found at <https://www.epa.gov/ust/field-constructed-tanks-and-airport-hydrant-systems-2015-requirements>. Federal UST regulations can be found at 40 CFR Part 280. Hawaii UST regulations can be found in the Hawaii Administrative Rules, Chapter 11-281. A brief summary of the regulations applicable to the Red Hill Facility beginning October 13, 2018, is provided below.

- **Tank Release Detection** – Field constructed tanks with a capacity greater than 50,000 gallons must meet either the release detection requirements in Subpart D (except groundwater monitoring and vapor monitoring

must be combined with inventory control as described below) or use one or a combination of the following alternative methods of release detection:

- Conduct an annual tank tightness test that can detect a 0.5-gallon-per-hour (gph) leak rate;
- Use an ATG system to perform release detection at least every 30 days. This method must be combined with a tank tightness test that can detect a 0.2 gph leak rate. The ATG must achieve a one gph detection limit in combination with a tank tightness test every three years or a two gph detection limit in combination with a tank tightness test performed every two years.
- Perform vapor monitoring using a tracer compound placed in the tank system capable of detecting a 0.1-gph leak rate at least every two years;
- Inventory control at least every 30 days that can detect a leak equal to or less than 0.50 percent of flow-through combined with one of the following:
 - A tank tightness test that can detect a 0.5-gph leak rate at least every two years;
 - Vapor or ground water monitoring at least every 30 days; or
- Another method approved by the implementing agency.
- **Piping Release Detection** – Owners and operators of underground piping¹ associated with field-constructed tanks greater than 50,000 gallons must follow either the release detection requirements in Subpart D (except ground water monitoring and vapor monitoring must be combined with inventory control as described below) or use one or a combination of the following alternative methods of release detection:
 - Perform a semiannual or annual line tightness test at or above the operating pressure that meets the detection limits specified in the regulations (0.5 to 1.5 gph depending on piping section volume);
 - Perform vapor monitoring using a tracer compound capable of detecting a 0.1-gph leak at least every two years;
 - Combine inventory control at least every 30 days that can detect a leak equal to or less than 0.50 percent of flow-through with one of the following:
 - A line tightness test;
 - Vapor monitoring or ground water monitoring at least every 30 days; or
 - Another method approved by the implementing agency.
- **Spill Prevention** – Field constructed tanks must meet the same spill requirements as other regulated UST systems. Spill catchment basins (spill buckets) must be either double walled (with periodic monitoring of the integrity of both walls of the spill bucket) or tested periodically for proper operation per the new spill prevention equipment testing requirements.
- **Overfill Prevention** – Field constructed tanks must meet the same overfill requirements as other regulated UST systems. Overfill prevention equipment must be inspected periodically for proper operation according to EPA's 2015 revisions to the overfill prevention equipment testing requirements.
- **Corrosion Protection** – For field constructed UST systems in use as of October 13, 2015, owners and operators must meet corrosion protection requirements for their tanks and piping in contact with the ground that routinely contain regulated substances. Tank and piping materials must be constructed either of fiberglass-reinforced plastic, cathodically protected and coated steel, steel jacketed with a noncorrodible material, or metal without corrosion protection if the tank is determined to not cause a release due to corrosion. All cathodic protection systems must be tested within 6 months of installation and at least every 3 years thereafter.
- **Operator Training** – UST Operators must be trained for Class A, B, and C Operator status. Training requirements for each type of operator are listed at 40 CFR §280.242.

State and federal UST system owners are exempt from meeting financial responsibility requirements.

The most common industry standard by which storage tanks are assessed is the API 653 standard. Although the standard is designed specifically for ASTs, several components of the standard and inspection process have been modified by the Navy and their contractors to assess the integrity and suitability for service of the tanks in

¹ Note that piping associated with the Red Hill USTs is located mostly in tunnels or above ground. Some sections of pipe penetrate the concrete plugs beneath the tanks, concrete support structures for the pipes, or earthen material where the pipelines emerge from the tunnel system.

question. The US Navy has employed a directive or scope of work of inspection to assess the tank using a modified API 653 inspection.

Most API 650/653 designed tanks have surfaces that are externally and internally accessible for inspection. A common design is a cylindrical shape that rests on the ground or concrete which makes the bottom of the tank inaccessible externally. Testing processes like Magnetic Flux Leakage (MFL) scanning of the bottom have been an accepted industry standard to inspect for soil-side corrosion. In many cases, the corrosion rate of the bottom plates is the controlling factor for the tanks suitability for service.

IV. RED HILL INFRASTRUCTURE

IV.a Tanks

IV.a.1. Findings

Upon review of original design drawings and historical documents, overall, key construction components of the tanks exceed or meet most modern day construction standards. Based on a limited review of historical inspection reports, the methods of tank inspection that have been applied at Red Hill were the best that could be implemented with the limitations in place, and no historical issues of concern have been noted related to structural integrity. For the Red Hill Facility tanks, nearly 100 percent of the external surface of the tank cannot be visually inspected. The Navy has scoped out the use of non-destructive testing to inspect the internal surfaces of the Red Hill tanks using the following: low frequency electromagnetic technique (LFET) and BFET (balanced field electromagnetic technique), longitudinal and shear-wave ultrasonic testing. The implemented inspection technologies and methods meet or exceed industry standard.

Limited review of previous inspections indicates no structural integrity, tank verticality, or out-of-roundness issues of immediate concern. Since the main USTs are located approximately 100 feet below ground and encased in concrete with a ¼-in steel liner, concerns of external factors are minimal. Damage mechanisms like distortion of the steel plates or other damage due to stress, seismic events, and settlement, which normally impact an AST are minimal or non-existent.

The evaluation team identified the following findings related to tank leak detection:

- Each tank in operation during the evaluation had successfully passed at least one tightness test with a detection limit of 0.5 gph since October 2014. Tanks 5, 14, 17, and 18 were not recently tested, but they were temporarily out of service during the inspection. Tank 1 and 19 are also permanently out of service.
- The first unscheduled fuel movement (UFM) report generated each month for the five months prior to the evaluation (see Attachment C) demonstrated that each UFM had been resolved in a logical manner based on a detailed investigation of the incident. Based on the observation that the gauges used to generate the UFM's are only accurate to within 3/16 of an inch, however, it can detect inventory losses during operation almost continuously.
- All soil gas data for the past few years were below action levels except near Tank 5 for a few months after the January 2014 release. While this empirically validates the system, no information was available on the leak detection limit for the soil gas system.
- Groundwater samples had the following exceedances in the first quarter of 2016 for Total Petroleum Hydrocarbon - Diesel²:
 - MW01 - 430 µg/L
 - MW02 - 6,500 µg/L
 - MW03 - 150 µg/L
 - OWDF01- 320 µg/L

It should be noted that EPA does not consider the groundwater monitoring activities at the Red Hill Facility to be within the scope of the facility's leak detection activities.

² The HDOH Environmental Action Level is 100 µg/L and Site-Specific Risk Based Level is 4,500 µg/L

IV.a.2. Observations

The Red Hill Facility comprises 24 USTs (including 20 storage tanks and 4 surge tanks) in addition to numerous ASTs and associated piping and equipment. The storage tanks are located at the highest elevation within the facility, whereas the surge tanks are adjacent to the pumphouse located downhill from the storage tanks.

The Department of the Navy constructed the USTs from 1940 to 1943, by excavating native soil and rock from the site, pouring a concrete enclosure for the tanks, covering the native material with gunite, and lining the concrete with carbon steel plates. The UST system has carbon steel, single-wall piping that connects the USTs to filling and dispensing stations at various piers and to a truck loading rack located along Pearl Harbor's shoreline. A pumphouse near the base of the Red Hill Facility provides the pressure required to lift fuel to the USTs. Adjacent to the pumphouse are four surge tanks that provide equalization for pipeline pressure and mitigate the operational issues that could result from the downhill flow of fluids due to the elevation difference across the system (more than 300 feet when the tanks are filled to the maximum allowable fluid level).

On May 9, the evaluation team reviewed available drawings for the Red Hill Facility USTs. On May 10, the evaluation team toured the Red Hill Facility USTs and viewed several pieces of leak detection equipment, including tank gauges, soil gas monitoring wells, and groundwater monitoring wells. The evaluation team also entered and viewed Tank 5 from a catwalk suspended approximately 195 feet above the bottom of the tank.

Based on PEI's review of the general design details, it is most likely that if potential leak paths are present under the steel liner, the product would likely stay between the steel liner and the concrete outer shell. It is possible for small cracks to develop in the steel liner that may allow fuel to escape or water to get behind the steel liner. Most likely these risk items would be at the cold joints near the upper and lower spring lines. The Navy does not currently fill the large USTs at Red Hill above the upper spring line. Historical data notes that water may have gotten under/behind the steel liner. Water can be corrosive to the steel plates over time. PEI suggests that besides cracks in the concrete outer shell, groundwater may have found its way under/behind the steel plates through the path dug to the roof vent or air shaft.

The applicable UST regulations exempt from cathodic protection requirements metal tanks and piping which are encased or surrounded by concrete (80 FR 41565). The 20 main storage USTs and the four surge tanks are encased in concrete, although pipes and nozzles penetrate the concrete plugs that form the tanks' foundations. Impressed current systems provide cathodic protection for several ASTs that are connected to the Red Hill Facility system in the downhill portion of the facility (near the shoreline), as well as an aboveground slop tank located near the Red Hill USTs. See the piping section (Section IV.b) for more information on the evaluation team's assessment of the Red Hill Facility's corrosion protection program.

The Red Hill Facility employs three methods of leak detection: (1) annual tank tightness testing; (2) ATG; and (3) soil gas monitoring. Although the Navy conducts groundwater monitoring, EPA does not consider this activity to be a leak detection method at this site. Each of these methods, including groundwater monitoring, is described in the subsections below. In addition to these methods, the Red Hill Facility previously employed the use of a tell-tale system comprising a series of steel pipes that penetrated the walls of the USTs near the tank bottom to observe fluid outside the steel shell of each tank; however, this system was decommissioned at all of the tanks and is no longer used due to concerns regarding corrosion and vulnerability of the tell-tale piping to leakage.

Tank Tightness Testing

Beginning in 2015, tank tightness testing at the Red Hill Facility occurs on an annual basis for all in-service storage tanks and surge tanks. The tank tightness testing system is Mass Technology Corporation's Mass Technology Precision Mass Measurement System (MTPMMS). It uses a flexible probe inserted to the bottom of the tank through the gauge port on the top of the tank. The device measures the differential pressure between a point at the bottom of the tank and another point immediately above the surface of the fuel, over a period of 5 days when the tank is closed to any fuel transfer. At the conclusion of the test, the tester conducts a statistical trend analysis of the pressure data to determine whether a leak exists. The Navy's consultant reports that this test can detect a total leak of as little as 0.5 gph, with a 95 percent confidence and a five percent probability of false alarm. 0.5 gph is the current detection limit specified in the regulations for tank tightness testing. MTPMMS has been third-party certified for bulk UST leak detection by Wilcox and Associates. It was first piloted at the Red Hill Facility in 2008 using a 2-day test that was reported to have a total leak detection limit of 0.7 gph, and implemented full-scale in 2009. Testing also occurred in 2011 and 2013. Starting in 2014, the testing contractor revised the test method detection limit to 0.5 gph, based on the consistency of previous biennial test data and the

results of a simulated leak evaluation performed by Ken Wilcox Associates, Inc. The tank tightness testing report in Attachment C contains the most recent test records prior to the date of the facility evaluation for all tested storage tanks except Tank 18.

ATG

ATGs on each of the Red Hill Facility tanks are calibrated at least once per year to an accuracy of 3/16 of an inch. The Navy also verifies ATG measurements after each fuel movement with a tape measure calibrated annually by the National Institute of Standards and Technology. Any discrepancies between the ATG measurements and manual gauging greater than 3/16 of an inch³ are investigated to identify potential leaks.

The Navy attempts to detect any unscheduled fuel movements (UFMs), including leaks, from their UST system by collecting and processing ATG data using the Automatic Fuel Handling Equipment (AFHE) System. SPAWAR's contractor, Englobal, administers the AFHE system, and control room operators receive alerts of any potential UFMs. AFHE accounts for volumes that move through the UST system using flow meters, and ATG data combined with strapping charts. Under static conditions (no fuel transfers), AFHE generates a warning alarm any time there is an apparent net loss or gain of more than half an inch of fuel in one of the tanks⁴, and a critical alarm for more than 0.75 inches. During scheduled fuel transfers, AFHE generates a warning alarm for more than one inch and a critical alarm for more than 1.5 inches. The evaluation team interviewed Mr. Teren Young from Englobal, who explained the configuration of the Supervisory Control and Data Acquisition (SCADA) system and the associated instrumentation and equipment. He presented an overview of how the control room interfaces with the instrumentation and how the computer acquires data from the field sensors.

The Navy investigates any UFM alarm and documents the results of the investigation in a UFM report. The Navy also conducts a visual trend analysis of ATG data using Excel Graphs that cover from several months to more than a year. During the assessment, interviews with Navy staff and reviews of relevant documents did not indicate that the Navy had made a formal determination as to the ATG's limit of detection (in gph).

Soil Gas Monitoring

ERG reviewed soil gas data for the past few years. The Navy collects soil gas samples from three co-located wells (completed at depths described as "shallow," "medium" and "deep"⁵) at each of the active storage tanks and analyzes them in the field for volatile organic compounds (VOCs) using a photoionization detector (PID). The Navy does not add any tracer compounds to their tank system. The PID displays readings in units of ppb total VOCs. The Navy compares the results to an action level representing half of the calculated vapor concentration for fuel-saturated water (280,000 parts per billion by volume [ppbv] for tanks containing jet fuel and 14,000 ppbv for tanks containing marine diesel).

Groundwater Monitoring

ERG reviewed the quarterly groundwater monitoring report for the first quarter of 2016. The Navy collects groundwater samples from four wells located in the lower access tunnel, one sampling point in the Red Hill Shaft, and five groundwater monitoring wells outside of the Red Hill Facility tunnel system. The Navy collects samples on a quarterly basis and analyzes the samples for petroleum constituents. The Navy compares results to site-specific risk-based levels (SSRBLs) for total petroleum hydrocarbons as diesel fuel (TPH-d) and benzene, as well as HDOH Environmental Action Levels (EALs). The Navy also measures each well in the Red Hill Facility tunnel for the presence of light non-aqueous phase liquids.

IV.a.3. Limitations and Recommendations

Although tank level systems may be able to detect smaller inventory losses, a leak of less than 0.5 gph (4,380 gallons per year) from any of the tanks may not be detectable with the facility's annual tank tightness testing.

³ Note that 3/16 of an inch of product loss in the barrel of a cylindrical tank that is 100 feet in diameter translates to approximately 1,000 gallons of product loss.

⁴ Note that ½ of an inch of product loss in the barrel of a cylindrical tank that is 100 feet in diameter translates to approximately 2,500 gallons of product loss.

⁵ Navy staff were not able to provide information on the specific depths of each well during the evaluation.

IV.b Piping

IV.b.1. Findings

Piping components in the tunnel system between the Red Hill Facility storage tanks and the pumphouse appear to be in generally good condition, as do piping components from the surge tank into the pump manifolds. Although the evaluation team noticed minor surface defects and pitting on the pipeline in some areas (example in Figure 1), there were no major issues observed on the piping. Any potential leak paths in these areas would likely be contained by the tunnel system and the oil-tight doors, and would likely be detected by pressure drops monitored in the control room.

Piping systems at the Upper Tank Farm (where the system's ASTs are located) are in generally good shape and have been designed and maintained to modern standards. Any potential product loss in this area would likely be contained by the liner located beneath the Upper Tank Farm tanks and equipment, and would likely be detectable with a pressure drop in the piping system.

Based on the observation that many of the rectifiers in the downhill portion of the facility exhibited significant changes in voltage and current over the period of time reviewed by the evaluation team, some of the impressed current systems on the piping at the Red Hill Facility may not be functioning properly.

IV.b.2. Observations

After exiting the tanks, the steel pipes run along the side of an open tunnel down to the pumphouse. They are suspended against the wall by a series of steel supports located approximately 30 feet on center. Roughly every 1,000 feet, the pipes penetrate a concrete wall that is approximately 3 feet thick. In some cases, the pipes are in direct contact with the concrete. In others, they are sleeved with various non-metallic materials.

Pipes running between the pumphouse and the filling/dispensing locations (e.g., Hotel Pier, truck rack) also receive cathodic protection from impressed current systems where they emerge from the underground tunnel to the surface. Aboveground piping has a protective layer of noncorrodible material, as shown in Attachment B.

The Navy monitors pressure in each of the three pipelines that convey product between the USTs at the top of the Red Hill Facility tunnel and at the pumphouse. Pressure transducers directly outside the pumphouse report to the main control room. Facility staff noted that any catastrophic release of fuel would be obvious to the control room almost immediately through the drop in pressure observed in the affected pipeline.

In addition to pipeline pressure monitoring, the Navy routinely conducts tightness tests on pipelines near the shoreline that are regulated by the U.S. Coast Guard. The Navy has not yet implemented routine line tightness testing for the portion of the facility uphill from the pump station, but during the evaluation Navy staff noted that they plan to implement routine line tightness in these areas soon.

The Navy has carried out an extensive API 570 inspection of the piping system connecting the pumphouse at Pearl Harbor to the Red Hill Facility tank farm. The API 570 inspection has been performed in addition to 'pigging' of the lines in 2010 and 2015. PEI has reviewed the API 570 inspection reports and concludes that the piping system inspection process meets or exceeds industry standard.

During the evaluation, ERG collected voltage and current readings from the easily accessible rectifiers. However, many of the rectifiers read zero voltage and current, and Red Hill Facility staff indicated that rectifiers are routinely checked using a multimeter, because some of the meters on the rectifiers do not function properly. During the evaluation, ERG requested information on all rectifier readings for the two months prior to the evaluation for all impressed current systems, as well as a summary of what the voltage and current values should be for each item. Attachment D summarizes the data provided by the Navy, along with the maximum percent change observed in the voltage and current over the two-month period of interest.



Figure 1. Example of Pitting on Pipeline in Lower Access Tunnel

After the evaluation, Navy personnel indicated that some of the rectifiers had zero readings as a result of the Upper Tank Farm piping and AST cathodic protection system awaiting repairs at the time of the evaluation. As of May 9, 2017, the cathodic protection contractor has made repairs to all rectifiers with the exception of rectifiers 9, 12, and 13 which are scheduled for repair in June 2017. Navy personnel noted that the cathodic protection system has a number of redundancies that still enable cathodic protection coverage with the noted rectifiers off line.

IV.b.3. Limitations and Recommendations

None.

IV.c Controls

IV.c.1. Findings

The Red Hill Facility control system contains all of the expected components and features, and is by far exceeding industry standards by upgrading a system that is only 10 to 12 years old.

IV.c.2. Observations

During the evaluation, Navy personnel noted that the facility was in the middle of a “refresh” of the entire instrumentation system. The old system was systematically being replaced with a new system in phases. The inspection focused on both the current system in use and the evaluation of the new system being installed.

As with any facility handling fuel storage and movements, there is a central computer server that is controlling and monitoring the whole facility. These systems are generally called SCADA systems and have many different configurations determined by the needs of the facility. The SCADA system that was installed at the Red Hill Facility is quite large in scale and scope for the needs of this facility. This server also acts as the alarm logging and history database for the facility and stores all the data to be retrieved at any time. Also, there is a redundant computer server that is always running and mirroring the data in the main server that can take over immediately in case of a computer malfunction. The main control room for the facility is where the HMI (Human Machine Interface) is located for the operator. This is the primary workstation during normal operations. There is always an operator at these controls during normal conditions (24 hours per day, 7 days per week) and additional operators are used during all cargo movements within the facility to assist the main operator. There are also remote workstations located in other locations where full access to the SCADA system is available anytime. These locations are mainly used in the event of a failure in the main control room or other emergency.

From the central operations room, almost every aspect of the operations can be controlled and monitored in real time. The server acts as the master controller for the whole facility. The server communicates and controls the equipment by connecting through a series of PLCs (Programmable Logic Controllers). Through the PLCs, the operator can control valves, pump and receive levels, pressures, flows and temperatures. The SCADA server also handles all alarms and shutdowns. The SCADA system monitors all parameters of the field instruments and will alarm and shutdown necessary systems when the values have gone into alarm. Most alarms in the system are “hard coded” in the system, meaning there is no way for the operator to change or override the alarms in the system. The operator can set “service or operational limits” in the system to assist them in tracking the progress of cargo operations. The server also has video and facility access security systems tied in so the operator can view of these areas.

The design of the SCADA system at Red Hill Facility is one that allows for complete control of the facility and allows for ease of future expansion and/or isolation of systems that might be out of service for repairs.

The new SCADA system being installed is very similar in design and application but it is being updated with new PLCs and computer servers for reliability and future upgrades. The system is also being set up with remote workstations just like the previous system. Most industrial facilities are running SCADA systems that are more than 10 years old unless they have gone through a recent upgrade.

The purpose of the SCADA system is to show the values from all field instruments. The Red Hill Facility has just under 800 field instruments and all of these instruments are inventoried and controlled through a computer tracking system. Each instrument is assigned a bar code that can be scanned into the computer system and a complete history of this device can be accessed. The computer system also keeps track of the calibration requirements for each instrument. Through the computer system, a general service/calibration schedule is generated to allow the technicians to maintain/calibrate field devices at all times. During the inspection, the

technician demonstrated the process for the items that were to be calibrated that day. The technician logged into the system and went to a page that informed him of the instruments that were due for inspection/calibration. The technician can select the device in the database and the complete history and description of the device can be found. In this database, the make, model, and serial number of the device can be found, the page number where the device can be found on the piping and instrumentation diagrams (P&IDs) drawings, and the calibration data. The database also has the information of when the item was replaced and the previous instruments details.

Once the technician selects the device to be calibrated, the system will open an instruction/sign off page for the device. The technician can work with operations and follow the instruction to isolate and calibrate the device. Throughout this process, the technician has to “approve” or “check off” each step of the calibration and report the findings. During the whole calibration process, the SCADA system is monitored to make sure the proper alarms are being set off or cleared during the process. The instructions in the database list the alarms and require the technician to acknowledge the presence of the alarm in the SCADA system. After the technician is finished with the calibration, the system will either mark that the unit passed and record the calibration information or, if the unit fails the calibration, the computer system will generate a “trouble ticket” for the device that will show up as a repair item for the technician.

The technician also explained and demonstrated how the system can be audited to make sure the calibrations/inspections are completed. A report is generated after the calibration. The report has time/date stamps when this was performed on the instruments. With this report, the operator/technician can log into the SCADA system and pull up the alarm history for the device. The alarm history of the SCADA system should match the time/date stamp found on the report from the database. The history of the logs can go back at least several years and allows for a complete audit of the history of calibrations and inspections.

The Red Hill Facility presents a unique situation for TLI (Tank Level Indication) due to the size of the tanks. The 20 tanks built into Red Hill are 250 feet tall which is far taller than any industry standard tanks. This does create an issue that there is not an “off-the-shelf” solution to monitor and measure the level of product in the tank. The facility has been working with manufacturers of the TLI equipment to put together a level gauging system needed to accurately monitor the levels in the tanks. The system they are currently using was made by GSI (Gauging Systems, Inc.) and has been a reliable system that has allowed them to maintain 3/16 of an inch accuracy. This accuracy is well within industry standards and allows for accurate and reliable measurement of the product during all operations of filling and draining these tanks. The TLI units are connected directly to the PLC units for each tank and are connected to the SCADA system so the operator is seeing real time data in the control room and there is no delay. From these TLI units, the SCADA system can control the alarms for each tank.

In addition to the TLI units, each tank is equipped with an independent level switch. This level switch is powered independently from the TLI Unit. This acts as a backup for the tank to make sure the tank does not overfill with product. The level switch is a mechanical unit that, once activated, will send a signal to the SCADA system for alarm and a signal to the main control valve for the tank to close. In essence, the facility uses an automated overfill protection system (AOPS) as outlined in the 4th edition of API 2350 and meets the criteria established for existing AOPS.

On May 10, the evaluation team reviewed P&IDs and noted that drawings appeared to be complete, based on prior knowledge of the Red Hill Facility and equipment observed during walkthroughs. P&IDs included numbered instrument loops, terminal blocks, piping flows, branches, and lines. The evaluation team also reviewed and discussed the process of updating drawings. Navy staff explained that the technician receives his own copy of the drawings and identifies needed updates during his normal work. At the end of the year, all of his changes are submitted to SPAWAR and the drawings are updated for the next year. The terminal then receives the new set of drawings and the process is repeated.

In conjunction with the ATGs which are monitored constantly at the control room, each of the Red Hill Facility USTs contains a high-low alarm, which indicates when a tank is approaching maximum allowable fill height, as well as a high-high alarm, which indicates when the UST has been filled to the maximum allowable fill height. These alarms report to the control room. The high-high alarm also triggers closure of the skin valve on each tank, to prevent overfill. Facility staff noted that none of the Red Hill Facility USTs are typically filled beyond 88 percent, so the upper dome of each tank is not normally filled with fluid. Tank gauges are calibrated on at least a semi-annual basis and checked by manual tank gauging after each fuel transfer.

The Red Hill Facility also prevents overfills by working carefully with each ship's crew during fuel transfers. Fuel transfer operations are planned and documented through standardized Notice of Receipt and Declaration of Intent protocols. Fuel transfer volumes are verified before initiating transfer, and the control room communicates directly with ship staff via radio. Although control room operators typically taper off flow rates to avoid hydraulic hammer, operators have the ability to cease any fuel transfer process immediately. The four surge tanks provide flow equalization and mitigate hydraulic hammer in these circumstances. The control room and surge tanks are located adjacent to the pump house, which the evaluation team visited on the afternoons of May 9 and 10.

IV.c.3. Limitations and Recommendations

None noted.

IV.d Hotel Pier

IV.d.1. Findings

The Hotel Pier is the main fueling pier associated with the Red Hill Facility, and is regularly inspected by the Coast Guard along with all of the other piers. It has all of the expected secondary containment, emergency shutdown systems, and alarms.

IV.d.2. Observations

After the opening conference on May 9th, the field team viewed the Hotel Pier (see Figure 2). The Hotel Pier is the main loading and unloading pier adjacent to Building 1757. This location also births the largest ships of any pier connected to the UST system. The Hotel Pier comprises four "hotels" (each "hotel" is a group of connections for the JP-5, JP-8, and F-76 pipelines). The Hotel Pier is made of concrete with spill and leak containment; it does not have any loading arms. It

had all the expected environmental controls such as drip channels sloped to the pier's storm sewer system, emergency shutdown systems, and alarms. Any spills or stormwater that land on the Hotel Pier drains to the storm sewer system located beneath the pier. When no ships are present, the storm sewer drains directly to the harbor through an outfall located near the southeast corner of the pier. However, when a ship approaches the pier for the purposes of fuel transfer, Navy personnel close a valve near the outfall which redirects any fluid in the storm sewer to the Navy's Fuel and Oil Recovery Facility (FOREFAC) for wastewater treatment. In this manner, the storm sewer system beneath the Hotel Pier provides secondary containment for all fuel transfer equipment at the pier.

During the evaluation, Navy personnel noted that the U.S. Coast Guard inspects the Hotel Pier annually for compliance with Title 33 of the Code of Federal Regulations. After the inspection, the Navy will either receive a citation from the Coast Guard if any deficiencies are noted, or a single sheet of paper indicating that no deficiencies were found. ERG reviewed this documentation for the past few years and noted that the Coast Guard determined the Hotel Pier to be in compliance during recent inspections.

Piping systems at the Hotel Pier and lower tank farm are in generally good shape and have been designed and maintained to modern standards. Any potential product loss may seep into the harbor but would be detectable with product loss and pressure drop in the piping system.

Thorough operational procedures are in place at the pier system in the form of visual inspection and maintenance procedure on the piping system to prevent such incidents.

ERG observed multiple visible and audible alarms on the Hotel Pier, but did not test the alarms during the evaluation.



Figure 2. Overview Photo of the Hotel Pier

IV.d.3. Limitations and Recommendations

Since the Coast Guard regularly inspects the piers, ERG and PEMY recommend that EPA and HDOH leave the Hotel Pier and other piers out of future inspection plans for Red Hill Facility.

IV.e Other Components

IV.e.1. Findings

No concerns were noted at the truck loading rack or Upper Tank Farm.

IV.e.2. Observations

The evaluation team visited the truck loading rack on May 11th. At the truck loading rack, fuels are dispensed to trucks, but no fuel is added to the system. The field team observed secondary containment structures at the truck loading rack, including curbing, grading of concrete, and a central sump. All observed structures were in good condition with no major debris or visible cracking.

The Upper Tank Farm has ASTs with leak detection and double bottoms. A large leak or overfill may cause product to migrate outside the tank and into the lined tank farm.

ERG observed multiple visible and audible alarms at the Truck Loading Rack, but did not test the alarms during the evaluation.

IV.e.3. Limitations and Recommendations

None noted.

V. FACILITY OPERATIONS

V.a Staff

V.a.1. Findings

The Red Hill Facility already has a training program in place that meets the requirements of the UST regulations that will soon be applicable to the facility. Although the facility did not conduct an annual refresher training in 2014 (likely due to furloughs), they have otherwise been conducting annual training on a regular basis.

V.a.2. Observations

On May 10, the evaluation team reviewed operator training records. ERG determined that the Navy is already meeting training requirements. ERG reviewed training records for the past three years, which were provided by the Navy's training supervisor, Eric Seman. The Navy provides operators of the UST system with annual, generic UST training through USTtraining.com, and one-time, site-specific training on specific operations that each employee will support at the facility. Mr. Floyd noted that operators cannot advance to the position of control room operator until they acquired a specific amount of experience in the operations group (e.g., as a "rover").

The generic UST training includes separate training classes for Class A/B and Class C operators. ERG briefly reviewed the slides provided during the training and verified that the curriculum was appropriate for the different classes of UST operators. ERG also reviewed the matrix that tracks site-specific training and noted that it generally covers the work areas relevant to UST system operation. ERG was able to verify training records for most of the individuals with whom ERG interacted during the evaluation.

V.b Recordkeeping

V.b.1. Findings

Records and documents maintained for the Red Hill Facility's UST system were generally in order, readily accessible, and up-to-date.

V.b.2. Observations

The evaluation team reviewed the following documents for the Red Hill Facility while on-site:

- P&ID Drawings;
- Facility Response Plan;

-
- Integrated Contingency Plan;
 - UST tank tightness testing records;
 - Tank gauge calibration records;
 - UST operator training records;
 - Pipeline Integrity Management Plans from 2010 and 2015;
 - Draft pigging report from 2010;
 - As-built diagrams from the 1940s illustrating the original construction of the USTs;
 - Unscheduled fuel movement (UFM) reports;
 - Monthly rectifier readings;
 - API 653 inspection reports from 1998;
 - Tank assessment reports (TARs) from 2007; and
 - Fuel Department Operations Manual.

The facility maintains all records on-site. In addition to documents reviewed on-site, the evaluation team requested copies of the following documents for further evaluation after the close of the on-site portion of the assessment:

- Integrity Management Plan from 2015;
- Draft pigging report for 2010;
- First UFM report (including the resolution of any issues noted) for each month from December 2015 to April 2016;
- Monthly rectifier readings for fuels for March and April 2016, along with parameters used to evaluate the readings;
- API 653 inspection report from 1998 and TARs from approximately 2007 for each of the 20 tanks that was inspected;
- Fuel Department Operations Manual;
- Copy of slide from inspection introductory presentation showing general layout of the facility;
- Description of any corrosion protection, overfill prevention, and leak detection practices/equipment used for the surge tanks, as well as an as-built drawing that illustrates the construction of the surge tanks; and
- Summary of current status of Modified API 653 inspections for the 20 storage USTs and 4 surge tanks, API 653 inspections of the Lower Tank Farm ASTs, and API 570 inspections of each section of piping.

The Navy provided all of these documents through a rolling submission that ended in November 2016.

V.b.3. Limitations and Recommendations

PEI has not performed a thorough review of all inspection reports due to a lack of availability. The Navy provided full tank inspection reports for Tank 5 only.

V.c General Housekeeping

In general, housekeeping was excellent throughout the areas observed by the evaluation team.

V.d Emergency Response

V.d.1. Findings

The evaluation team verified that emergency response plans were in order, readily accessible and up-to-date. The team also verified that facility staff are adequately trained for emergency response activities and possess a working knowledge of what is required in the event of a spill or other type of release.

V.d.2. Observations

As discussed in the recordkeeping section (Section V.b), the evaluation team reviewed the site-specific Facility Response Plan, Integrated Contingency Plan, and Fuel Department Operations Manual. In addition to reviewing these plans, the evaluation team discussed emergency response activities with

facility staff (e.g., to respond to spills in the harbor) and talked through emergency response drills that facility staff execute to ensure operational readiness.

V.d.3. Limitations and Recommendations

None noted.

ATTACHMENT A

Red Hill Facility EPA and HDOH Site Visit Agenda

Day 1 – Monday, 09 May 2016

Topic/Activity	Group	Location	Time	Remarks
Joint in-brief for EPH/HDOH and Board of Water Supply	ALL	Bldg. 1757, 2 nd Floor Conf. Room	0730-0815	Introductions, facility overview, safety/security brief, and temporary badging
Records Review	All	Bldg. 1757, 2nd Floor Conf. Room	0830-1050	<ul style="list-style-type: none"> - Review of how equipment records are kept - Maintenance and inspection practices - Compliance with standards - Type of instrumentation - Reliability of system configuration - Emergency response procedures - Equipment and training records - Alarm systems, procedures, and reliability of controls systems - Records related to staining in the tunnels or below tanks
Walk-down of Hotel Pier	All	Hotel Pier	1100-1200	Observe spill protection systems
Lunch			1200-1330	
Transit to Adit 1	All	Bldg. 1757 to Adit 1	1330-1345	Transportation provided by FLC GOV's
Control Room, Pump House, Surge Tunnel	All	UGPH	1345-1530	Walk-thru of control room to include instrumentation, computer systems and controls
Transit to Bldg. 1757	All	Bldg. 1757	1530-1600	Transportation provided by FLC GOV's
Debrief and pre-brief Day 2 schedule	All	Bldg. 1757, 2nd Floor Conf. Room	1600-1630	

Day 2 – Tuesday, 10 May 2016

Transit to Adit 5	All	Bldg. 1757 to Adit 5	0730-0800	Two 7 PAX GOV's
Walk-down of Red Hill Upper Tank Gallery from Tank 15/16 to Tank 5	All	Adit 5 to Tank 5	0800-0845	View visible portion of tank externals in upper gallery
View Tank 5	All	Tank 5	0845-0915	Observe tank 5 from pedestrian walkway No Photography

Day 2 – Tuesday, 10 May 2016

Walk-down of Red Hill Lower Tank Gallery from Tank 20 to Red Hill Shaft	All	Lower Tank Gallery	0915-1015	View oil tight doors, corrosion monitoring locations, determination of piping wall thickness, kinds of piping, API fire rating of valves etc.
View Red Hill Shaft	All	Red Hill Shaft	1015-1030	NAVFAC EV to coordinate access and viewing of RH Shaft
Walk entire Harbor Tunnel from Red Hill Shaft to Adit 1	All	Harbor Tunnel	1030-1200	View piping in tunnels
Travel from Adit 1 to Bldg. 1757	All	Bldg. 1757	1200-1215	FLC GOV's
Lunch			1215-1330	
Records Review	All	Bldg. 1757, 2nd Floor Conf. Room	1330-1530	Continuation of previous days review as required.
Debrief and pre-brief Day 3 schedule	All	Bldg. 1757, 2nd Floor Conf. Room	1530-1600	

Day 3 – Wednesday, 11 May 2016


Review of documentation and facilities as required	All	Bldg. 1757, 2nd Floor Conf. Room	0800-1600	Continuation of previous days review as required. Limited SME availability
--	-----	----------------------------------	-----------	---


Day 4 – Thursday, 12 May 2016


Review of documentation and facilities as required	All	Bldg. 1757, 2nd Floor Conf. Room	0800-1600	Continuation of previous days review as required. Limited SME availability
--	-----	----------------------------------	-----------	---


ATTACHMENT B

Photograph Log


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 1	
COMMENTS: Fuel Department Operations and Maintenance Manual	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 2	
COMMENTS: Integrity Management Plan – POL Pipelines (May 2015)	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 3	
COMMENTS: Final API-653 Inspection Report for Tank 15 (January 2007)	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 4	
COMMENTS: 2013 Spill Control and Countermeasure (SPCC) Plan for Commander, Navy Region Hawaii (CNRH)	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 5	
COMMENTS: Integrated Contingency Plan	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 6	
COMMENTS: Red Hill Tunnel Fuel Storage Facility Response Plan	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 7	
COMMENTS: Integrity Management Plan – POL Pipelines (November 2010)	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 8	
COMMENTS: Tank Tightness Test Binder	

DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 9	
COMMENTS: Fire, Life Safety, and Environmental Risk Assessment	

DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 10	
COMMENTS: UST Operator Training Program – Roster Sheet	

DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 11	
COMMENTS: UST System Operator Training Records	

DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 12	
COMMENTS: UST System Operator Training – Certificates of Participation	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 13	
COMMENTS: Final 2015 Annual Leak Detection Testing Report	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 14	
COMMENTS: Pipelines running from Hotel Pier	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 15	
COMMENTS: One "Hotel" of four on the Hotel Pier, with risers for all three fuels stored at the Red Hill Facility	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 16	
COMMENTS: Telephone at Hotel Pier	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 17	
COMMENTS: Trailer mounted flowmeter	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 18	
COMMENTS: Hotel Pier looking east from the end of the pier toward Red Hill	

DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 19	
COMMENTS: View of docks adjacent to pier illustrating the boom system in place to control oil spills in emergencies	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 20	
COMMENTS: Spill response kits inside of cage on Hotel Pier	

DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 21	
COMMENTS: Alarm system at Hotel Pier	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 22	
COMMENTS: Emergency response number posted	

DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 23	
COMMENTS: Diversion valve for Hotel Pier storm water drainage system	

DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 24	
COMMENTS: Hotel Pier alarms	

DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 25	
COMMENTS: Emergency response number posted	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 26	
COMMENTS: Pipes entering the ground running uphill from the Hotel Pier. Above-ground piping is covered with a layer of noncorrodible material.	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 27	
COMMENTS: Pumphouse	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 28	
COMMENTS: Pumphouse	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 29	
COMMENTS: Pumphouse	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 30	
COMMENTS: Pumphouse	

DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 31	
COMMENTS: Tile covering French drain beneath Red Hill Facility tunnel	


DATE TAKEN: 5/9/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 32	
COMMENTS: Pipelines supported by concrete wall in tunnel	

DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 33	
COMMENTS: Tank vent associated with one of the storage USTs.	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 34	
COMMENTS: Minor cracking in tunnel floor	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 35	
COMMENTS: Stairway leading to gauging port on top of underground storage tanks	

DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 36	
COMMENTS: SP-26 Underground storage tank nozzle and skin valve	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 37	
COMMENTS: Cover for soil vapor monitoring wells	

DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 38	
COMMENTS: Pipeline running to fuel oil recovery (FOR) process	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 39	
COMMENTS: Tell-tale system on Tank 19 (Tank 19 has been permanently removed from service and the tell-tale system has been decommissioned).	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 40	
COMMENTS: Tell-tale system on Tank 19 (Tank 19 has been permanently removed from service and the tell-tale system has been decommissioned).	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 41	
COMMENTS: Skin valve on tank nozzle	

DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 42	
COMMENTS: Pitting on pipeline	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 43	
COMMENTS: Typical surface defects on pipeline	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 44	
COMMENTS: Staining on Tank 5, just below and to the right of the nozzle.	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 45	
COMMENTS: Tank penetrations near the bottom of Tank 5	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 46	
COMMENTS: Staining on tunnel wall (appearance similar to bunker oil)	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 47	
COMMENTS: Spill kit in tunnel	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 48	
COMMENTS: Typical flush-mounted groundwater monitoring well near underground storage tanks	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 49	
COMMENTS: Pipelines supported by concrete wall in tunnel	

DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 50	
COMMENTS: Pipelines supported by concrete wall in tunnel	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 51	
COMMENTS: Flashing lining tunnel walls in some areas	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 52	
COMMENTS: Oil-tight door	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 53	
COMMENTS: Counterweight for oil-tight door	

DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 54	
COMMENTS: Flashing lining tunnel walls in some areas	


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 55	
COMMENTS: Typical Surface defects noted on piping, showing failure of the pipeline protective wrap. Facility staff noted that this does not affect piping integrity, and the protective wrapping is actually scheduled for removal.	 A photograph of a dark, cylindrical pipe with a significant area of surface corrosion or damage where the protective wrap has failed. Yellow spray paint markings are visible: a crosshair on the left, the alphanumeric code '2780-07' on the right, and another crosshair further right. A timestamp '05/10/2016 15:14' is in the bottom right corner.


DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 56	
COMMENTS: Markings describing pipe defects	 A photograph of a pipe with yellow spray paint markings. The markings include 'AREA #10', 'DENT', and a circular diagram with several points labeled with numbers: '399', '398', '401', and '398'. A line points from the text 'Depth OF DENT .625' to the center of the circular diagram. A timestamp '05/10/2016 15:25' is in the bottom right corner.

DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 57	
COMMENTS: Pipe support in tunnel	

DATE TAKEN: 5/10/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 58	
COMMENTS: Sump and float switch in tunnel	


DATE TAKEN: 5/11/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 59	
COMMENTS: Rectifier near Hotel Pier showing no voltage or current	

DATE TAKEN: 5/11/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 60	
COMMENTS: AST tank in Upper Tank Farm	

DATE TAKEN: 5/11/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 61	
COMMENTS: Truck loading rack	


DATE TAKEN: 5/11/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 62	
COMMENTS: Truck loading rack	


DATE TAKEN: 5/11/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 63	
COMMENTS: Truck loading rack	

DATE TAKEN: 5/11/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 64	
COMMENTS: Spreadsheet documenting operator training (names have been cropped out).	

DATE TAKEN: 5/11/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 65	
COMMENTS:	

Text from 2015 Integrity Management Plan describing cathodic protection systems on-site.

DATE TAKEN: 5/11/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 66	
COMMENTS: Declaration of inspection form	

DATE TAKEN: 5/11/2016	
TAKEN BY: Chris Krejci	SITE LOCATION: Red Hill Facility
PHOTO #: 67	
COMMENTS: Tank tightness testing records	

ATTACHMENT C
Release Detection Records



FINAL 2015 ANNUAL LEAK DETECTION TESTING REPORT OF 14 BULK FIELD- CONSTRUCTED UNDERGROUND STORAGE TANKS AT RED HILL UNDERGROUND FUEL STORAGE FACILITY

JOINT BASE PEARL HARBOR- HICKAM, HAWAII



Prepared for:
**Defense Logistics Agency Energy
Ft. Belvoir, Virginia**

Prepared under:
**NAVFAC Atlantic
Contract N62470-10-D-3000-0048**

Performed by:
**Michael Baker International
Virginia Beach, VA**

Date:
6 JULY 2015

Michael Baker
INTERNATIONAL
Project: 140500
Task: 1.1.80

**FINAL 2012 ANNUAL LEAK DETECTION TESTING REPORT
OF 14 BULK FIELD-CONSTRUCTED UNDERGROUND STORAGE TANKS
AT THE HITT UNDERGROUND FUEL STORAGE FACILITY**

JOINT BASE LEVITT HARBOR-HICKAM, HAWAII

Prepared For:

**Defense Logistics Agency Energy
Et. Belvoir, AL**

Prepared Under:

**WVLEVC Annual
Contract W95410-10-D-3000-0048**

Prepared By:

Michael Baker International

Milpitas Beach, Milpitas

9 JULY 2012

TABLE OF CONTENTS

	<u>Page No.</u>
LIST OF ABBREVIATIONS AND ACRONYMS	ii
PROFESSIONAL ENGINEER CERTIFICATION:	iii
EXECUTIVE SUMMARY	iv
1.0 INTRODUCTION	1
1.1 Purpose of Project	1
1.2 Site Background and History	1
1.3 Historical Geot Detection Results	3
1.4 Project Scope	3
1.5 Project Team	4
1.6 Objectives of Testing Procedures Used	4
2.0 GEOTECHNICAL TESTING AND RESULTS	8
3.0 CONCLUSIONS AND RECOMMENDATIONS	8
3.1 Conclusions	8
3.2 Recommendations	8
4.0 REFERENCES	10

List of Tables

Table 1-1: Items Tested	4
Table 2-1: Test Results	8

List of Figures

Figure 1-1: Location Map – KCP Hill Complex	5
Figure 1-2: KCP Hill System Layout	6

List of Appendices

Appendix A	Qualitative Order of Consent: KCP Hill Bulk Fuel Storage Escalation
Appendix B	Mass Technology Corporation Test Reports

LIST OF ABBREVIATIONS AND ACRONYMS

VOC	Voluntaristic Order on Consent
BECN2L BWB	Bank of Europe-constructed nucleotide sequence bank Best Management Practice
CMB CIBH	Central Management Bureau Communist Israel Kibbutz House (CIBH)
DOH DTV	Department of Health Defense Forces Agency
EBV	Environmental Protection Agency
E-10 EISC EP	Europe Global Inc. Electronically Supported Center Epsilon Inc.
EP	European Policy
IP	Inc.
IB IB-2, 8	Initial Base Initial Protocol 2, 8
NDFB NFBBI NLC	National Detectable Risk List National Bank International Nuclear Technology Corporation
NVLEVC NMGDE	National Emergency Evacuation Commission National Market Group on Risk Detection Evaluation
BD BEV BZV	Biological of Detection Biological of the same system Biological and the same system

PROFESSIONAL ENGINEER CERTIFICATION:

**Final 2012 Annual Test Detection Testing Report
Of the Bulk Electrical-Construction Underground Storage Tanks
At the Hill End Storage Complex**

John Baze, Owner Hill End-Pickens, N.M.

This report was prepared by a professional engineer and was prepared in accordance with good engineering practices. The following results, test notes, and supporting data were prepared and referenced collected.

I declare that I was examined this report and attest that it was prepared in accordance with good engineering practices.

Engineer: Christopher D. Caputi, P.E.

Registration Number: 033383

State: Arizona

Date: April 2012



EXECUTIVE SUMMARY

[illegible][illegible]

Various leak detection testing of the 14 BECN2L2 aPonIP P6 installed on or before the new annual summer/late fall date of 14 October 2012 under DGV Euergh's Gas Detection Centralized Waiver/Compliance (CMB) to comply with the VOC requirements. In addition, the DGV Euergh Gas Detection CMB aPonIP P6 notified immediate/within BECN2L 19 can be used to its full use before and the remaining four BECN2L2 (BECN2L 2, 14, 15 and 18) are each placed back in service by or for the leak detection testing to be completed to comply with the VOC agreement.

1.0 INTRODUCTION

1.1 Purpose of Bioreact

The Defense Logistics Agency (DLA) Environmental Impact Statement (EIS) for the, through the National Environmental Policy Act (NEPA) of 1969, the Department of Defense (DoD) is required to prepare an EIS for the proposed construction of the new Bioreact facility, located at the Defense Logistics Agency (DLA) in the City of Washington, D.C. The purpose of the EIS is to provide information on the potential impacts of the proposed facility on the environment and to provide a basis for the decision-making process. The EIS is required by the National Environmental Policy Act (NEPA) of 1969, which requires the federal government to consider the environmental impacts of its actions. The EIS is a key component of the decision-making process for the proposed facility. The EIS is required by the National Environmental Policy Act (NEPA) of 1969, which requires the federal government to consider the environmental impacts of its actions. The EIS is a key component of the decision-making process for the proposed facility. The EIS is required by the National Environmental Policy Act (NEPA) of 1969, which requires the federal government to consider the environmental impacts of its actions. The EIS is a key component of the decision-making process for the proposed facility.

1.2 Site Background and History


The new Bioreact facility is located on the site of the old Bioreact facility, which was located on the site of the old Bioreact facility. The new Bioreact facility is located on the site of the old Bioreact facility, which was located on the site of the old Bioreact facility. The new Bioreact facility is located on the site of the old Bioreact facility, which was located on the site of the old Bioreact facility.

The new Bioreact facility is located on the site of the old Bioreact facility, which was located on the site of the old Bioreact facility. The new Bioreact facility is located on the site of the old Bioreact facility, which was located on the site of the old Bioreact facility. The new Bioreact facility is located on the site of the old Bioreact facility, which was located on the site of the old Bioreact facility. The new Bioreact facility is located on the site of the old Bioreact facility, which was located on the site of the old Bioreact facility. The new Bioreact facility is located on the site of the old Bioreact facility, which was located on the site of the old Bioreact facility. The new Bioreact facility is located on the site of the old Bioreact facility, which was located on the site of the old Bioreact facility. The new Bioreact facility is located on the site of the old Bioreact facility, which was located on the site of the old Bioreact facility.

to the Bottom portion of the BEDFORD. VII. The following is a list of the various localities where the various beds are found.

[illegible]

Figure 1-1: Location Map – Red Hill Storage Complex



1.3 Historical Gas Detection Results

Before the test event, gas detection testing was conducted previously as a DGV Energy Gas Detection CWB Post management practice (BWB). The last previous tests on 12 of the 18 BECON2L2s were completed from 33 January 2013 through 2 April 2013. The West Leeward Oil Corporation (WLC) gas detection tests were successful with no detectable gas spikes above the test method's maximum detectable gas rate (MDGR) of 0.3 gallons per hour (gph) (Cell 01). BECON2L2s 2, 14, and 15 were out-of-service during the 2013 test event for internal inspections and were not tested.


1.4 Project Scope

WLC gas detection tests on 14 of the 18 BECON2L2s were performed from 14 October 2014 through 14 May 2012. Note that the 2012 previous test event of the Keq Hill tanks, initially scheduled for the first quarter of 2012, was postponed in October 2014 in response to the annual test recommendations agreed upon in the VOC. Table 1-1 provides a description of the systems tested. Figure 1-3 provides a layout diagram of the Keq Hill storage complex.

-	8	3'5	3'0	-	1	1	-	-	-	2-b1	000'000'51	025	001	05 12NCEB
есивез шод қасионер дигершинеб	-	-	-	-	-	-	-	-	-	-	000'000'51	025	001	01 12NCEB
есивезшинеб иқ есивез-го-иго	82	1'8	3	1	3	1'1	-	-	-	2-b1	000'000'51	025	001	81 12NCEB
воисебан иқ есивез-го-иго	11	3'22	3'0	2'0	2'1	3	-	-	-	02-Е	000'000'51	025	001	11 12NCEB
-	82	1'8	3	1	3	1'1	-	-	-	02-Е	000'000'51	025	001	01 12NCEB
-	11	3'22	3'0	2'0	2'1	3	-	02	02	02-Е	000'000'51	025	001	21 12NCEB
воисебан иқ есивез-го-иго	44	1'4	2'5	1	-	5'1	-	-	-	02-Е	000'000'51	025	001	41 12NCEB
-	41	1'52	2'0	2'0	-	1'1	-	02	02	02-Е	000'000'51	025	001	31 12NCEB
-	44	1'4	2'5	1	-	5'1	-	-	-	2-b1	000'000'51	025	001	51 12NCEB
-	21	2'5	2'0	1	-	1	-	-	-	2-b1	000'000'51	025	001	11 12NCEB
-	13	2'31	2'0	1	-	5'1	-	-	-	2-b1	000'000'51	025	001	01 12NCEB
-	51	5'5	2'0	1'0	-	-	1	-	-	2-b1	000'000'51	025	001	0 12NCEB
-	15	02	2'0	1	2'1	5	-	24	2-b1	2-b1	000'000'51	025	001	8 12NCEB
-	51	5	2'0	2'0	-	1	-	-	2-b1	2-b1	000'000'51	025	001	1 12NCEB
-	44	1'4	2'5	1	-	5'1	-	-	8-b1	8-b1	000'000'51	025	001	0 12NCEB
воисебан иқ есивез-го-иго	44	1'4	2'5	1	-	5'1	-	-	8-b1	8-b1	000'000'51	025	001	2 12NCEB
-	31	1'5	2'0	2'0	2'0	5'1	-	-	8-b1	8-b1	000'000'51	025	001	4 12NCEB
-	41	1'52	2'0	2'0	-	1'1	-	02	8-b1	8-b1	000'000'51	025	001	3 12NCEB
-	31	1'5	2'0	2'0	2'0	5'1	-	-	8-b1	8-b1	000'000'51	025	001	5 12NCEB
есивез шод қасионер дигершинеб	-	-	-	-	-	-	-	-	-	-	000'000'51	025	001	1 12NCEB
затешнос	жонлаг(сумма)	жее(пигет) пгол	жее(пигет) жее(пигет) жее(пигет) жее(пигет) жее(пигет) жее(пигет)						жонлаг(сумма)	жее(пигет) пгол	жее(пигет) пгол	жее(пигет) пгол	жонлаг(сумма)	

Figure I-5: Red Hill System Layout

DRAWING NOTE: PIPING LOCATIONS AND ROUTING ARE DIAGRAMMATIC ONLY.



DATE: 15 MAY 2015 PRJ / TASK NO.:
SCALE: NTS 140296 / 4.189
DGN / DWN / CHK BY: FILE NAME:
AKK / AKK / MC 140296_RH.DWG

Michael Baker
INTERNATIONAL

MICHAEL BAKER INTERNATIONAL
VIRGINIA BEACH, VIRGINIA

RED HILL SYSTEM LAYOUT
ANNUAL RED HILL BFCUST LEAK DETECTION
TEST REPORT
JOINT BASE PEARL HARBOR- HICKAM, HAWAII

1.2 Project Team

Wicpac Bgcl subcontracted WLC to perform the leak detection testing. Field-testing overlapped, coordination with local utility lines representatives, digital surveillance/digital controls, and usual report preparation and submission were provided by Wicpac Bgcl personnel.

1.3 Qualifications of Testing Personnel

The testing personnel were those people as the WLC - Block-Water Measurement System 21W-1000 \ CBW-1000 (3rd Point test) leak detection method. Determination of leakage is based on the criteria established in the Ken Wilcox Associates, Inc. Field leak analysis as stated by the National Leak Check on Leak Detection Evaluations (NLCDE) (KEL 05). The WLC Block-Water Measurement System (3rd Point test) is certified with a capability to detect leaks on a tank proportional to the product surface area (b2V) with a proportionality of detection (bD) of 0.2 percent and proportionality of a leak signal (bLV) of 2 percent. Due to the effect of the tank, a total of 150 Points of testing was performed for each test, consisting of 48 Points for initial establishment of tank and product and the subsequent 3rd Point test events (150 Points).

By performing a number of non-overlapping tests in sequence and averaging the resultant leak rates, a more precise measurement can be established for detection of leaks. Prolonged sequential averaging, the larger the number of tests performed in the averaging will result in a lower measurement and, therefore, a smaller size leak can be detected with a 0.2 percent bD.

3rd Point test 20,000 gallons or greater

For tanks with b2V of 1,522 ft³ or less, leak rate is 0.1 gallons per Point (gBP) with bD = 0.2% and bLV = 2%.

For tanks with larger b2V, leak rate equals [(b2V in ft³ ÷ 1,522 ft³) × 0.018 gBP].

Leak rate may not be scaled below 0.1 gBP.

Example:

For a 100 foot diameter tank with b2V = 1820 ft³; leak rate = [(1820 ft³ ÷ 1,522 ft³) × 0.018 gBP] = 0.21 gBP.

Using the statistical analysis of the test events: 0.21 gBP ÷ Square Root of 0.21 gBP = 0.3118 gBP.

The 0.1 gbw WDFB previously noted for the testing of the KCP Hill tanks in 2000, 2011, and 2013 was established during the original Pleurotest test event in 2000. Due to the pleural and mucocutaneous epithelial Pottow construction of the tanks, WLC established a conservative test WDFB of 0.1 gbw. Based on the consistency of the previous Pleurotest test data and the results of a simulated leak evaluation performed by Ken Milcox Associates Inc. in May 2000 (Ref 03), WLC is confident in reducing the test WDFB to 0.2 gbw. The 0.2 gbw WDFB is still conservative relative to the test method calculated rate of 0.55 gbw.

3.0 LEAK DETECTION TESTING AND RESULTS

WLC's test reports are provided in Appendix V. The 14 BECNETs were leak detection tested with no detection leak found. The average leak test results were WDFK of 0.2 gph. BECNETs 2, 14, 15, and 18 were out-of-service during the test event and, therefore, not tested. In summary, BECNET 10 was temporarily isolated from receiving groundwater level during the test event, due to the initial issues and was tested at less than the tank's full flow rate level. Test results are listed in Table 3-1.

Table 3-1: Test Results

Vessel Designation	Height (E66)	Diameter (E66)	Leak Flowrate Height (E66)	Flowrate	Calculated WDFK (gph)	Test Date	Result
BECNET 1	320	100	Benchmarked from Service				
BECNET 3	320	100	308.5	1b-8	0.2	11 April - 10 April 2012	Pass
BECNET 3	320	100	310.5	1b-8	0.2	14 April - 10 April 2012	Pass
BECNET 4	320	100	311.01	1b-8	0.2	10 October - 30 October 2014	Pass
BECNET 2	320	100	Out-of-Service for Inspection				
BECNET 6	320	100	311.0	1b-8	0.2	14 October - 31 October 2014	Pass
BECNET 11	320	100	313.32	1b-2	0.2	12 November - 30 November 2014	Pass
BECNET 8	320	100	311.08	1b-2	0.2	14 October - 31 October 2014	Pass
BECNET 9	320	100	311.18	1b-2	0.2	30 October - 30 October 2014	Pass
BECNET 10	320	100	311.43	1b-2	0.2	31 October - 1 November 2014	Pass
BECNET 11	320	100	311.0	1b-2	0.2	18 April - 30 April 2012	Pass
BECNET 13	320	100	313.30	1b-2	0.2	9 November - 13 November 2014	Pass
BECNET 13	320	100	313.42	E-10	0.2	30 April - 4 May 2012	Pass
BECNET 14	320	100	Out-of-Service for Inspection				
BECNET 12	320	100	310.85	E-10	0.2	0 May - 14 May 2012	Pass
BECNET 10	320	100	28.20	E-10	0.2	4 May - 0 May 2012	Pass
BECNET 13	320	100	Out-of-Service for Inspection				
BECNET 18	320	100	Out-of-Service for Maintenance				
BECNET 10	320	100	Benchmarked from Service				
BECNET 30	320	100	311.42	1b-2	0.2	30 October - 2 November 2014	Pass

3.0 CONCLUSIONS AND RECOMMENDATIONS

3.1 Conclusions

Completion of the 18 BECONZLs passed the 2012 Plenary test detection testing. BECONZLs 2, 14, 15 and 18 were out-of-scope and were not tested. The test of BECONZL 19 test was not completed at the 111 Pctgpt (~210 test) due to operational limitations; testing was completed at ~28 test.

3.5 Recommendations

Annual test detection testing of the 14 BECONZLs should be completed on or before the annual surveillance test of 14 October 2012 under DGV Enclg's Test Detection CWB to complete all VOC agreement. In addition, the DGV Enclg's Test Detection CWB should be notified immediately when BECONZL 19 can be added to its 111 Pctgpt and when reviewing both BECONZLs (BECONZL 2, 14, 15 and 18) are each placed back in scope in order for test detection testing to be completed to complete all VOC agreement.

4.0 REFERENCES

- Кел01 Елусл 3013 Б!емулсл лутегултл Лелтлуг Кеборл Ол БлпК Е!елл Комсллслелл
 Оулуеллелллул Злолсгел Ллул 3 – Кеу Н!л Оулуеллелллул Злолсгел Елел
 Злолсгел Елелл!л, лолул Блсгел Белл НеллОл - Н!елллу, Нллул!л. Блеллелл
 лол ДГВ Еулелл, Ел. Белло!л, Алелллу!л, нулу ИВЛЕВС Вллулу!л
 Комслсл Иелл!0-10-D-3000-0030. Делелл И Вллу! 3013.
 (Лллу!ел лулл!лул лул лелл лол И БЕЕОЗЛз лелелл - 3013 Б!емулсл
 лелл лелл)
- Кел03 Г!еллуг Рл лел ИМСЕГЕ (33^{ул} Елу!лу): Млсз Леллуолелл Комлорл!лу –
 Блел!лу Млсз Меллеллелл Злзлелл ЗИИ-1000 лул СВН-1000 (3л
 Рол лел) – БНГК ОИДЕКСКОИИД ЗЛОКВЕ ЛВИК РЕВК
 DELECTION METHOD (20,000 гллулу ол глелел).
 Лелл Делл: 33 Вллул Иллу
 Белл!лу Делл: 30 Деллелл 3011
[Рллу:\www.mwglc.org\cvslz\mlsz_lclluolcll_с.лул](http://www.mwglc.org/cvslz/mlsz_lclluolcll_с.лул)
- Кел03 Леллуг ол лел Млсз Леллуолелл Комлорл!лу ЗИИ-1000 Гелл Делелл
 Злзлелл ол И М!лул Сллул Ллулз л Кеу Н!л. Блеллелл лол: М!еллел
 Блел л. л. Блеллелл Бл: Кеу М!лелл Влсслелл, л. л.
 Делелл И Млл 3000

APPENDIX B –

MASS TECHNOLOGY CORPORATION TEST REPORTS



Precision Leak Measurement Report
P.O. Box 1578
Kilgore, Texas 75662


ԷԼԵԿ ԲԵՐ ԻՈՒ
ԲԵՐԼ ԻՅԻՐՈՒ, ԻԼ

ԲԻՐՈՅԵԼ ԿՈՄՊԼԵԿՏ – ԿԻԼԳՈՐ ԵՐԿՐ ԵՐԿՐՈՒ

ՉԻԼԵ ՉՈՒԴԵԼԻՉՈՒ – ԼԻՅԻԼԶ ԲԻԼԿԵԲՅՈՒ

ՉԵՐԵ ՕՒ ԿՈՒԿ: ԷՆԻԼԻՉ ԳԼ ԼԵԴՈՒԼԵՐ ԿՈՄՊԼԵԿՏԵՄԵՆԷ, ԼԵՐՈՒ, ՉԵԼԻԿԵՉ, ԿՅԲԵԼԻՅԻՉ ԳՈՐ ԵԴՈՒԴԿԵՄԵՆԷ
ԲՈ ԴԵԼԵՐԿ ԲԵ ԼԵԴՈՒԼԵՐ ԳՆՆՈՅԻ ԲԼԵԴԲՈՅՉ ԲԵՉԲԻՅՈՒ ՕՒ ԼԵՐԿ # 5 ԳՈ ՈՍԴԵԼԵՐՈՒՍԴ
ԷՈՒ ԶԲՈՐԵԿ ԲՅՈՒ ԼՈԿԵԲՈՒ ԳԲ ԷԼԵԿ ԲԵՐ ԻՈՒ, ԲԵՐԼ ԻՅԻՐՈՒ, ԻԼ.

ԲԵՐՈՒԲ ԿՈՄԲԼԵԴ ՔԼ:


ԲԻԿԵԼ ՉԻՅՈՒԴԲԵԼ

ԴԵԲԵ: 03-Դ3-50Դ2

ՉՈՒԿԱՅԻԼ

ԼԵՉԲԻՅՈՒ ՕՒ ԼԵՐԿ # 5 Գ Դ5,000,000 ԶԻԼ ՈՍԴԵԼԵՐՈՒՍԴ ԶԲՈՐԵԿ ԲՅՈՒ ԼՈԿԵԲՈՒ ԳԲ ԷԼԵԿ ԲԵՐ ԻՈՒ, ԲԵՐԼ ԻՅԻՐՈՒ, ԻՅԿՅԻԼ ԿՈՒԿԱՅԵՄԵԴ ԷԵՐԻՆԻՅԻԼ ԴԴ, 50Դ2 ԳՈՐ ԿՅՉ ԿՈՒԴԼԵԲԵԴ ԷԵՐԻՆԻՅԻԼ ԴԵ, 50Դ2. ԼԲԵ ԼԵՉՈՒԲ ՕՒ
ԲԲԲ ԲԵՉԲԻՅՈՒ ԻՉ ԲԲԲ ԲԵ ԲՅՈՒ ԶԼԶԵԿ ԻՉ ԴԵԲԵԿԵԼԵԴ ԲՈ ՔԵ ԲԼԵԴ ԲՈ ԻՉՈՅԲԻՈՒ. ՎԻԼ ԲՅՈՒ ԼՅԻԼԵՉ ԿԵԼԵ
ԳԴԵԴՈՅԲԵԼԻ ԶԵՐՈՒԼԵԴ ՉՈՒԴ ԲԲԲ ՈՒ ՈՍՈՒՅԻԼ ԼԵԴՈՒՅՉ ԿԵԼԵ ՈՒԲԵԴ. ԼԵՉԲԻՅՈՒ ԿՅՉ ԴԵԼԵՐԿՈՒԼԵԴ ՈՒՅՈՒ ԲԵ
ԿՅՉ ԼԵԴՈՒՅԼ ԿՈՒԴՈՅԲԻՈՒ ԴԻՓՈԿՈԼԻՉ ԶԵԲ ՕՈՒԻ ԻՍ ԲԵ ԲԲԻԼԴ ԴՅԻԼԻ ԵԼՅԻՆՅԲԻՈՒՉ. ՎԻԼ ԲՅՈՒ ԼՅԻԼԵՉ
ԿԵԼԵ ԳԴԵԴՈՅԲԵԼԻ ԶԵՐՈՒԼԵԴ ՉՈՒԴ ԲԲԲ ԳՆԼ ԷՈՒԴ ԼՈՅՉ ԿՅՉ ԻՉՈՅԲԻՈՒ ԲՈ ԼԵԴԿՅԵ. ԼԲԵԼԵՐԵ, ԲԵ
ԿՈՒԴՅԻԿԱՅԵՆ ԼՆԲԵԼԻԼԻ ՕՒ ԲԵ ԲՅՈՒ ԿՅՉ ՈՒԲ ԿՈՒԴԼՈՒԼԵԴ ԳՈՐ ԲԵ ԲԵՉ ԻՉ ԿՈՒԴՈՒԼԵԴ ԿՈՒԴՈՒԼԵԴ.

ԼԵՐԿ # 5: ՎԷԲԵ Դ50 ԴՈՒԼԻՉ ՕՒ ԲԵՉԲԻՅՈՒ ԲԵ ԲՅՈՒ ԻՉ ԿԵԼԻԼԵԴ ԲՈ ՔԵ ԲԼԵԴ.


IsuK D9f9 IsuK # 5

D!9wefei: J00 t.
IsuK Llb6: Aef!c9l N2L
2bec!t!c C!9v!fλ: 0.80

Hef!gf: J20 t.
Couf6uf2: 1b-8
b!o9ncf Γ6v6l: J08.5 t.

2f9lf D9f6: 05\JJ\J0J2
Nu!f Ob6!9fou: L!9v!2 B!cK6f2ou


Combl6f!ou D9f6: 05\J6\J0J2
L6zf B6znlf2: C6v!t!69 L!gf



All dimensions, line locations, sizes and valve descriptions have been furnished by the facility operator.

[illegible]

190K # 5 !2 c6rf!t!69 fo p6 f!gMf.





Precision Leak Measurement Report
P.O. Box 1578
Kilgore, Texas 75662


ԷԼԵԿ ԲԵՂ ԻՈՒՍ
ԲԵՂԻ ԻՍԻՐՈՒ, ԻՍ

ԲԻՐՈՅԵԼ ԿՈՄՊԼԵԿՏ – ԿԻԼԳՈՐ ԵՐԿՐ ԵՐԿՐՈՒ

ՉԻՔ ՉՈՒԴԵԼԻՉՈՒ – ԼԻՂԻՆ ԲԻՔԵԲՉՈՒ

ՉԵՐԵ ՕՒ ԿՈՒՔ: ԷՆԻՄԻՐ ԳԻ ԼԵԴՈՒԼԵՂ ԿՈՄՊԼԵԿՏԵՄԻ, ԼԵՐՈՒ, ՉԵԼԻՑԵՆ, ԿՐԵԼԻՂԻՆ ԳՈՂ ԵԴՈՒԴԿԵՄԻ
ԲՈ ԴԵԼՈՒԿ ԲԵ ԼԵԴՈՒԼԵՂ ԳՈՍՈՂԻ ԲԼԵԴԲՈՒՆՆ ԲԵՉԲԻՆՂ ՕՒ ԼԵՐԿ # 3 ԳՈ ՈՒԴԵԼԵՐՈՒՍԴ
ԷՈՒ ԶԲՈՂԵՑ ԲՈՒԿ ԼՈՑԲԵՂ ԳԲ ԷԼԵԿ ԲԵՂ ԻՈՒՍ, ԲԵՂԻ ԻՍԻՐՈՒ, ԻՍ.

ԵՐԵՐԻՔ ԿՈՒԴԵԼԵՂ ԲԼ:


ԲԻՔԻԼ ՉԻՂԻՐԼԻ

ԴԵԲԵ: 03-Ե3-ՏՈԵ2

ՉՈՒԿԱՐԻՂ

ԼԵՉԲԻՆՂ ՕՒ ԼԵՐԿ # 3 Գ ԵՏ,ԵՐՈՒ,ԵՐՈՒ ԵՂԻ ՈՒԴԵԼԵՐՈՒՍԴ ԶԲՈՂԵՑ ԲՈՒԿ ԼՈՑԲԵՂ ԳԲ ԷԼԵԿ ԲԵՂ ԻՈՒՍ, ԲԵՂԻ
ԻՍԻՐՈՒ, ԻՂԿԵՂԻ ԿՈՒԿԵՄԵԼԵՂ ԷԵՐԻՂԵՂ ԵՂ, ՏՈԵ2 ԳՈՂ ԿՐԵ ԿՈՒԴԵԼԵՂ ԷԵՐԻՂԵՂ ԵՂ, ՏՈԵ2. ԼԵՐԵ ՆԵՂԻՔ
ՕՒ ԲԵՂԻ ԲԵՉԲԻՆՂ ԼԵ ԲԵՂԻ ԲԵ ԲՈՒԿ ՉԼԵԿԵՂ ԼԵ ԴԵԼԵԿԵԼԵՂ ԲՈ ԲԵ ԲԼԵԴԲՈՒՆՆ ԲՈ ԼՈՑԲԵՂ. ՎԻ ԲՈՒԿ ՆՂԻՂԵՑ ԿԵԼԵ
ԳԴԵԴՈՂԵԼԻՂ ԶԵՐՈՒԼԵՂ ՉՈՒՔ ԲԵՂԻ ՈՒ ՈՒՂԵՂԻ ԼԵՂԻՂԵՑ ԿԵԼԵ ՈՒԼԵՂ. ԼԵՉԲԻՆՂ ԿՐԵ ԴԵԼՈՒԿԵՂ ՈՒՂԵՑ ԲԵ
ԿՐԵ ԼԵԴՈՒԼԵՂ ԿՈՒԴԵԼԵՂ ԲԵԼՈՑՈՒՆ ԶԵԲ ՕՒԲ ԼԵ ԲԵ ԲԵԼԵՂ ԴՂԵԼԻ ԵՂԵԼԵԼԵՂԵՂ. ՎԻ ԲՈՒԿ ՆՂԻՂԵՑ
ԿԵԼԵ ԳԴԵԴՈՂԵԼԻՂ ԶԵՐՈՒԼԵՂ ՉՈՒՔ ԲՈՒԿ ԷՈՒՂ ԼՈՒՂ ԿՐԵ ԼՈՑԲԵՂ ԲՈ ԼԵՂԵՂԵՑ. ԼԵԼԵԼՈՒԵ, ԲԵ
ԿՈՒԴԵԼԵՂԵՂ ԼԵԼԵԼԵԼԵՂ ՕՒ ԲԵ ԲՈՒԿ ԿՐԵ ՈՒԼ ԿՈՒԴԵԼԵՂԵՂ ԳՈՂ ԲԵ ԲԵՉԻ ԼԵ ԿՈՒԴԵԼԵՂ ԿՈՒԴԵԼԵՂ.

ԼԵՐԿ # 3: ՎԵԼԵ ԵՐՈՒՆ ՕՒ ԲԵՉԲԻՆՂ ԲԵ ԲՈՒԿ ԼԵ ԿԵԼԵԼԵՂ ԲՈ ԲԵ ԲԼԵԴԲՈՒՆՆ.

IsuK D9fg IsuK # 3

D!gwefe!:
IsuK 1ab6:
2bec!t!c C!gaf!f!:


J00 t.
Λe!f!c9! N21
0.80

05\J4\50J2
1!gaf!2 B!cKef2ou

Hef!g!f:
Coufeuf2:
b!o9ncf Γe!e!:

520 t.
1b-8
5J0.5 t.

05\J4\50J2
Cef!t!e9 1!g!f



All dimensions, line locations, sizes and valve descriptions have been furnished by the facility operator.

[illegible]

Tank Test Results Summary Mass Technology Corporation

Mass (ft H₂O)

160.050
160.048
160.046
160.044
160.042
160.040
160.038
160.036
160.034
160.032
160.030

20 25 30 35 40 45 50 55 60 65 70 75 80 85 90 95 100 105 110 115 120 125 130

Tank: Red Hill Tank 3

Test Results

Test No.: 2015

Start Date: 2/14/15

End Date: 2/19/15

The linear regression performed on data for the 5-day test sequence indicates a volumetric change rate below the MDLR of 0.5 GPH and is interpreted as "NO LEAK".

Linear Regression

Compensated Data



Precision Leak Measurement Report
P.O. Box 1578
Kilgore, Texas 75662


ԷԼԵԿ ԲԵՐ ԻՈՒՍ
ԲԵՐԼ ԻՅԻՐՈՒ, ԻԼ

ԲԻՐՈՅԵԼ ԿՈՄՊԵՆԻ – ԿԻԼԳՈՐ ԵՐԿՐ ԵՐԿՐՈՒ

ՉԻԲԵ ՉՈՒԲԵԼԻՉՈՒ – ԼԻՅԻԼԻՉ ԲԻԿԵԲԵՐՈՒ

ՉԵՐԵ ՕԼ ԿՈՒԿ: ԷՆԻՄԻՐ ԳԼ ԼԵԴՈՒԼԵՐ ԿՈՄՊԵՆԻՄԵՆԼ, ԼԵՐՈՒ, ՉԵԼԻԿԵՉ, ԿՐԵԼԻՅԻՉ ԳՈՐ ԵԴՈՒԲԿԵՆԼ
ԲՈ ԴԵԼԵՐԿ ԲԵ ԼԵԴՈՒԼԵՐ ԳՈՍՈՐԳ ԲԼԵԲԲՈՒՆԵՉ ԲԵՉԲԻՅՈՒ ՕԼ ԼԵՐԿ # Գ ԳՈ ՈՐԴԵԼԵՐՈՒՄԳ
ԷՈԵԼ ՉԲՈՐԳԵ ԲՅՈՒ ԼՈԿԵԲՈՒ ԳԲ ԷԼԵԿ ԲԵՐ ԻՈՒՍ, ԲԵՐԼ ԻՅԻՐՈՒ, ԻԼ.

ԲԵՐՈՒԲ ԿՈՄԲԼԵԲՈՒ ՔԼ:


ԲԻԿԵԼ ՉԻՅՈՒԲԵՐ


ԴԵԲԵ: ԵՅ-ԵՈ-ՅՈՒԳ

ՉՈՒԿԱՐԵԼ

ԼԵՉԲԻՅՈՒ ՕԼ ԼԵՐԿ # Գ Գ ԵՅ,ԵՈՐ,ՈՐՐ ԵՐԼ ՈՐԴԵԼԵՐՈՒՄԳ ՉԲՈՐԳԵ ԲՅՈՒ ԼՈԿԵԲՈՒ ԳԲ ԷԼԵԿ ԲԵՐ ԻՈՒՍ, ԲԵՐԼ
ԻՅԻՐՈՒ, ԻՅԿՐԵԼԼ ԿՈՒԿԵՆԵԲՈՒ ՕԵԲՈՐԵԼ ԵԲ, ՅՈՒԳ ԳՈՐ ԿՐՉ ԿՈՒԴԼԵԲՈՒ ՕԵԲՈՐԵԼ ՅՅ, ՅՈՒԳ. ԼԲԵ ԼԵՉՈՒԲ ՕԼ
ԲԲԲ ԲԵՉԲԻՅՈՒ ԼՉ ԲԲԲ ԲԲԵ ԲՅՈՒ ՉԼՉԵԿ ԼՉ ԴԵԲԵԿԵԼԵԲՈՒ ԲՈ ՔԵ ԲԼԵԲԲ ԲՈ ԼՉՈԲԲՈՒ. ՎԻՐ ԲՅՈՒ ԼՅԻԼԵՉ ԿԵԼԵ
ԳԴԵԴՈԲԲԵԼԼ ՉԵՐԵԲՈՒ ՉՈՒԲ ԲԲԲ ԵՈ ՈՒՈՒՈՐԳ ԼԵԴՈՒՅՉ ԿԵԼԵ ՈՒԲԵԲ. ԼԵՉԲԻՅՈՒ ԿՐՉ ԴԵԼԵՐԿԵԲ ՈՒՅՈՒՅ ԲԲԵ
ԿՐՉ ԼԵԴՈՒՅՈՒԼԼ ԿՈՒԲՈՐԵԲՈՒ ԴԼՈԲՈՒՅԼ ՉԵԲ ՕՈԲ ԼՈՒ ԲԲԵ ԲԲԻԼԼ ԴՅԻԼԼ ԵԼՅԻՈԲԲՈՒՅ. ՎԻՐ ԲՅՈՒ ԼՅԻԼԵՉ
ԿԵԼԵ ԳԴԵԴՈԲԲԵԼԼ ՉԵՐԵԲՈՒ ՉՈՒԲ ԲԲԲ ԳՈՒ ԷՈՒԼԼ ԿՐՉ ԼՉՈԲԲՈՒ ԲՈ ԼԵԴԿՐԵ. ԼԲԵԼԵԼՈՒԵ, ԲԲԵ
ԿՈՒԲԵԼԵԼԼ ԼՈՒԵԼԼԼԼ ԼՈՒ ԲԲԵ ԲՅՈՒ ԿՐՉ ՈՒԲ ԿՈՒԴԼԵԲՈՒՅԲՈՒ ԳՈՐ ԲԲԵ ԲԵՉԼ ԼՉ ԿՈՒՉԴԵԼԵԲ ԿՈՒԼՈՒՅԼԵ.

ԼԵՐԿ # Գ: ՎԵԲԵ ԵԲՑ ԴՈՒՅ ՕԼ ԲԵՉԲԻՅՈՒ ԲԲԵ ԲՅՈՒ ԼՉ ԿԵԼԼԼԼԼԼԼԼ ԲՈ ՔԵ ԲԼԵԲԲ.

Нелігі:	520 т.
Сондық:	16-8
Бірінші Гөл:	511.01 т.
Сондық:	10\53\5014
Бірінші:	Селітесі 111



All dimensions, line locations, sizes and valve descriptions have been furnished by the facility operator.

[illegible]

Tank Test Results Summary Mass Technology Corporation

Mass (ft H₂O)

Tank	Test No.	Start Date	End Date	Test Results
Red Hill 2014	Tank 4	10/16/14	10/23/14	The linear regression performed on data for the 7-day test period indicates a volumetric change rate below the 0.5 GPH MDLR for this tank and is interpreted as "NO LEAK".

Linear Regression

Compensated Data



Precision Leak Measurement Report
P.O. Box 1578
Kilgore, Texas 75662


ԷԼԵԿ ԲԵՐ ԻՒՒ
ԲԵՐԼ ԻՅԻՐՈՒ, ԻԼ

ԲԻՐՈՋԵԲ ՄԱՍՆԱԶԵՐ – ՄԼ. ՄԱՆԻԿ ՇԻՐՈՒ

ՉԻԲԵ ՉՈՒԲԵԼԻՉՈՒ – ԼԻՅԱԼԶ ԲԻՇԿԵԲՅՈՒ

ՉԵՐԵ ՕՒ ՄՈՒԿ: ԷՆԻՄԻՉՔ ՁԻ ԼԵԺՈՒԼԵՐ ՄԱՍՆԱԶԵՄԵՆԻ, ԼՅՐՈՒ, ՉԵԼԻՇԵՉ, ՄԱԳԵԼԻՅԻՉ ԳՈՐ ԵԺՈՒԲՄԵՆԻ
ԷՐ ԻԵԼԵՐԻՄ ՔԻԵ ԼԵԺՈՒԼԵՐ ԳՈՍՈՐԴԻ ԲԼԵՄԲՈՒՆԵՉ ԲԵՉԲԻՆՅՈՒ ԵՐ ԼՅՈՒԿ # Ե ԳՈ ՈՍԳԵԼԵՐՈՍՈՍԳ
ԷՈՒԵԼ ՉԲՈՒՆԱԶԵ ԲՅՈՒԿ ԼՈՇԳԵՐԳ ԳԲ ԷԼԵԿ ԲԵՐ ԻՒՒ, ԲԵՐԼ ԻՅԻՐՈՒ, ԻԼ.

ԲԵՐՈՒԲ ԿՈՄԲԼԵՐԳ ՔԻ:


ԲԻՇԿԻՆ ՉԻՆԳԻՎԻ

ԾԳԲԵ: ԵՏ-ԵՐ-ՅՐԵԺ

ՉՈՄԱՄԱՐԻՆ

ԼԵՉԲԻՆՅՈՒ ԵՐ ԼՅՈՒԿ # Ե Գ ԵՏ,ԵՐՐ,ՐՐՐ ԶԻԼ ՈՍԳԵԼԵՐՈՍՈՍԳ ՉԲՈՒՆԱԶԵ ԲՅՈՒԿ ԼՈՇԳԵՐԳ ԳԲ ԷԼԵԿ ԲԵՐ ԻՒՒ, ԲԵՐԼ
ԻՅԻՐՈՒ, ԻՅՄԱՅԻԻ ԿՈՄԱՄԵՆԵՐԳ ՕՇԲՈՐԵԼ ԵԺ, ՅՐԵԺ ԳՈՐ ՄԱՉ ԿՈՄԲԼԵԲԵՐԳ ՕՇԲՈՐԵԼ ՅԵ, ՅՐԵԺ. ԼՔԵ ԼԵՉՈՒԲ ՕՒ
ՔԻՅԲ ԲԵՉԲԻՆՅՈՒ ԻՉ ՔԻՅԲ ՔԻԵ ԲՅՈՒԿ ՉԼՉԲԵՄ ԻՉ ԳԵԲԵԼԻՄԵՐԳ ԷՐ ՔԵ ԲԼԵՄԲ ԷՐ ԻՉՈՒԳԲՈՒ. ՎԻԼ ԲՅՈՒԿ ԼՅԻԼԵՉ ՄԵԼԵ
ԳԳԵԺՈՒԳԲԵԼԻՆ ՉԵՐՈՒԼԵՐ ՉՈՒՔ ՔԻՅԲ ՈՒ ՈՍՈՒՆԴԻԼ ԼԵՐԳԻՆՅՈՒ ՄԵԼԵ ՈՒԲԵՐԳ. ԼԵՉԲԻՆՅՈՒ ՄԱՉ ԻԵԼԵՐԻՄԵՐԳ ՈՒՆՅՈՒ ՔԻԵ
ՄԱՉՉ ԼԵՐՄՈԼՈԶԻ ԿՈՒԲՈՒՆԴԻՈՒ ԻՐՈԲՈՇՈՒՉ ՉԵԲ ՕՈՒԻ ԻՄ ՔԻԵ ՔԻԼԻՐ ԻՅԻԼԻՆ ԵԼՅԻՆԴԻՈՒՆԻ. ՎԻԼ ԲՅՈՒԿ ԼՅԻԼԵՉ
ՄԵԼԵ ԳԳԵԺՈՒԳԲԵԼԻՆ ՉԵՐՈՒԼԵՐ ՉՈՒՔ ՔԻՅԲ ԳՈՒՆ ԷՈՒԻՐ ԼՈՉՉ ՄԱՉ ԻՉՈՒԳԲԵՐԳ ԷՐ ԼԵՐԿԱԶԵ. ԼՔԵԼԵԲՈՒԵ, ՔԻԵ
ԿՈՒԳԲԻՄԱՄԵՆԻ ԼՈՒԲԵՐԼԻՆ ՕՒ ՔԻԵ ԲՅՈՒԿ ՄԱՉ ՈՒԲ ԿՈՄԲԼՈՒՄԻՉԵՐԳ ԳՈՐ ՔԻԵ ԲԵՉԲ ԻՉ ԿՈՒՉԻՐԵՐԳ ԿՈՒՇԻՆԻՆԻՆԵ.

ԼՅՈՒԿ # Ե: ՎԷԲԵԼ ԵՐՑ ԻՐՈՒՆԻ ՕՒ ԲԵՉԲԻՆՅՈՒ ՔԻԵ ԲՅՈՒԿ ԻՉ ԿԵԼԲԻՆԵՐԳ ԷՐ ՔԵ ԲԼԵՄԲ.




IsuK Dəfə IsuK # 6

Dİəwəfəi: 100 k.
IsuK 1əb6: 16i!cə1 121
2bəc!t!c Cəəv!fλ: 0.80

Həlgəf: 520 k.
Cəw!cəu!z: 1b-8
b!o9ncf 1əvəi: 511.ə k.

2fəi!f Dəf6: 10\14\5014
1u!f O!bərəfəi: 11əv!z B!c!cəf2ou


Cəw!b!c!ou Dəf6: 10\51\5014
1əz! Bəz!f2: Cəi!t!c9 1!gəf



All dimensions, line locations, sizes and valve descriptions have been furnished by the facility operator.

[illegible]

190K # 0 12 0614169 to 06 1184.





Precision Leak Measurement Report
P.O. Box 1578
Kilgore, Texas 75662


ԷԼԵԿ ԲԵՐ ԻՈՒՍ
ԲԵՐԱԼ ԻՍԻՐՈՒ, ԻԼ

ԲԻՐՈՂԵԿ ԿՈՄՊԼԵԿՏ – ԿԻԼԳՈՐ ԵՐԿՐԱՆ

ՉԻՔ ԶՈՒԲԵԼԱԶՈՒ – ԼԻՂԱԼԶ ԲԻՐՔԵԼԶՈՒ

ՉԵՐԵ ՕՒ ԿՈՐԿ: ԷՆԻՄԻՔ ԳԼԻ ԼԵՐՈՒԼԵՐԻ ԿՈՄՊԼԵԿՏԵՆԻ, ԼԻՐՈՒ, ՉԵԼԱԿԵԶ, ԿԱԳԵԼԱԶԻԶ ԳՈՐԾՈՒԹՅԱՆԻ
ԲՈ ԴԵԼՈՒԿ ԲԼԵ ԼԵՐՈՒԼԵՐԻ ԳՈՍՈՒՅԻ ԲԼԵՐԻՄԵԶԶ ԲԵԶԲԻՄԵՐ ՕՒ ԼԻՐԿ # 1 ԳՈ ՈՍԳԵՐԵՐՈՒՄԻ
ԷՆԵԼ ԶԲՈՐԱԶԵ ԲՈՒԿ ԼՈՑԲԵՐԻ ԳԻ ԷԼԵԿ ԲԵՐ ԻՈՒՍ, ԲԵՐԱԼ ԻՍԻՐՈՒ, ԻԼ.

ԿԵՐՈՒԲ ԿՈՄՔԼԵԿՐ ԲՆ:


ԲԻՐԿՆ ԶԻՆԳԻՐ

ԾԳԲԵ: ԵԶ-ԵՐ-ԶՈՒԿ

ՉՈՒՄԱՐԻՆ

ԼԵԶԲԻՄԵՐ ՕՒ ԼԻՐԿ # 1 Գ ԵԶ,ԵՐՈՒ,ՈՐՈՒ ԶՈՒ ՈՍԳԵՐԵՐՈՒՄԻ ԶԲՈՐԱԶԵ ԲՈՒԿ ԼՈՑԲԵՐԻ ԳԻ ԷԼԵԿ ԲԵՐ ԻՈՒՍ, ԲԵՐԱԼ
ԻՍԻՐՈՒ, ԻՂԱՐԻՍ ԿՈՒՄԵՆԵԿԵՐ ՈՒԼԵՄԲԵԼ ԵԶ, ՆՈՒԿ ԳՈՐԾ ԿԱԶ ԿՈՒՄՔԼԵԿԵՐ ՈՒԼԵՄԲԵԼ ՆՆ, ՆՈՒԿ. ԼԲԵ ԲՈՒԿ
ԿՈՒԳԻՄԵՐ ԵԶ-Զ ԳՈՐԾ Գ ԴԵԿԵԶԻՈՒ ԼԵՐԿ ԲԵԶԲ ԿԱԶ ԿՈՒԳՈՒԿԵՐԻ. ԼԲԵ ԼԵԶՈՒԿ ՕՒ ԲԼԵԶԲ ԲԵԶԲԻՄԵՐ ԼԶ ԲԼԵԶԲ ԲՈՒԿ
ԶԼԶԵՄ ԼԶ ԳԵԲԵԼԱՄԵՐԻ ԲՈ ԲԵ ԲԼԵԶԲ ԲՈ ԼՈՐԱԳԻՈՒ. ՎԻԻ ԲՈՒԿ ՆՂԻԼԵԶ ԿԵԼԵ ԳԳԵՐՈՒԳԵԼԻՆ ԶԵՐՈՒԿ ԶՈՒԿ ԲԼԵԶԲ
ՈՍՈՒԶՈՒՅԻ ԼԵՐԳԻՄԵՐԶ ԿԵԼԵ ՈՒԿԵՐԻ. ԼԵԶԲԻՄԵՐ ԿԱԶ ԴԵԼՈՒԿՆԵՐԻ ՈՒՄԵՐ ԲԼԵ ԿԱԶԶ ԼԵԿՏՈԼՈԳԻ ԿՈՒԴՈՒԳԻՈՒ
ԴԻՓՈԿՈԼԶ ԶԵԲ ՕՈՒԿ ԼՈՒ ԲԼԵ ԲԼԵԶԲ ԴՂԻՆԻՆ ԵՂԻՆԻՆԻՈՒՅԻ. ՎԻԻ ԲՈՒԿ ՆՂԻԼԵԶ ԿԵԼԵ ԳԳԵՐՈՒԳԵԼԻՆ ԶԵՐՈՒԿ ԶՈՒԿ ԲԼԵԶԲ
ԳՈՒՂ ԷԼԻՐԻ ԼՈՒԶ ԿԱԶ ԼՈՐԱԳԵՐԻ ԲՈ ԼԵՐԿԱԶԵ. ԼԲԵԼԵԼՈՒԿ, ԲԼԵ ԿՈՒԳԻՄԱՆԵՐԻ ԼՈՒԳԵԼԻՆԻՂ ՕՒ ԲԼԵ ԲՈՒԿ ԿԱԶ ՈՒԿ
ԿՈՒՄՔԼՈՒՅԵՐԻ ԳՈՐԾ ԲԼԵ ԲԵԶԲ ԼԶ ԿՈՒԶԻՐԵԼԵՐԻ ԿՈՒԿՈՒԶԼԵ.

ԼԻՐԿ # 1: ՎԵԼԵԼ ԵՐԶ ԴՈՒՐԶ ՕՒ ԲԵԶԲԻՄԵՐ ԲԼԵ ԲՈՒԿ ԼԶ ԿԵԼԻՆԵՐԻ ԲՈ ԲԵ ԲԼԵԶԲ.

IsuK Dgfg IsuK # 1

D!gwefe!:
 IsuK 1gbe:
 2bec!t!c C!gvl!f!g:


J00 t.
 Ael!cgl N21
 0.85
 JJ\J2\50J4
 11gvl2 B!cKef2ou

Helg!f:
 Coufeuf2:
 b!oQncf Gel!l:

520 t.
 1b-2
 5JS.52 t.
 JJ\55\50J4
 Cgl!t!eQ 1!glf

2fglf Dgfe:
 Nu!f Obelsgfor:


Combl!f!ou Dgfe:
 1g2f Bgzn!f2:



All dimensions, line locations, sizes and
 valve descriptions have been furnished
 by the facility operator.

[illegible]

190K # 12 cells!69 fo 06 figMf.



IsuK D9fg IsuK # 8

D!gwefe!:
IsuK 1ab6:
2bec!t!c C!gaf!f!:


J00 t!f.
^e!f!c9! N21
0.85

J0\J4\50J4
1!gaf!2 B!c!ef2ou

H6!g!f:
Coufeuf2:
b!o9ncf f!el:

520 t!f.
1b-2
5JJ.08 t!f.


J0\5J\50J4
C6!f!t!e9 1!g!f



All dimensions, line locations, sizes and valve descriptions have been furnished by the facility operator.

[illegible]

190K # 8 !2 c6rf!t!69 fo p6 f!gμf.





Precision Leak Measurement Report
P.O. Box 1578
Kilgore, Texas 75662


ԷԼԵԿ ԲԵՐ ԻՒՒ
ԲԵՐԼ ԻՅԻՐՈՒ, ԻԼ

ԲԻՐՈՅԵԲ ՄԱՍՆԱՅՁԵՐ – ՄԼ. ՄԱՆԻԿ ՇԻՐՈՒ

ՉԻԲԵ ՉՈՒԲԵԼԻՉՈՒ – ԼԻՅՈՒՆ ԲԻՇԿԵԲՅՈՒ

ՉԵՐԵ ՕՒ ՄՈՒԿ: ԷՆԻՄԻՆՔ ԳԼԼ ԼԵՃՈՒԼԵՐ ՄԱՍՆԱՅՁԵՄԵՆԻ, ԼՅՐՈՒ, ՉԵԼԻՇԵՆ, ՄԱԳԵԼԻՅԻՆ ԳՈՐԾՈՒԹՅԱՆԻ
ԲՈ ԴԵԼՈՒՄ ՔԻԵ ԼԵՃՈՒԼԵՐ ԳՆՆՈՅԻ ԲԼԵՄԲՈՒՆՆ ԲԵՉԲԻՆՅՈՒ ՕՒ ԼՅՈՒԿ # Զ ԳՆ ՈՍԳԵԼԵՐՈՒՍԻՊ
ԷՆԵԼ ՉԲՈՒՅՁԵ ԲՅՈՒԿ ԼՈՇԲԵՐ ԳԲ ԷԼԵԿ ԲԵՐ ԻՒՒ, ԲԵՐԼ ԻՅԻՐՈՒ, ԻԼ.

ԲԵՐՈՒԲ ՇՈՒԲԼԵՐ ՔԼ:


ԲԻՇԿԼ ՉԻՅՈՒՑԻՔԵՐ

ԾԳԲԵ: ՅՏ-ՅՕ-ՅՕՅԺ

ՉՈՒՄԱՐԻՆ

ԼԵՉԲԻՆՅՈՒ ՕՒ ԼՅՈՒԿ # Զ Գ ԵՏ,ԵՕՕ,ՕՕՕ ԶԻԼ ՈՍԳԵԼԵՐՈՒՍԻՊ ՉԲՈՒՅՁԵ ԲՅՈՒԿ ԼՈՇԲԵՐ ԳԲ ԷԼԵԿ ԲԵՐ ԻՒՒ, ԲԵՐԼ
ԻՅԻՐՈՒ, ԻՅՄԱՅԻՒ ՇՈՒՄԵՆԵՐ ՕՇԲՈՐԵԼ ՅՏ, ՅՕՅԺ ԳՈՐԾ ՄԱՅ ՇՈՒԲԼԵԲԵՐ ՕՇԲՈՐԵԼ ՅԶ, ՅՕՅԺ. ԼՔԵ ԼԵՉՈՒԲ ՕՒ
ՔԻՅԲ ԲԵՉԲԻՆՅՈՒ ԻՆ ՔԻՅԲ ՔԻԵ ԲՅՈՒԿ ՉԼՉԲԵՄ ԻՆ ԳԵԲԵԼԻՄԵՐ ԲՈ ՔԵ ԲԼԵՄԲ ԲՈ ԻՅՈՅԲԻՈՒ. ՎԻԼ ԲՅՈՒԿ ԼՅԻԼԵՆ ՄԵԼԵ
ԳԳԵԾՈՅԲԵԼԻ ՉԵՐՈՒԵՐ ՉՈՒՔ ՔԻՅԲ ՆՕ ՈՍՈՒՅՈՅԻ ԼԵՐԳԻՆՅՆ ՄԵԼԵ ՆՕԲԵՐ. ԼԵՉԲԻՆՅՈՒ ՄԱՅ ԴԵԼՈՒՄԵՐ ՈՆԻՆՅՈՒ ՔԻԵ
ՄԱՅՆ ԼԵՐՄՈԼՈԳԻ ԸՈՒԲՈՒՅԲԻՈՒ ԴԻՓՈՇՈՒՆ ՉԵԲ ՕՈՒԻ ԻՆ ՔԻԵ ՔԻԼԻՐ ԴՅԻԼԻ ԵՎՅԻՆՅԲԻՈՒՆ. ՎԻԼ ԲՅՈՒԿ ԼՅԻԼԵՆ
ՄԵԼԵ ԳԳԵԾՈՅԲԵԼԻ ՉԵՐՈՒԵՐ ՉՈՒՔ ՔԻՅԲ ԳՆԼ ԷՆԻՐ ԼՈՅՆ ՄԱՅ ԻՅՈՅԲԵՐ ԲՈ ԼԵՐԿԱՅԵ. ԼՔԵԼԵՒՈՒԵ, ՔԻԵ
ՇՈՒԲՅԻՄԱՆԻ ԼՆԲԵՐԼԻՆ ՕՒ ՔԻԵ ԲՅՈՒԿ ՄԱՅ ՆՕԲ ՇՈՒԲԼՈՒՄԻՅԵՐ ԳՈՐԾ ՔԻԵ ԲԵՉԻ ԻՆ ՇՈՒՉԳԵԼԵՐ ՇՈՒՈՒՆԻՆԼԵ.

ԼՅՈՒԿ # Զ: ՎԷԲԵԼ ԵՐՑ ԴՈՒՆՆ ՕՒ ԲԵՉԲԻՆՅՈՒ ՔԻԵ ԲՅՈՒԿ ԻՆ ՇԵԼԲԻՒԼԵՐ ԲՈ ՔԵ ԲԼԵՄԲ.




IsuK D9fg IsuK # 0

D!gwefei: J00 t.
 IsuK Lgb6: Λeif!c9l N2L
 Zbec!t!c C!gvl!fλ: 0.85

Heliγf: S20 t.
 Couf6uf2: 1b-2
 b!o9ncf Γe!el: SJT.Δ8 t.

Zfglf D9f6: J0\SS\SOJ†
 Nu!f Ob6!r9fou: L!gvlz B!cK6f2ou


Cowb!ef!ou D9f6: J0\S0\SOJ†
 L6zf B6zn!f2: C6!f!t!69 L!gμf



All dimensions, line locations, sizes and
 valve descriptions have been furnished
 by the facility operator.

[illegible]

190K # 2 is self!69 to 06 figMf.




190K D9fg 190K # 10

Diagram: 100 ft.
190K 14b6: 161ftc91 021
2b6c!t!c 019!fλ: 0.85

2fg1f D9f6: 10\31\5014
0u!f 0b619f01: 119!2 B!cK6f20u

Helg!f: 520 ft.
Couf6u!2: 1b-2
b!o9ncf Γ6161: 511.43 ft.


Compl6f!ou D9f6: 11\01\5014
162f B62n!f2: C61f!t!69 1!g!f



All dimensions, line locations, sizes and
valve descriptions have been furnished
by the facility operator.

[illegible]

190K # 10 12 14 16 18 20 22 24 26 28 30 32 34 36 38 40 42 44 46 48 50 52 54 56 58 60 62 64 66 68 70 72 74 76 78 80 82 84 86 88 90 92 94 96 98 100





Precision Leak Measurement Report
P.O. Box 1578
Kilgore, Texas 75662


ԷԼԵԿ ԲԵՊ ԻՒՒԼ
ԲԵՅՈՒ ԻՅԱԲՈՒ, ԻԼ

ԲԻՕԼՈԳԻԿԱԼ ՄԱՍՆԱԶԳԵՄԵՆ – ՄԼ. ՄԱՆԻԿ ԸՆԴՈՍ

ՉԻԲԵ ՉՈՒԲԵՐՈՒՄ – ԱՆՎՈՐՆ ԲԼԿԵԲԶՈՍ

ՉԵՐԵ ՕՒ ՄՈՒԿ: ԷՆՈՒՆԻՍ ԳԼԻ ԼԵԺՈՒԼԵՊ ՄԱՍՆԱԶԳԵՄԵՆԻ, ԼՅՐՈՒ, ՉԵՐՎԵՐ, ՄԱԳԵՐԱՅԻՆ ԳՈՐԾՈՒԹՅԱՆ
ԲՈ ԽԵՒՈՒՄ ՔԻՄԵ ԼԵԺՈՒԼԵՊ ԳՆԱՍՈՐԻ ԲԼԵՊԲԱՆԵՐ ԲԵՐԲՈՒՄ ՕՒ ԱՅՈՒԿ # ԴԴ ԳՈ
ՈՍԳԵՐՈՒՄԻ ԷՆԵՐ ԶՓՈՐԶԵ ԲՅՈՒԼՈՐԵՊ ԳԻ ԷԼԵԿ ԲԵՊ ԻՒՒԼ, ԲԵՅՈՒ ԻՅԱԲՈՒ, ԻԼ.

ԲԵՐՈՒԲ ԿՈՄԽԻԼԵՊ ՔԼ:


ԲԼԿԼ ՉԻՆԴԻԼԻ

ԾԳԲԵ: 03-Դ3-ՏՈԴ2

ՉՈՒՄԱՐԻՆ

ԱԵՐԲՈՒՄ ՕՒ ԱՅՈՒԿ # ԴԴ Գ ԴՏ,ԵՐՐ,ՐՐՐ ԶՐԻ ՈՍԳԵՐՈՒՄԻ ԶՓՈՐԶԵ ԲՅՈՒԼՈՐԵՊ ԳԻ ԷԼԵԿ ԲԵՊ ԻՒՒԼ, ԲԵՅՈՒ
ԻՅԱԲՈՒ, ԻՅՄԱՅԻՒ ԿՈՒՄԱՆԵՐԵՊ ԷԵՐԻՆԴՐԻՆ Դ8, ՏՈԴ2 ԳՈՐԾ ՄԱՅ ԿՈՒԽԼԵԲԵՊ ԷԵՐԻՆԴՐԻՆ Դ3, ՏՈԴ2. ԱՔԵ ԼԵՐՈՒԲ ՕՒ
ՔՐԳԻ ԲԵՐԲՈՒՄ ԻՆ ՔՐԳԻ ՔԻՄԵ ԲՅՈՒԿ ՉԼԶԲԵՄ ԻՆ ԳԵԲԵՐՈՒՄԵՊ ԲՈ ՔԵ ԲԼԵՊԻ ԲՈ ԻՅՈՐԲՈՒՄ. ՎԻԻ ԲՅՈՒԿ ԼԳԻԼԵՆ ՄԵՐԵ
ԳԳԵԺՈՐԲԵԼԻՆ ԶԵՐՈՒԼԵՊ ՉՈՒԽ ՔՐԳԻ ՈՍ ՈՍՈՒՆԴՐԻ ԼԵՐԳԻՄԶՆ ՄԵՐԵ ՈՒԲԵՊ. ԱԵՐԲՈՒՄ ՄԱՅ ԽԵՒՈՒՄԵՊ ՈՆԻՄ ՔԻՄԵ
ՄԱՅՆ ԱԵՐԽՈՐՈԼՈԳԻ ԿՈՒԽՈՐԲՈՒՄ ԽՐՈԲՈՐՈՒՆ ԶԵԲ ՕՈՒԻ ԻՍ ՔՐԵ ՔՐԻԼԻ ԽԳԻՆԻ ԵՐԳԻՆԴՐՈՒՆ. ՎԻԻ ԲՅՈՒԿ ԼԳԻԼԵՆ
ՄԵՐԵ ԳԳԵԺՈՐԲԵԼԻՆ ԶԵՐՈՒԼԵՊ ՉՈՒԽ ՔՐԳԻ ԳՆԼ ԷՆԻԳ ԼՈՅՆ ՄԱՅ ԻՅՈՐԲՈՒՄ ԲՈ ԼԵՐԿԱԶԵ. ԱՔԵՐԵՒՈՒՐ, ՔՐԵ
ԿՈՒԲՈՒՄԱՆԻ ԼՈՒԲԵՐԼԻՆ ՕՒ ՔՐԵ ԲՅՈՒԿ ՄԱՅ ՈՒԲ ԿՈՒԽՐՈՒՄԵՊ ԳՈՐԾ ՔՐԵ ԲԵՐԲ ԻՆ ԿՈՒՆԴԵՐԵՊ ԿՈՒՆԻՆԻԼԵ.

ԱՅՈՒԿ # ԴԴ: ՎԷԲԵՐ ԴՏՐ ՔՈՒՆԻՆ ՕՒ ԲԵՐԲՈՒՄ ՔՐԵ ԲՅՈՒԿ ԻՆ ԿԵՐԲԻԼԵՊ ԲՈ ՔԵ ԲԼԵՊԻ.


IsuK Dəfə IsuK # JT

Dıgıwəfəı: J00 k.
IsuK ııəbē: Λəıf!cəı ıı2ı
Zbēc!t!c Cıəv!fλ: 0.85

Həlgıf: 520 k.
Cıwəfıfz: ıb-2
bıođncf Γəvəı: 5JT.ə k.

Zfəıf Dəfē: 05\J8\50J2
ııu!f Ođəıəfıı: ııəv!z B!cKəfzıı


Cıwəıəf!ıı Dəfē: 05\53\50J2
ııəzf Bəznıfz: Cəıf!t!əđ ıılgıf



All dimensions, line locations, sizes and valve descriptions have been furnished by the facility operator.

[illegible]

190K # JJ !2 c6rf!t!69 fo P6 f!gMf.





Precision Leak Measurement Report
P.O. Box 1578
Kilgore, Texas 75662


ԷԼԵԿ ԲԵՐ ԻՈՒՍ
ԲԵՐԱԼ ԻՍԻՐՈՒ, ԻԼ

ԲԻՐՈՂԵԿ ԿՈՄՊԼԵԿՏ – ԿԻԼԳՈՐ ԵՐԿՐԱՆ

ՉԻՔ ԶՈՒԲԵԼԱԶՈՒ – ԱԳՆԱԶ ԲԻՐՔԵԶՈՒ

ՉԵՐԵ ՕՒ ԿՈՒՐԿ: ԷՆԱՆԶԻ ՍԻԼ ԼԵՃՈՒԼԵՐԻ ԿՈՄՊԼԵԿՏԵՆԻ, ԼԻՐՈՒ, ՉԵԼԱԿԵԶ, ԿԱԳԵԼԱԶԻԶ ԳՈՐԾՈՒԹՅԱՆԻ
ԲՈ ԴԵԼՈՒԿ ՔՐԵ ԼԵՃՈՒԼԵՐԻ ԳՆԱՈՒՅԻ ԲԼԵՄԲԱԶԶ ԲԵԶԲԱՆՈՒ ՕՒ ԱԳՐԿ # 15 ԳՈ
ՈՐԴԵՐԵԼՈՒՄԻ ԷՆԵԼ ԶՈՒԲԵԼԱԶԵ ԲԱՐԿ ԼՈԿԱԳԵՐ ԳԻ ԷԼԵԿ ԲԵՐ ԻՈՒՍ, ԲԵՐԱԼ ԻՍԻՐՈՒ, ԻԼ.

ԲԵՐՈՒԿ ԿՈՄՊԼԵԿՏ ՔԼ:


ԲԻՐՔԼ ՉԻՐԱՆԴՅԱՆ

ԾԱԳԵ: 15-10-5014

ՉՈՒՄԱՐԱԿ

ԱԵԶԲԱՆՈՒ ԱԳՐԿ # 15 Գ 15,000,000 ԶՈՐ ՈՐԴԵՐԵԼՈՒՄԻ ԶՈՒԲԵԼԱԶԵ ԲԱՐԿ ԼՈԿԱԳԵՐ ԳԻ ԷԼԵԿ ԲԵՐ ԻՈՒՍ, ԲԵՐԱԼ ԻՍԻՐՈՒ, ԻՍԿԱՆՈՒ ԿՈՒՄԱՆԵԿԻ ՈՐԴԵՐԱՐԵԼ Ե, 5014 ԳՈՐ ԿԱԶ ԿՈՄՊԼԵԿՏԻ ՈՐԴԵՐԱՐԵԼ 13, 5014. ԱՐԵ ԼԵԶՈՒԿ ՕՒ ՔՐԱԳ ԲԵԶԲԱՆՈՒ Զ ԶՐԵԼԱԿՈՒՄԻ ԲՈ ՔԵ ԲԼԵՄԲ ԲՈ ԶՈՒԲԵԼԱԶ. ՎԻԼ ԲԱՐԿ ԼԱԶԵԶ ԿԵԼԵ ԳՐԵԾՈՒԳԵԼԱԿ ԶԵՐՈՒԼԵՐԻ ԶՈՒՔ ՔՐԱԳ ՈՒ ՈՒՆԶՈՒՅԻ ԼԵՐԳԱՆՆԵԶ ԿԵԼԵ ՈՒԲԵԼ. ԱԵԶԲԱՆՈՒ ԿԱԶ ԴԵԼՈՒԿՈՒՄԻ ՈՒՆՆԵԶ ՔՐԵ ԿԱԶԶ ԱԵԿՆՈԼՈԳԻ ԿՈՒՐՈՒԳԵԼՈՒ ԴԻՓՈԿՈԼԶ ԶԵԲ ՕՒԿ ԻՍ ՔՐԵ ՔՐԱԿ ԴԱԿԼԱ ԵՆԶԻՆԵԼՈՒՄԸ. ՎԻԼ ԲԱՐԿ ԼԱԶԵԶ ԿԵԼԵ ԳՐԵԾՈՒԳԵԼԱԿ ԶԵՐՈՒԼԵՐԻ ԶՈՒՔ ՔՐԱԳ ԳՆԱԿ ԷՆԻՐԻ ԼՈԶԶ ԿԱԶ ԶՈՒԲԵԼԱԶ ԲՈ ԼԵՐԿԱԶԵ. ԱՐԵԼԵԴՈՒՄԸ, ՔՐԵ ԿՈՒԳԵԼԱՄԱՆԻ ԼԱԳԵՐԼԱԿ ՕՒ ՔՐԵ ԲԱՐԿ ԿԱԶ ՈՒԿ ԿՈՄՊԼՈՒԶԵՐԻ ԳՈՐ ՔՐԵ ԲԵԶԲ Զ ԿՈՒԶԼԵՐԵՐԻ ԿՈՒՆԻՆԶԱԼԵ.

ԱԳՐԿ # 15: ՎԷԲԵԼ 1Ե8 ԴՈՒՆԸ ՕՒ ԲԵԶԲԱՆՈՒ ՔՐԵ ԲԱՐԿ Զ ԿԵԼԲԻԼԵՐԻ ԲՈ ՔԵ ԲԼԵՄԲ.

IsuK D9fg IsuK # JS

D!gwefe!:
IsuK 1gh6:
2bec!t!c C!gvl!f!:


J00 t.
Λe!f!c9! N21
0.85

JT\0E\50J†
1!gvl!z B!cK6f2ou

H6!g!f:
Coufeuf2:
b!o9ncf Γe!e!:

520 t.
1b-2
5JS.30 t.


JT\J3\50J†
C6!f!t!e9 1!g!f



All dimensions, line locations, sizes and valve descriptions have been furnished by the facility operator.

[illegible]

190K # JS !2 c6rf!t!69 fo p6 f!gMf.





Precision Leak Measurement Report
P.O. Box 1578
Kilgore, Texas 75662


ԷԼԵԿ ԲԵՊ ԻՈՒՍ
ԲԵՐԱԼ ԻՅԱՐՈՒ, ԻԼ

ԲԻՐՈՋԵԲ ՄԱՍՆԱԶԵՐ – ՄԼ. ՄԱՐԿ ՇԱԳՐՈՒ

ՉԻԲԵ ՉՈՒԲԵԼԱԴՅՈՒՆ – ԱԼԳԱԴՆ ԲԼԿԵԲԶՈՒ

ՉԵՐԵՔ ՕԷ ՄՈՒԿ: ԷՆԱՆԻՔ ՁԻՒ ԼԵԺՈՒԼԵՊ ՄԱՍՆԱԶԵՐՄԵՆԷ, ԼՅՐՈՒ, ՉԵԼԱԿԵՉ, ՄԱԳԵԼԱԳԻՆԶ ԳՈՐԺ ԵԺՈՒԲՈՒՄԵՆԷ
ԲՈ ԻԵԼԵՐԱՄ ՔՐԵ ԼԵԺՈՒԼԵՊ ԳՈՍՈՒՅԻ ԲԼԵՊԲԱՆԵՉԶ ԲԵՉԲԻՆՍՑ ՕԷ ԱԳՈՒԿ # ԴԴ ԳՈ
ՈՍԳԵԼԵՐՈՍՈՒՊ ԷՈՒԷ ՉԲՈՒՅԵԸ ԲՅԱՒ ԼՈՇԱԲԵՊ ԳԷ ԷԼԵԿ ԲԵՊ ԻՈՒՍ, ԲԵՐԱԼ ԻՅԱՐՈՒ, ԻԼ.

ԲԵՐՈՒԲ ՇՈՒԲԼԵՊ ՔԼ:


ԲԼԿԼ ՉԻՅՈՒՑԲԵԼ

ԴՅԲԵ: 02-Դ8-ՅՐԴ2

ՉՈՒՄԱՐԱԼ

ԱԵՉԲԻՆՍՑ ՕԷ ԱԳՈՒԿ # ԴԴ Գ ԴՅ,ԵՐՐ,ՐՐՐ ԶՅԱՒ ՈՍԳԵԼԵՐՈՍՈՒՊ ՉԲՈՒՅԵԸ ԲՅԱՒ ԼՈՇԱԲԵՊ ԳԷ ԷԼԵԿ ԲԵՊ ԻՈՒՍ, ԲԵՐԱԼ ԻՅԱՐՈՒ, ԻՅԱՄՅՈՒՍ ԾՈՒՄԱՆԵՐԵՊ ՎԻՒՍԻ ՅԺ, ՅՐԴ2 ԳՈՐԺ ՄԱՉ ՇՈՒԲԼԵՊ ՄԱԳ Կ, ՅՐԴ2. ԱՔԵ ԼԵՉՈՒԲ ՕԷ ՔՐԵՉ ԲԵՉԲԻՆՍՑ ԻՉ ՔՐԵՉ ՔՐԵ ԲՅԱՒ ՉԼՉԲԵՄ ԻՉ ԳԵԲԵԼԱՄԵՊ ԲՈ ՔԵ ԲԼԵՊԲ ԲՈ ԻՉՈՒՅԲԻՈՒՆ. ՎԻՒ ԲՅԱՒ ԼՅԱԼԵՉ ՄԵԼԵ ԳԳԵԺՈՒՅԲԵԼԼ ՉԵՐՈՒԼԵՊ ՉՈՒՐ ՔՐԵՉ ՈՒ ՈՍՈՒՅՈՒՅԻ ԼԵՊԲԻՆՍՑ ՄԵԼԵ ՈՒԲԵՊ. ԱԵՉԲԻՆՍՑ ՄԱՉ ԻԵԼԵՐԱՄԵՊ ՈՒՅՈՒՅ ՔՐԵ ՄԱՉՉ ԱԵԿՈՒՐՈՒՅԼ ԸՈՒԲՈՒՅԲԻՈՒ իՐՈԲՈՐՈՒՉ ՉԵԲ ՕՈՒԷ ԻՍ ՔՐԵ ՔՐԻԼԳ ԻՅԱԲԼԼ ԵՒՅԻՅԲԻՈՒՆ. ՎԻՒ ԲՅԱՒ ԼՅԱԼԵՉ ՄԵԼԵ ԳԳԵԺՈՒՅԲԵԼԼ ՉԵՐՈՒԼԵՊ ՉՈՒՐ ՔՐԵՉ ԳՈՒՂ ԼՈՉՉ ՄԱՉ ԻՉՈՒՅԲԵՊ ԲՈ ԼԵՊԿՅԵ. ԱՔԵԼԵՐՈՒԵ, ՔՐԵ ՇՈՒՅԻՄԱՄԵՆԷ ԻՍԲԵՐԼԼԼԼ ՕԷ ՔՐԵ ԲՅԱՒ ՄԱՉ ՈՒԲ ՇՈՒԲԼՈՒՄԻՉԵՊ ԳՈՐԺ ՔՐԵ ԲԵՉԲ ԻՉ ՇՈՒՅԲԵԼԵՊ ՇՈՒՈՒՅԻՄԵ.

ԱԳՈՒԿ # ԴԴ: ՎԷԲԵԼ ԴՅՐ ՔՈՒՐԻՉ ՕԷ ԲԵՉԲԻՆՍՑ ՔՐԵ ԲՅԱՒ ԻՉ ՇԵԼԲԼԼԼԼԼԼԼԼ ԲՈ ՔԵ ԲԼԵՊԲ.




IsuK D9fg IsuK # J3

Diagrams: J00 &
IsuK Lgh6: A6f!c9l N2L
Zb6c!t!c Cl9v!fλ: 0.8†

Helgμf: J20 &
Couf6uf2: EΔ9
b!o9ncf Γ6v6l: JJS.†2 &.

Zfguf D9f6: 0†\Jθ\J0J2
Nu!f Ob6r9fou: L!9v!z B!cK6f2ou


Compl6f!ou D9f6: 02\0†\J0J2
L6zf B6zn!f2: C6f!t!69 L!gμf



All dimensions, line locations, sizes and valve descriptions have been furnished by the facility operator.

[illegible]

190K # J3 !2 c6rf!t!69 fo p6 f!gMf.





Precision Leak Measurement Report
P.O. Box 1578
Kilgore, Texas 75662


ԷԻՇԸ ԲԵՊ ԻՈՒՈ
ԲԵՅՈՒ ԿԳԻՐՈՒ, ԻՈ

ԲԻՈՂԵԿԻ ՄԳՆԱՅՑԵՐ – ՄԼ. ՄԳԼԻԿ ԸՆԴՊՈՒ

ՉԻԲԵ ՉՈՒԲԵՐՈՒՄՈՒ – ԼԻՂՈՒՆ ԲԻԿԵԲԶՈՒ

ՉԵՐԵ ՕՒ ՄՈՒԿ: ԷՆՈՒՆԻՔ ՍԻ ԼԵԴՈՒԼԵՊ ՄԳՆԱՅՑԵՄԵՆԻ, ԼՅՐՈՒ, ՉԵՐՈՒԿԵՆ, ՄԳԲԵՐՈՒՆԵ ԳՈՐ ԵԴՈՒԲՈՒՄԵՆԻ
ԲՈ ԴԵՐՈՒՄ ԲՐԵ ԼԵԴՈՒԼԵՊ ԳՆՈՒՆԻՔ ԲԵՐԲՈՒՆԵՆ ԲԵՐԲՈՒՆԵՆ ՕՒ ԼՅՈՒԿ # ԴՇ ԳՈ
ՈՐԴԵՐՈՒՄԻՔ ԷՆԵՐ ԶՐՈՒՅՑԵ ԲՅՈՒԿ ԼՈՑԳԲԵՊ ԳԻ ԷԻՇԸ ԲԵՊ ԻՈՒՈ, ԲԵՅՈՒ ԿԳԻՐՈՒ, ԻՈ.

ԲԵՐՈՒԻ ԿՈՄԲԼԵՊ ԲՆ:


ԲԻԿՆ ԶԻՆԴԻՐԼԻ

ԴՅԲԵ: 02-Դ8-ՏՈԴՇ

ՉՈՒՄԱՐԻՆ

ԼԵՐԲՈՒՆԵ ՕՒ ԼՅՈՒԿ # ԴՇ Գ ԴՇ,ԵՈՈ,ՈՈՈ ԶՈՒ ՈՐԴԵՐՈՒՄԻՔ ԶՐՈՒՅՑԵ ԲՅՈՒԿ ԼՈՑԳԲԵՊ ԳԻ ԷԻՇԸ ԲԵՊ ԻՈՒՈ, ԲԵՅՈՒ ԿԳԻՐՈՒ, ԿԳՄԳՈՒ ԿՈՒՄԵՆԵՐԵՊ ՄԳՆ Զ, ՏՈԴՇ ԳՈՐ ՄԳՇ ԿՈՒԲԼԵԲԵՐԵՊ ՄԳՆ ԴԴ, ՏՈԴՇ. ԼՐԵ ԼԵՐՈՒԻ ՕՒ ԲՐԳԻ ԲԵՐԲՈՒՆԵ ԼՇ ԲՐԳԻ ԲՐԵ ԲՅՈՒԿ ՉՂՇԲԵՈ ԼՇ ԴԵԲԵՐՈՒՄԵՐԵՊ ԲՈ ԲԵ ԲԵՐԲՈՒ ԲՈ ԼՇՈՒՑԲՈՒ. ՎԻՈ ԲՅՈՒԿ ԼՅՈՒՅՇ ՄԵՐԵ ԳԴԵԴՈՒՑԲԵՐԼ ԶԵՐՈՒԼԵՊ ՉՈՒԲՈՒ ԲՐԳԻ ՆՈ ՈՒՆԴՈՒՆԻՔ ԼԵՐԴՈՒՆԵՆ ՄԵՐԵ ՆՈԲԵՐԵ. ԼԵՐԲՈՒՆԵ ՄԳՇ ԴԵՐՈՒՄԵՐԵՊ ՈՒՆԵՆ ԲՐԵ ՄԳՇ ԼԵԴՐՈՒՅՐԵՊ ԿՈՒԲՈՒՑԲՈՒ ԴՐՈԲՈՒՐՈՒՆԵ ԶԵԲ ՕՈՒԻ ԼՆ ԲՐԵ ԲՐԻՐԵ ԴՅՈՒԼ ԵՐԶՈՒՑԲՈՒՆԵ. ՎԻՈ ԲՅՈՒԿ ԼՅՈՒՅՇ ՄԵՐԵ ԳԴԵԴՈՒՑԲԵՐԼ ԶԵՐՈՒԼԵՊ ՉՈՒԲՈՒ ԲՐԳԻ ԳՆՂ ԷՆԻՐԵ ԼՈՇՇ ՄԳՇ ԼՇՈՒՑԲԵՐԵՊ ԲՈ ԼԵՐԿՅԵ. ԼՐԵԼԵՐՈՒԵ, ԲՐԵ ԿՈՒԲՈՒՄԵՆԻ ԼՆԲԵՐԼԻԼ ԵՐԵ ԲՅՈՒԿ ՄԳՇ ՆՈԲ ԿՈՒԲՈՒՄԼԵՐԵՊ ԳՈՐ ԲՐԵ ԲԵՐԻ ԼՇ ԿՈՒՇԴԵՐԵՊ ԿՈՒՇՈՒՆԼԵ.

ԼՅՈՒԿ # ԴՇ: ՎԷԲԵ ԴՏՈ ԴՈՒՆԵ ՕՒ ԲԵՐԲՈՒՆԵ ԲՐԵ ԲՅՈՒԿ ԼՇ ԿԵՐԲՈՒԼԵՐԵՊ ԲՈ ԲԵ ԲԵՐԲՈՒ.


IsuK D9fg IsuK # J2

D!gwe6ei: J00 t.
 IsuK Llb6: Λeif!c9l N2L
 2b6c!t!c C!gA!fλ: 0.8†

H6!gμf: J20 t.
 Couf6u62: tΔ9
 b!o9ncf Γ6Λ6l: JTO.85 t.

2fglf D9f6: 02\0θ\J0J2
 Nu!f Ob6r9fou: L!gA!2 B!cK6f2ou


Cowb!6f!ou D9f6: 02\J†\J0J2
 L6zf B6zn!f2: C6r!t!69 L!gμf



All dimensions, line locations, sizes and
 valve descriptions have been furnished
 by the facility operator.

[illegible]

190K # J2 !2 c6rf!t!69 fo p6 f!gMf.





Precision Leak Measurement Report
P.O. Box 1578
Kilgore, Texas 75662


ԷԼԵԿ ԲԵՂ ԻՈՒՒ
ԲԵՂԻ ԻՂԻՐՈՒ, ԻԻ

ԲԻՐՈՂԵԿ ԽՈՍՈՂՈՒՄ – ԽԻ. ԽՈՂԻԿ ԸՂԻՂՈՒ

ՉԻԲԵ ՉՈՒԴԵՐԼԻՉՈՒ – ԼԻՂԼԻՉ ԲԻԿԵԲԻՉՈՒ

ՉՈՒԴԵ ՕԼ ԽՈՂԻԿ: ԷՐԽԼԻՉ ԳԼ ԼԵԴՈՒԼԵՂ ԽՈՍՈՂՈՒՄԵՒ, ԼՂՐՈՒ, ՉԵՐԼԻԿԵՉ, ԽՂԲԵՐԼԻՉԻ ԳՈՂ ԵԴՈՒԴԽԵՒԼ
ԲՈ ԴԵՐԼՈՒՄ ԲՐԵ ԼԵԴՈՒԼԵՂ ԳՈՍՈՂԻ ԲԼԻՂԲՈՒՆԵՉ ԲԵՉԲԼՈՒՄ ՕԼ ԼՂՈՒԿ # ԼԵ ԳՈ
ՈՍԴԵՐԼՈՒՄ ԷՈՒ ԶԲՈՂՂԵ ԲՈՒԿ ԼՈՑԲԵՂ ԳԼ ԷԼԵԿ ԲԵՂ ԻՈՒՒ, ԲԵՂԻ ԻՂԻՐՈՒ, ԻԻ.

ԲԵՐՈՒԼ ԸՈՒԴԼԵՂ ՐԼ:


ԲԻԿԼ ՉԻՂՈՂԲԵՐ

ԾՂԲԵ: 02-Լ8-ՉՈՂ2

ՉՈՒՄԱՂԻ

ԼԵՉԲԼՈՒ ՕԼ ԼՂՈՒԿ # ԼԵ Գ ԼՉ,ԵՈՐ,ՈՐՐ ԶՂԼ ՈՍԴԵՐԼՈՒՄ ԶԲՈՂՂԵ ԲՈՒԿ ԼՈՑԲԵՂ ԳԼ ԷԼԵԿ ԲԵՂ ԻՈՒՒ, ԲԵՂԻ
ԻՂԻՐՈՒ, ԻՂՄԵՒ ԸՈՒՄԱՆԵԿՂ ԽՂԼ Գ, ՉՈՂ2 ԳՈՂ ԽՂՉ ԸՈՒԴԼԵԿՂ ԽՂԼ Ծ, ՉՈՂ2. ԼՐԵ ԼԵՉՈՒԼ ՕԼ ԲՐՂԼ ԲԵՉԲԼՈՒՄ
ԼՉ ԲՐՂԼ ԲՐԵ ԲՈՒԿ ՉԼՉԵՒ ԼՉ ԴԵԲԵՐԼԽԵՂ ԲՈ ՐԵ ԲԼԻՂԲ ԲՈ ԼՉՈՂԲԼՈՒ. ՎԻՒ ԲՈՒԿ ԼՂԼԵՉ ԽԵՐԵ ԳԴԵԴՈՂԲԵՒԼ
ՉԵՐՈՒԵՂ ՉՈՒԿ ԲՐՂԼ ՈՐ ՈՍՈՂՈՂԻ ԼԵՂԲԼՈՒՄ ԽԵՐԵ ՈՒԼԵՂ. ԼԵՉԲԼՈՒ ԽՂՉ ԴԵՐԼՈՒՄԵՂ ՈՂԼՈՒՄ ԲՐԵ ԽՂՉՉ
ԼԵԿՈՒՈԼՂ ԸՈՒԴՈՂԲԼՈՒ ԴԼՈԲՈԼԻՉ ՉԵԼ ՈՒԼ ԼՈ ԲՐԵ ԲՐԻԼԼ ԴՂԲԼ ԵՂԼՈՂԲԼՈՒՄ. ՎԻՒ ԲՈՒԿ ԼՂԼԵՉ ԽԵՐԵ
ԳԴԵԴՈՂԲԵՒԼ ՉԵՐՈՒԵՂ ՉՈՒԿ ԲՐՂԼ ԳՈՂ ԷՈՂԼ ԽՂՉ ԼՉՈՂԲԼՈՒ ԲՈ ԼԵՂԲԼՈՒ. ԼՐԵԼԵՐԵ, ԲՐԵ ԸՈՒԲՂԽԵՒԼ
ԼՈՒԵՂԼԻԼ ՕԼ ԲՐԵ ԲՈՒԿ ԽՂՉ ՈՒԼ ԸՈՒԴՈՒՄԼԵՂ ԳՈՂ ԲՐԵ ԲԵՉԼ ԼՉ ԸՈՒՉԼԴԵՐԵՂ ԸՈՒԼՈՂԼԵ.

ԼՂՈՒԿ # ԼԵ: ՎԼԵՐ ԼՉՐ ՐՈՒՐԻՉ ՕԼ ԲԵՉԲԼՈՒՄ ԲՐԵ ԲՈՒԿ ԼՉ ԸԵՐԼԼԼԵՂ ԲՈ ՐԵ ԲԼԻՂԲ.


IsuK D9fg IsuK # J9

D!gwefe!:
 IsuK L!b6:
 2b6c!t!c C!g!f!g:

J00 t.
 A6!f!c9! N2L
 0.8t
 02\04\50J2
 L!g!z B!cK6f20u

H6!g!f:
 Couf6uf2:
 b!o9ncf G6!el:

520 t.
 E!9
 28.29 t.
 02\09\50J2
 C6!f!t!69 L!g!f



All dimensions, line locations, sizes and
 valve descriptions have been furnished
 by the facility operator.

[illegible]

Tank Test Results Summary Mass Technology Corporation

Mass (ft H₂O)

Tank	Test Results
Red Hill 16	The linear regression performed on data for the 5-day test sequence indicates a volumetric change rate below the MDLR of 0.5 GPH and is interpreted as "NO LEAK".

Linear Regression
Compensated Data



Precision Leak Measurement Report
P.O. Box 1578
Kilgore, Texas 75662


ԷԻՇԸ ԲԵՊ ԻՈՒՂ
ԲԵՅՈՒ ԻՅԱՐՈՒ, ԻՂ

ԲԻՈՂԵԿՏ ԿՈՄՊԼԵԿՏ – ԿԻԼԳՈՐ ԸՆԴՈՒՄ

ՉԻՔԵ ՉՈՒԴԵՐՈՒՄ – ԼԻՂՈՒՄ ԲԻՇԿԵԲՈՒՄ

ՉԵՐԵ ՕՒ ԿՈՒՔ: ԷՆԻՄԻՔ ԳԻՂ ԼԵԴՈՒԼԵՊ ԿՈՄՊԼԵԿՏԵՆԻ, ԼՅՐՈՒ, ՉԵՐԼԵՇ, ԿՅՐԵՐԼՅԻՆ ԳՈՐԾՈՒԹՅՈՒՆ
ԲՈ ԴԵՐՈՒՄ ԲԻՔԵ ԼԵԴՈՒԼԵՊ ԳՈՍՈՒՂ ԲԼԵՊԲՈՒՆՆ ԲԵՇԲԼՅՈՒՄ ՕՒ ԼՅՈՒԿ # 50 ԳՈ
ՈՍԳԵՐԵՐՈՒՄ ԷՈՒ ՉԲՈՒՆՆ ԲՅՈՒ ԼՈՇԲԵՊ ԳԻ ԷԻՇԸ ԲԵՊ ԻՈՒՂ, ԲԵՅՈՒ ԻՅԱՐՈՒ, ԻՂ.

ԲԵՐՈՒԿ ԿՈՄՊԼԵԿՏ ԲՂ:


ԲԻՇԿՂ ՉԻՅՈՒՄԲԵՐ

ԴՅԲԵ: ԵՇ-ԵՈ-50ԵԴ

ՉՈՒՄԱՐԼ

ԼԵՇԲԼՅՈՒՄ ՕՒ ԼՅՈՒԿ # 50 Գ ԵՇ,ԵՈՐ,ԵՈՐ ԶՂԻ ՈՍԳԵՐԵՐՈՒՄ ՉԲՈՒՆՆ ԲՅՈՒ ԼՈՇԲԵՊ ԳԻ ԷԻՇԸ ԲԵՊ ԻՈՒՂ, ԲԵՅՈՒ ԻՅԱՐՈՒ, ԻՅՄՅՂԻ ԿՈՒՄԵՆԵՊ ՕԿԲՈՒԵ 5Զ, 50ԵԴ ԳՈՐԾ ԿՅՐ ԿՈՒԴԼԵԲՈՐ ՈՒԼԵՄՐԵՐ 2, 50ԵԴ. ԼԲԵ ԲՅՈՒԿ ԿՈՒԴՅՈՒՄԵՊ ԵԲ-2 ԳՈՐԾ Գ ԴԵԿԻԶԻՈՒ ԼԵՐԿ ԲԵՇԲ ԿՅՐ ԿՈՒԴՈՒԿԵՊ. ԼԲԵ ԼԵՇՈՒԿ ՕՒ ԲԲԳԻ ԲԵՇԲԼՅՈՒՄ ԻՆ ԲԲԳԻ ԲԲԵ ԲՅՈՒԿ ՉԼՂԲԵՄ ԻՆ ԳԵԲԵՐՈՒՄԵՊ ԲՈ ԲԵ ԲԼԵՊԻ ԲՈ ԻՅՈՒԴԲՈՒՄ. ՎԻՂ ԲՅՈՒԿ ՎՅԻԼԵՇ ԿԵՐԵ ԳԳԵԴՈՒԴԲԵՐԼ ՉԵՐՈՒԵՊ ՉՈՒԿ ԲԲԳԻ ՈՒ ՈՍՈՒՆՈՒՂ ԼԵՐԳԻՄՆՆ ԿԵՐԵ ՈՒԴԵՊ. ԼԵՇԲԼՅՈՒՄ ԿՅՐ ԴԵՐՈՒՄԵՊ ՈՂԻՄՆ ԲԲԵ ԿՅՐ ԼԵԿԲՈՒՈԼՂ ԿՈՒԴՈՒԴԲՈՒՄ ԴԻՐՈԲՈԿՈԼՆ ՉԵԲ ՕՈՒԿ ԻՈ ԲԲԵ ԲԲԻԿ ԴՅԻԼՂ ԵՐՅԻՈՒԴԲՈՒՄ. ՎԻՂ ԲՅՈՒԿ ՎՅԻԼԵՇ ԿԵՐԵ ԳԳԵԴՈՒԴԲԵՐԼ ՉԵՐՈՒԵՊ ՉՈՒԿ ԲԲԳԻ ԳՈՂ ԷՈՒԿ ԼՈՂՆ ԿՅՐ ԻՅՈՒԴԲՈՒՄ ԲՈ ԼԵՐԿՅԵ. ԼԲԵՐԵՐՈՒԵ, ԲԲԵ ԿՈՒԴՅՈՒՄԵՆԻ ԼՈՒԵՐԵՐԼՂ ՕՒ ԲԲԵ ԲՅՈՒԿ ԿՅՐ ՈՒԴ ԿՈՒԴՈՒՄԼԵՊ ԳՈՐԾ ԲԲԵ ԲԵՇԲ ԻՆ ԿՈՒՆԻԳԵՐԵՊ ԿՈՒԿՈՂՆԻԼԵ.

ԼՅՈՒԿ # 50: ՎԷԲԵՐ ԵՐՑ ԴՈՒՆՆ ՕՒ ԲԵՇԲԼՅՈՒՄ ԲԲԵ ԲՅՈՒԿ ԻՆ ԿԵՐԲԻՒԼԵՊ ԲՈ ԲԵ ԲԼԵՊԻ.

IsuK D9fg IsuK # 50

D!gwefe!:
IsuK L!b6:
2b6c!t!c C!g!f!g!:


J00 t!.
^6e!f!c9! N2L
0.85

J0\50\50J4
L!g!z B!c!6f20u

H6!g!f:
Coufeuf2:
b!o9ncf G6!6!:

520 t!.
1b-2
5JJ.42 t!.

JJ\02\50J4
C6!f!t!69 L!g!f




All dimensions, line locations, sizes and valve descriptions have been furnished by the facility operator.

Եզնութ

Այս ելույթը ցույց է տալիս, որ չկա խնայողականության փոփոխություն: Այսպիսով, չկա խնայողականության փոփոխություն, որը կարող է լինել 0.2 ցլլոնի փոփոխություն: Այս փոփոխությունը ցույց է տալիս, որ չկա խնայողականության փոփոխություն: Այսպիսով, չկա խնայողականության փոփոխություն: Այսպիսով, չկա խնայողականության փոփոխություն:

Այս # 50-ը ցույց է տալիս, որ չկա խնայողականություն:



UFM REPORT

12/25/2015

Background:	EXAMPLE: At (time), on (Day of the week), December 25, 2015, Red Hill tank Q110 had a UFM			
Action:	At (time) placed the tank into an evolution to remove the alarm At (time) the Red Hill Rover checked lower and upper tunnels (all Conditions were normal or the following problems were found) At (time) the Red Hill rover top gauged tank Q110 The comparison from the last top gauge is 01/16"			
Cause:	I believe the AFHE computer for tank Q110 may need calibration or to be reset. Tank Q110 dropped down to 207'-09-15/16". The tank is still in an evolution for AFHE fuel level movement and for monitoring. Also, the BS&W has risen from 0'-00-00" to 05'-07-05/16". The BS&W level alarm has been activated on AFHE for tank Q110.			
Top Gauge of Tank Q110:				
	Date:	Time:	Top Gauge	Rover Name
Previous:	20-Dec-15	4:00 PM	211'-08-06/16"	D. Cardona
Current:	25-Dec-15	5:20 AM	211'-08-06/16"	J. Espenida
Originator and Review:				
			Name	
Created by:	Concur/Do Not Concur	Alex Bayudan		
Bulk Supervisor:	Concur/Do Not Concur	Sam Perfecto		
Fuel Operation Supervisor:	Concur/Do Not Concur	Tom Williams		
Deputy Director:	Concur/Do Not Concur	John Floyd		
Director:	Concur/Do Not Concur	LCDR Lovgren		

Encl (1)

WEEKLY UFM SUMMARY REPORT

2/11/2016

Background:	Example: For the week of 04 - 11 February, there were no UFM to Report.			
Action:	No action required			
Cause:	N/A			
Top Gauge of Tank 0110:				
	Date:	Time:	Top Gauge	Rover Name
Previous:				
Current:				
Originator and Review:				
	Name			
Created by:	N/A		Edgar Pascua	
Bulk Supervisor:	Concur/Do Not Concur		Sam Perfecto	
Fuel Operation Supervisor:	Concur/Do Not Concur		Tom Williams	
Deputy Director:	Concur/Do Not Concur		John Floyd	
Director:	Concur/Do Not Concur		LCDR Lovgren	

ENCL (2)

MEMORANDUM FOR THE RECORD

31 December 2015

From: Williams, Thomas M., NAVSUP Pearl Harbor, Code 703, Fuel Operations Supervisor

Subj: MEMORANDUM FOR THE RECORD (MFR) ISO UFM REPORTS FROM 25 DECEMBER TO 31 DECEMBER 2015






The purpose of this MFR is to record that no UFM's were reported for the period starting 25 December 2015 and ending 31 December 2015 from the UGPH Operators and there were no UFM's logged on the AFHE system.

A handwritten signature in black ink, consisting of a stylized 'T' followed by a circle and a horizontal line extending to the right.

T. M. Williams

UFM REPORT

1/20/2016

Background:	ISSUE 2190 FROM TK#1811I TO FLCPH T/T			
Action:	MID SHIFT OPERATOR SET UP EVOLUTION FOR ISSUE			
Cause:	SET UP WRONG METER NUMBER, OPERATOR ERROR			
Top Gauge of Tank 0110:				
	Date:	Time:	Top Gauge	Rover Name
Previous:				
Current:				
Originator and Review:				
		Name		
Created by:	<input checked="" type="radio"/> Concur / <input type="radio"/> Do Not Concur	ALTON DAITE 		
Bulk Supervisor:	<input checked="" type="radio"/> Concur / <input type="radio"/> Do Not Concur	Sam Perfecto 		
Fuel Operation Supervisor:	<input checked="" type="radio"/> Concur / <input type="radio"/> Do Not Concur	Tom Williams 		
Deputy Director:	<input checked="" type="radio"/> Concur / <input type="radio"/> Do Not Concur	John Floyd 		
Director:	<input checked="" type="radio"/> Concur / <input type="radio"/> Do Not Concur	LCDR Covgren 		






UFM REPORT

02 Feb 16

Background:	Red Hill tank 0104 activated UFM alarm during manual input.			
Action:	Tank topped off pass ops limit for Mass Tech high level testing. In process of manual gauging to complete transfer record after transfer.			
Cause:	Operator's error; cannot calculate tank level pass ops limit on manual input from AFHE. Tom Williams Comment: No fuel moved. This was caused by the operator putting a manual level entry into the AFHE system after the tank was filled to above the High operating limit. The manual change reverted to the actual level and that made it seem like there was fuel movement.			
:				
	Date:	Time:	Top Gauge	Rover Name
Previous:				
Current:				
Originator and Review:				
			NAME	
Created by: E. Pascua	Concur /Do Not Concur	Edgar Pascua		
Bulk Supervisor:	Concur/ Do Not Concur	Sara Perfecta		
Fuel Operation Supervisor:	<u>Concur</u> /Do Not Concur	Tom Williams		
Deputy Director:	<u>Concur</u> /Do Not Concur	John Floyd		
Director:	<u>Concur</u> /Do Not Concur	LCDR Lovgren		

UFM REPORT







3/22/2016

Background:	At 2338, on March 22, 2016, Surge Tank 1 had a UFM			
Action:	At 2339 placed the tank into an evolution to remove the alarm			
	Gauge and inspection not needed as this was caused by operator error			
Cause:	During alignment of system for HIE (F-24) delivery, HIE was not able to provide fuel when their pumps were turned on. In the process of trouble shooting, DFSP Pearl Harbor alignment was shifted to verify flow path was open. Operator did not set up the evolution to include surge 1, so when fuel flowed into surge 1, it caused an UFM alarm. Since this was operator error, the UFM protocols were not required.			
Top Gauge of Tank 0110:				
	Date:	Time:	Top Gauge	Rover Name
Previous:	N/A			
Current:	N/A			
Originator and Review:				
		Name		
Created by:		 Ron Hendricks		
Bulk Supervisor:	<input checked="" type="radio"/> Concur/ <input type="radio"/> Do Not Concur	 Sam Perfecto		
Fuel Operation Supervisor:	<input checked="" type="radio"/> Concur/ <input type="radio"/> Do Not Concur	 Tom Williams		
Deputy Director:	<input checked="" type="radio"/> Concur/ <input type="radio"/> Do Not Concur	 John Floyd		
Director:	<input checked="" type="radio"/> Concur/ <input type="radio"/> Do Not Concur	 LCDR Lovgren		

End (1)

UFM REPORT

4/2/2016

Background:	At 1644, on April 2, 2016, Red Hill tank 0112 had a UFM			
Action:	At 1644 placed the tank into an evolution to remove the alarm At 1700 the Red Hill Rover checked lower and upper tunnels all Conditions were normal At 1720 the Red Hill rover top gauged tank 0112 The comparison from the last top gauge is 01/16"			
Cause:	I believe communications for AFHE computer for tank 0112 have failed as evidenced by no movement of fuel in tank 0112 as verified by Top Gauge. Englobal called and emailed. Supervisor called. COC emailed.			
Top Gauge of Tank 0110:				
	Date:	Time:	Top Gauge	Rover Name
Previous:	15-Mar-16	2:22 PM	211'-07-00/16"	K. Lindo
Current:	2-Apr-16	4:35 PM	210'-07-01/16"	J. Espenida
Originator and Review:				
			Name	
Created by:			 Ron Hendricks	
Bulk Supervisor:	<input checked="" type="radio"/> Concur/Do Not Concur		 Sam Perfecto	
Fuel Operation Supervisor:	<input checked="" type="radio"/> Concur/Do Not Concur		 Tom Williams	
Deputy Director:	<input checked="" type="radio"/> Concur/Do Not Concur		 John Floyd	
Director:	<input checked="" type="radio"/> Concur/Do Not Concur		 LCDR Lovgren	

Encl (1)

ATTACHMENT D

Recent Cathodic Protection System Rectifier Readings

Site Name	Report Date	Report Time	Channel 1 Volts	Channel 2 Amps	Maximum % Change in Volts	Maximum % Change in Amps
Rect #09 @ UTF Tank #48 & Piping	3/6/2016	19:00	7.85	12.822	32%	497%
	3/21/2016	19:00	10.7	0.018		
	4/5/2016	19:00	11.11	0.018		
	4/13/2016	4:39	11.04	0.012		
	4/20/2016	19:00	11.2	0.018		
Rect #10 @ UTF Tank #55 & Piping	3/6/2016	19:00	11.62	16.842	1%	2%
	3/21/2016	19:00	11.64	17.13		
	4/5/2016	19:00	11.68	17.148		
	4/13/2016	4:39	11.68	17.142		
	4/20/2016	19:00	11.65	17.052		
Rect #11 @ UTF Tank #54 & Piping	3/5/2016	21:00	1.19	-0.012	6%	200%
	3/20/2016	21:00	1.15	-0.006		
	4/4/2016	21:00	1.12	0.012		
	4/13/2016	4:39	1.14	0.018		
	4/13/2016	2:37	1.13	0.006		
	4/27/2016	7:00	1.13	0		
Rect #12 @ UTF Tank #53 & Piping	3/5/2016	19:00	0.87	0.018	37%	133%
	3/20/2016	19:00	0.85	0.03		
	4/4/2016	19:00	0.86	0.012		
	4/13/2016	4:39	0.82	0.024		
	4/19/2016	19:00	1.16	0.006		
Rect #13 @ UTF Tank #46 & Piping	3/5/2016	21:00	12.82	7.11	2%	13%
	3/20/2016	21:00	12.69	7.56		
	4/4/2016	21:00	12.65	7.914		
	4/13/2016	4:39	12.68	8.106		
	4/19/2016	21:00	12.58	8.124		
Rect #14 @ UTF Tank #47 & Piping	3/6/2016	19:00	5.98	27.168	1%	6%
	3/21/2016	19:00	5.95	27.888		
	4/5/2016	19:00	5.99	28.068		
	4/13/2016	4:39	6	28.134		
	4/20/2016	19:01	5.96	26.364		
Rect #16 @ Fitness Center	3/6/2016	19:00	2.33	0.048	1%	81%
	3/21/2016	19:00	2.35	0.024		
	4/5/2016	19:00	2.33	0.054		
	4/13/2016	4:39	2.32	0.03		
	4/20/2016	19:00	2.32	0.03		

Site Name	Report Date	Report Time	Channel 1 Volts	Channel 2 Amps	Maximum % Change in Volts	Maximum % Change in Amps
Rect #20 @ Hotel Pier	3/5/2016	19:00	17.14	0	147%	550%
	3/20/2016	19:00	16.94	0.012		
	4/4/2016	19:00	16.92	0.012		
	4/8/2016	19:01	0.68	0.516		
	4/8/2016	15:11	0.68	0.012		
	4/8/2016	14:57	15.55	0.444		
	4/8/2016	13:43	0.68	0		
	4/13/2016	4:39	17.18	0.006		
	4/15/2016	10:21	15.58	-0.276		
	4/15/2016	7:57	0.66	0.012		
	4/18/2016	3:09	17.43	0.006		
	4/29/2016	19:00	17.08	0.012		
Rect #23 @ VC-15 (North Avenue)	3/6/2016	5:00	3.48	7.944	1%	7%
	3/21/2016	5:00	3.49	7.704		
	3/21/2016	3:11	3.47	7.536		
	4/5/2016	5:00	3.46	7.542		
	4/13/2016	4:39	3.46	7.668		
	4/18/2016	3:09	3.48	7.662		
	4/20/2016	5:00	3.45	7.44		
Rect #24 @ Multi Product Tank 301	3/9/2016	2:59	2.46	1.308	1%	2%
	3/24/2016	2:59	2.47	1.304		
	4/8/2016	3:00	2.45	1.296		
	4/13/2016	4:39	2.45	1.318		
	4/23/2016	2:59	2.46	1.32		
Rect #27 @ VS-1A	2/29/2016	19:00	0.83	0.006	16%	86%
	3/15/2016	19:00	0.83	0.006		
	3/30/2016	19:00	0.74	0.006		
	4/13/2016	4:39	0.75	0.012		
	4/14/2016	19:00	0.74	0.006		
	4/29/2016	19:00	0.71	0.006		
Rect #46 @ UTF Tank 46	3/6/2016	3:19	6.61	15.636	0.5%	0.3%
	3/21/2016	3:19	6.62	15.654		
	4/5/2016	3:19	6.62	15.654		
	4/13/2016	4:39	6.64	15.684		
	4/20/2016	3:19	6.63	15.654		
Rect #47 @ UTF Tank 47	3/6/2016	3:30	6.01	23.31	0.3%	1.1%
	3/21/2016	3:30	6.02	23.154		
	4/5/2016	3:29	6.01	23.298		

Site Name	Report Date	Report Time	Channel 1 Volts	Channel 2 Amps	Maximum % Change in Volts	Maximum % Change in Amps
	4/13/2016	4:39	6.03	23.418		
	4/20/2016	3:30	6.03	23.382		
Rect #48 @ UTF Tank 48	3/5/2016	21:48	15.43	3.928	0.5%	1.8%
	3/20/2016	21:49	15.5	3.88		
	4/4/2016	21:49	15.5	3.92		
	4/13/2016	4:39	15.48	3.952		
	4/19/2016	21:48	15.43	3.952		
Rect #53 @ UTF Tank 53	3/5/2016	23:06	5.8	25.914	1%	1%
	3/20/2016	23:06	5.84	26.136		
	4/4/2016	23:06	5.81	25.896		
	4/13/2016	4:39	5.81	25.974		
	4/19/2016	23:06	5.83	26.04		
Rect #54 @ UTF Tank 54	3/6/2016	0:59	6.18	20.94	1%	2%
	3/21/2016	3:11	6.2	21.144		
	4/5/2016	0:59	6.21	21.204		
	4/13/2016	4:39	6.22	21.234		
	4/20/2016	0:59	6.21	21.276		