



Red Hill – Monitoring Well Fuel Product Gauging Photos

AECOM

01/12/2026 – 01/16/2026



[P1050957.JPG] – RHMW17 – 01/12/2026 – 1132  
No fuel product observed. Water observed is clear in the bailer sample.




[P1030299.JPG] – NMW24 – 01/12/2026 – 0946  
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging Photos

AECOM

01/12/2026 – 01/16/2026



[P1030298.JPG] – NMW25 – 01/12/2026 – 0819  
No fuel product observed. Water observed is clear in the bailer sample.




[P1050960.JPG] – RHMW04 – 01/13/2026 – 0838  
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging Photos

AECOM

01/12/2026 – 01/16/2026



[P1030302.JPG] – RHMW20 – 01/13/2026 – 1105  
No fuel product observed. Water observed is clear in the bailer sample.




[P1050962.JPG] – NMW26 – 01/14/2026 – 0844  
No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging Photos


AECOM

01/12/2026 – 01/16/2026



[P1030303.JPG] – NMW33 – 01/14/2026 – 0858

No fuel product observed. Water observed is clear in the bailer sample.




[P1030305.JPG] – NMW34 – 01/14/2026 – 1106

No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging Photos

AECOM

01/12/2026 – 01/16/2026



[P1030306.JPG] – NMW32 – 01/15/2026 – 0841  
No fuel product observed. Water observed is clear in the bailer sample.



[P1030307.JPG] – NMW30 – 01/16/2026 – 0833  
No fuel product observed. Water observed is clear in the bailer sample.