


Red Hill – Monitoring Well Fuel Production Gaugin Photos


AECOM

06/22/2026 – 06/26/2026



[P1060358.JPG] RHMW17 – 06/22/2026 – 1046

No fuel product observed. Water observed is clear in the bailer sample. Floating green debris at surface dislodged from bailer check ball seat.




[P1030639.JPG] NMW24 – 06/22/2026 – 0747

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Production Gaugin Photos


AECOM

06/22/2026 – 06/26/2026



[P1030640.JPG] NMW25 – 06/22/2026 – 0859

No fuel product observed. Water observed is clear in the bailer sample.




[P1240268.JPG] RHMW20 – 06/23/2026 – 1039

No fuel product observed. Water observed is clear in the bailer sample. Orange color on the bailer due to reflective PPE clothing.

Red Hill – Monitoring Well Fuel Production Gaugin Photos


AECOM

06/22/2026 – 06/26/2026



[P1060359.JPG] RHMW04 – 06/23/2026 – 0830

No fuel product observed. Water observed is clear in the bailer sample.




[P1030643.JPG] NMW26 – 06/24/2026 – 1012

No fuel product observed. Water observed is clear in the bailer sample. Small debris noted at surface.

Red Hill – Monitoring Well Fuel Production Gaugin Photos


AECOM

06/22/2026 – 06/26/2026



[P1060362.JPG] NMW33 – 06/24/2026 – 0804

No fuel product observed. Water observed is clear in the bailer sample.




[P1060363.JPG] NMW34 – 06/24/2026 – 0956

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Production Gaugin Photos


AECOM

06/22/2026 – 06/26/2026



[P1030645.JPG] NMW32 – 06/25/2026 – 0751

No fuel product observed. Water observed is clear in the bailer sample. Orange/yellow color near the water surface due to reflective PPE clothing.



[P1060364.JPG] NMW30 – 06/26/2026 – 0752

No fuel product observed. Water observed is clear in the bailer sample.