


Plates 3-6 inspected by Gammon and W. Choy (PWC) on 21 July 1995 from 0950 to 1220. Plates sand blasted to remove coating, but not all flame-sprayed aluminum.


P - Patch
N - Nozzle
L - tower Leg
E - pad Eye
T - tee
X - pit location and depth



CONAM MMP INSPECTION INC
PROJECT: RED HILL TANK # 13
ITEM: FLOOR LAYOUT
BY: L. Woodman DATE: 7/3/95
CLIENT: AMAN ENVIRONMENTAL
REMARKS: _____

Plates 1 and 2 inspected by J. Gammon (FSC) and R. Koyama (PWC) on 20 July 1995 from 1005 to 1115. Plates sandblasted as noted above.

No 5063



Plates 3-6 inspected by Gammon and W. Choy (PWC) on 21 July 1995 from 0950 to 1220

P - patch
 N - Nozzle
 L - tower Leg
 E - pad Eye
 T - tee
 X - pit location and depth


N = plate thickness next to pit
 B = plate thickness at bottom of pit

Plates 1-6 inspected by B. Dmitrijev and J. Gammon (KISC), R. Koyama (PWC); and HT1 J. Shell and HT1 R. Hall (SUBASE IMF NDT Shop) on 28 July 1995 from 1610 to 1800. Shell and Hall are certified Level 2 inspectors. Plates 1, 2, and part of plates 2 and 3 outside of tower were blasted to white metal.

CONAM MMP INSPECTION INC
 PROJECT: RED HILL TANK # 13
 ITEM: FLOOR LAYOUT
 BY: L. Woodman DATE: 7/3/95
 CLIENT: AMAN ENVIRONMENTAL
 REMARKS: _____

Plates 1 and 2 inspected by J. Gammon (KISC) and R. Koyama (PWC) on 20 July 1995 from 1005 to 1115. No 5063

07-13-1995 07:31AM FROM MMP QUALITY INSPECTIONS TO 918088331512215 P.10




[Handwritten signature]

REMARKS: _____

No 5063

489
333

156



P - patch
 N - Nozzle
 L - tower Leg
 E - pad Eye
 T - tee
 X - pit location and depth

07-13-1995 07:31AM FROM MMP QUALITY INSPECTIONS TO 918088331512215 P.10

CONAM MMP INSPECTION INC

PROJECT: RED HILL TANK # 13


ITEM: FLOOR LAYOUT

BY: L. Woodman DATE: 7/3/95

CLIENT: AMAN ENVIRONMENTAL

REMARKS: _____

I.P. Form No. 09011 Rev. 2/92
 Plates 1 and 2 inspected by J. Gammon (FSL) and R. Koyama (PWC) on 20 July, 1995 from 1005 to 1115. Plates sandblasted as noted above.



Plates 3-6 inspected by Gammon and W. Choy (PWC) on 21 July 1995 from 0950 to 1220. Plates sand blasted to remove coating, but not all flame-sprayed aluminum.

- P - patch
- N - Nozzle
- L - tower leg
- E - pad Eye
- T - tee
- X - pit location and depth

Pits found by our follow up inspection

CONAM MMP INSPECTION INC

PROJECT: RED HILL TANK # 13

ITEM: FLOOR LAYOUT

BY: L. Woodman DATE: 7/3/95

CLIENT: AMAN ENVIRONMENTAL

REMARKS: _____

M.P. Form No. DPO11 Rev. 2/92


Plates 1 and 2 inspected by J. Gammon (FSC) and R. Koyama (PWC) on 20 July 1995 from 1005 to 1115

No 5063

07-13-1995 07:31AM FROM MMP QUALITY INSPECTIONS IU 918088331512215 P.10

Plates 3-6 inspected by Gammon and W. Choy (PWC) on 21 July 1995 from 0950 to 1220. Plates sand blasted to remove coating, but not all flame-sprayed aluminum.

P - patch
N - Nozzle
L - tower Leg
E - pad Eye
T - tee
X - pit location and depth



CONAM MMP INSPECTION INC

PROJECT: RED HILL TANK # 13

ITEM: FLOOR LAYOUT

BY: L. Woodman DATE: 7/3/95

CLIENT: AMAN ENVIRONMENTAL

REMARKS: _____

Plates 1 and 2 inspected by J. Gammon (PWC) and R. Koyama (PWC) on 20 July 1995 from 1005 to 1115. Plates sand blasted as noted above.

No 5063