Office of Health Care Assurance

State Licensing Section

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

Facility's Name: Raquel Care Home	CHAPTER 100.1
Address: 1656 Hoolulu Road, Wahiawa, Hawaii 96786	Inspection Date: January 19, 2018

THIS PAGE MUST BE SUBMITTED WITH YOUR PLAN OF CORRECTION. IF IT IS NOT, YOUR PLAN OF CORRECTION WILL BE RETURNED TO YOU, UNREVIEWED.

RULES (CRITERIA)	PLAN OF CORRECTION	Completion Date
§11-100.1-23 Physical environment. (g)(3)(A) Fire prevention protection. Type I ARCHs shall be in compliance with, but not limited to, the following provisions: Fire escapes, stairways and other exit equipment shall be maintained operational and in good repair and free of obstruction; FINDINGS Slide bolt locking device on the second exit wood door.	DID YOU CORRECT THE DEFICIENCY? USE THIS SPACE TO TELL US HOW YOU CORRECTED THE DEFICIENCY To Prevent Intruders from Coming into my home. Sliding Boit Locking Device was removed on the second exit wood door to be free of obstruction.	01-26-2018

RULES (CRITERIA)	PLAN OF CORRECTION	Completion Date
§11-100.1-23 Physical environment. (g)(3)(A) Fire prevention protection. Type I ARCHs shall be in compliance with, but not limited to, the following provisions: Fire escapes, stairways and other exit equipment shall be maintained operational and in good repair and free of obstruction;	PLAN OF CORRECTION PART 2 FUTURE PLAN USE THIS SPACE TO EXPLAIN YOUR FUTURE PLAN: WHAT WILL YOU DO TO ENSURE THAT IT DOESN'T HAPPEN AGAIN? In the future I'll make sure not to use Slide Bolt Locking or any other device on the Second exist wood door,	1 - 1

Print Name: LORETO RAQUEL

Date: 01-26-2018