TANK NUMBER: NSCPH-A-H6-1

ACTIVITY: NSC - PEARL HARBOR

STATUS: ABANDONED

LOCATION: HOTEL PIER STRUCTURE 1308

BORING PROGRAM

One soil boring was drilled approximately 7 feet from the end and 2 feet from the outer edge of the tank. The boring was drilled to approximately 5 feet below ground surface. Ground water was found at a depth of about 5 feet.

SOIL SAMPLING PROGRAM

Soil samples were collected at 3 and 4.5 feet below ground surface.

SITE LITHOLOGY

The site is underlain by gravel and coral backfill to 5 feet below ground surface.

LABORATORY PROGRAM

Soil samples collected from depths of 3 and 4.5 feet were analyzed for total petroleum hydrocarbons (TPH) using a modified Environmental Protection Agency (EPA) Method 8015, volatile organic compounds using EPA Method 8240, and polychlorinated biphenyls (PCBs) and pesticides using EPA Method 8080.

CHEMICAL RESULTS

Soil samples collected from depths of 3 and 4.5 feet had TPH concentrations of 62.2 and 13,700 milligrams per kilogram (or parts per million), respectively. The soil sample collected at a depth 3 feet also had a toluene concentration of 680 micrograms per kilogram (or parts per billion). All other analyzed chemical parameters using EPA Methods 8015, 8240, and 8080 were below detection limits.

TANK NO.	NSCPH-A-H6-1	
 ACTIVITY	NSC - Pearl Harbor	
 STATUS	Abandoned	
 NEAREST BLDG.	- Structure 1308	

TANK INFORMATION:

SITE INFORMATION:

Location	•	Paving Material/Thickness	Gravel	
Installation Date	 1942	 Appearance	- Fair	
Capacity, gal.	5,000	 Surface Contamination	Staining on surface	
Use/Process	Fueling Facility			
	 Empty/JP-5	TESTING PROGRAM: N/A		
	Carbon steel	Date Tested		
Depth To Invert	- 10'	 Leak Rate High		
Diameter	6.17'	 Leak Rate Low	- -	
. •	·	 Special Requirements	· · · · ·	
Spill/Overfill Containment	None			
•••	Impressed Current	BORING PROGRAM:		
	eak Detection Stock Inventory		11-15-89	
	•	 Number of Borings	ļı	
	 Wrapped	 Sample Depth (s)	3, 4.5'	
• •	Underground	Laboratory Analysis	TPH EPA METHOD 8015	
Туре	Pressure		VOC EPA METHOD 8240 PCB EPA METHOD 8080	
Contruction Material	 Steel		PESTICIDES EPA METHOD 8080	
		M/A - Not Applicable		

N/A - Not Applicable



O 10 FEET SCALE



EXPLANATION:

TANK LOCATION

BORING LOCATION

GROUND-WATER MONITORING WELL

ESE

NSC PEARL HARBOR

TANK NSCPH-A-H6-1 SITE MAP

DATE	PROJECT No.	FIG #	
05/04/90	6-90-4122		
05/04/90 SHEET No.	DWG No.	SIZE	
1 of 1	13800156	8.5 X 11	
DRAWN BY:	APPROVED BY:	REV	
P. LEETS			

TANK NUMBER: NSCPH-A-H6-2

ACTIVITY: NSC - PEARL HARBOR

STATUS: ABANDONED

LOCATION: HOTEL PIER STRUCTURE 1308

BORING PROGRAM

One soil boring was drilled approximately 7 feet from the end and 2 feet from the outer edge of the tank. Ground water was found at about 7 feet below ground surface in the boring. The soil boring was advanced to 10 feet below the first occurrence of ground water (17 feet below ground surface) and a 2-inch-ID ground-water well was installed.

SOIL SAMPLING PROGRAM

Soil samples were collected at depths corresponding to the midpoint, 2 feet below the invert (bottom) of the tank (approximately 7 and 12 feet), and at a depth of 17 feet below ground surface.

SITE LITHOLOGY

The site is underlain to a depth of about 10 feet by fill material that appears to be coral. Beneath the fill material is coral with clay and gravel to a depth of about 15 feet. Slightly silty fine-grained sand with coral is present to a depth of 17 feet.

LABORATORY PROGRAM

One soil sample collected at a depth of 7 feet was analyzed for total petroleum hydrocarbons (TPH) using a modified Environmental Protection Agency (EPA) Method 8015, volatile organic compounds using EPA Method 8240, and polychlorinated biphenyls (PCBs) and pesticides using EPA Method 8080.

One Ground-water sample was analyzed for TPH, volatile organic compounds, and PCBs and pesticides using EPA Methods 8015, 624, and 8080, respectively.

CHEMICAL RESULTS

A soil sample collected at a depth of 7 feet had a TPH concentration of 49,000 milligrams per kilogram (or parts per million) and a total xylene concentration of 2,700 micrograms per kilogram (or parts per billion). All other analyzed chemical parameters using EPA Methods 8015, 8240, and 8080 were below detection limits.

The ground-water sample had a TPH concentration of 9.42 milligrams per liter (or parts per million). All other chemical parameters analyzed for in this ground-water sample using EPA Methods 8015, 624, and 8080 were below detection limits.

TANK NO.	NSCPH-A-H6-2
ACTIVITY	NSC - Pearl Harbor
 STATUS	Abandoned
 NEAREST BLDG.	Structure 1308
1	

TANK INFORMATION:

SITE INFORMATION:

ocation	Hotel Pier Structure #1308	Paving Material/Thickness	Gravel		
Installation Date	1943	Appearance	Fair		
Capacity, gal.	5,000	 Surface Contamination	Staining on surface		
Jse/Process	Fueling Facility				
Contents - Amount/Type	Empty/JP-5	TESTING PROGRAM: N/A			
Construction Materials	Carbon steel	Date Tested			
Depth To Invert	10'	 Leak Rate High			
Diameter	6.17'	 Leak Rate Low			
.ength	22'	 Special Requirements			
Spill/Overfill Containment	None				
Corrosion Protection	i Impressed Current 	 	NC BOACBAM.		
Leak Detection	Stock Inventory	BORING PROGRAM:			
		Date Drilled	11-27-89 		
Internal Protection	•	 Number of Borings	i 1		
External Protection	•	 Sample Depth (s)	2, 7, 12'		
Tenk Piping	Underground	 Laboratory Analysis	TPH EPA METHOD 8015		
Туре	 Pressure		VOC EPA METHOD 8240 PCB EPA METHOD 8080 PESTICIDES EPA METHOD 8080		
Contruction Material	 Steel	!!	PESTICIOES EPA METMOD 0000		

N/A - Not Applicable



10 FEET SCALE



EXPLANATION:

TANK LOCATION



BORING LOCATION



GROUND-WATER MONITORING WELL



NSC PEARL HARBOR

TANK NSCPH-A-H6-2 SITE MAP

DATE COLL COL	PROJECT No.	FIG #	
DATE 05/04/90 SHEET No.	6-90-4122 DWG No.	SIZE	
1 of 1	13800156	8.5	X 11
DRAWN BY: P. LEETS	APPROVED BY:		REV

TANK NUMBER: MSCPH-A-MLR-1

ACTIVITY: NSC - PEARL HARBOR

STATUS: ABANDONED

LOCATION: HALAWA SERVICE STATION STRUCTURE S-921

BORING PROGRAM

Two soil borings were drilled adjacent to the east side of the tank. The borings were located approximately one-third of the distance in from each tank end and approximately 2 feet from the outer edge of the tank. Ground water was found at about 6 feet below ground surface in the borings. The borings were advanced to approximately 17 feet below ground surface and one 2-inch-ID ground-water monitoring well was installed in Boring B-2.

SOIL SAMPLING PROGRAM

Soil samples were collected at depths corresponding to the midpoint of the tank, 2 feet below the invert (bottom) of the tank (approximately 7 and 12 feet), and at 17 feet below ground surface.

SITE LITHOLOGY

The site is underlain by sand, silty sand, and silty clay to a depth of 17 feet.

LABORATORY PROGRAM

Soil samples collected from depths of 7 and 12 feet in each boring were analyzed for total petroleum hydrocarbons (TPH) using a modified Environmental Protection Agency (EPA) Method 8015, volatile organic compounds using EPA Method 8240, and polychlorinated biphenyls (PCBs) and pesticides using EPA Method 8080.

One ground-water sample was analyzed for TPH, volatile organic compounds, and PCBs and pesticides using EPA Methods 8015, 624, and 8080, respectively.

CHEMICAL RESULTS

Soil samples collected from Boring B-2 at depths of 7 and 12 feet had TPH concentrations of 153 and 67.9 milligrams per kilogram (or parts per million), respectively. Ethylbenzene concentrations of 650 and 1,300 micrograms per kilogram (ug/kg, or parts per billion) were detected in samples collected at depths of 7 and 12 feet, respectively, in Boring B-2. Boring B-2 also had a total xylenes concentration of 2,200 ug/kg in a soil sample collected at a depth of 12 feet. Soil samples collected from a depth of 12 feet in Boring B-1 had DDT, dieldrin, and endrin concentrations of 4.46, 2.17, and 2.81 ug/kg, respectively. All other analyzed chemical parameters using EPA Methods 8015, 8240, and 8080 were below detection limits.

The analyzed ground-water sample contained 730 micrograms per liter (or parts per billion) of methyl ethyl ketone. All other chemical parameters analyzed for in this ground-water sample using EPA Methods 8015, 624, and 8080 were below detection limits.