

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/05/2026 – 01/09/2026



[P1030273.JPG] – RHMW01R Seal (Before Sampling) – 01/05/2026 – 0952



[P1030277.JPG] – RHMW01R Seal (After Sampling) – 01/05/2026 – 1226

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/05/2026 – 01/09/2026



[P1050932.JPG] – RHMW02 Seal (Before Sampling) – 01/05/2026 – 0921



[P1050937.JPG] – RHMW02 Seal (After Sampling) – 01/05/2026 – 1215

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/05/2026 – 01/09/2026



[P1030278.JPG] – RHMW21 Seal (Before Sampling) – 01/05/2026 – 1251



[P1030281.JPG] – RHMW21 Seal (After Sampling) – 01/05/2026 – 1433

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/05/2026 – 01/09/2026



[P1050944.JPG] – RHMW03 Seal (Before Sampling) – 01/07/2026 – 1020



[P1050946.JPG] – RHMW03 Seal (After Sampling) – 01/07/2026 – 1133

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/05/2026 – 01/09/2026



[P1050941.JPG] – RHMW05 Seal (Before Sampling) – 01/07/2026 – 0856



[P1050943.JPG] – RHMW05 Seal (After Sampling) – 01/07/2026 – 1009

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/05/2026 – 01/09/2026



[P1030286.JPG] – RHP07 Seal (Before Sampling) – 01/07/2026 – 0926




[P1030290.JPG] – RHP07 Seal (After Sampling) – 01/07/2026 – 1103

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

01/05/2026 – 01/09/2026



[P1030276.JPG] – RHMW01R – 01/05/2026 – 1007

No fuel product observed. Water observed is clear in the bailer sample.




[P1050935.JPG] – RHMW02 – 01/05/2026 – 1010

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

01/05/2026 – 01/09/2026



[P1030280.JPG] – RHMW21 – 01/05/2026 – 1305

No fuel product observed. Water observed is clear in the bailer sample.




[P1030284.JPG] – RHMW10 – 01/06/2026 – 1103

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

01/05/2026 – 01/09/2026



[P1030282.JPG] – RHMW19 – 01/06/2026 – 0844

No fuel product observed. Water observed is clear in the bailer sample.




[P1050938.JPG] – RHP05 – 01/06/2026 – 0905

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

01/05/2026 – 01/09/2026



[P1050940.JPG] – RHP06 – 01/06/2026 – 1202

No fuel product observed. Water observed is clear in the bailer sample.




[P1240136.JPG] – RHP08 – 01/06/2026 – 1049

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

01/05/2026 – 01/09/2026



[P1050945.JPG] – RHMW03 – 01/07/2026 – 1029

No fuel product observed. Water observed is clear in the bailer sample.




[P1050942.JPG] – RHMW05 – 01/07/2026 – 0903

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

01/05/2026 – 01/09/2026



[P1030289.JPG] – RHP07 – 01/07/2026 – 0940

No fuel product observed. Water observed is clear in the bailer sample.




[P1050950.JPG] – RHMW06 – 01/08/2026 – 1029

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

01/05/2026 – 01/09/2026



[P1240138.JPG] – RHP01 – 01/08/2026 – 0854

No fuel product observed. Water observed is clear in the bailer sample.




[P1030291.JPG] – RHP02 – 01/08/2026 – 0840

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

01/05/2026 – 01/09/2026



[P1240139.JPG] – RHP03 – 01/08/2026 – 1010

No fuel product observed. Water observed is clear in the bailer sample.




[P1030294.JPG] – RHMW18 – 01/09/2026 – 0854

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

01/05/2026 – 01/09/2026



[P1030296.JPG] – RHP04A – 01/09/2026 – 1139

No fuel product observed. Water observed is clear in the bailer sample.




[P1050954.JPG] – RHMW08 – 01/09/2026 – 0949

No fuel product observed. Water containing Rhodamine WT from February dye tracer study injection.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/05/2026 – 01/09/2026



[P1050952.JPG] – RHMW09 – 01/09/2026 – 0811

No fuel product observed. Water observed is clear in the bailer sample.