



Daily Dust Monitoring Report: December 5, 2024

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station E642, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor-E642	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	8.52	6.74	5.72	5.77	70	35
PM 10	Avg, ug/M3	9.19	8.29	7.71	7.53	300	150



Debris Removal	
Envizor-4	20.8816, -156.6786
Envizor- E642	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754



Daily Dust Monitoring Report: December 10, 2024

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Envizor-5 was redeployed at the location of E642

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	7.93	8.39	7.52	7.89	70	35
PM 10	Avg, ug/M3	9.94	13.59	10.96	12.48	300	150



Debris Removal	
Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754



Daily Dust Monitoring Report: December 12, 2024

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	9.24	4.98	10.53	8.86	70	35
PM 10	Avg, ug/M3	10.88	6.93	13.93	11.12	300	150



Debris Removal	
Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754



Daily Dust Monitoring Report: December 17, 2024

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	6.35	4.71	6.42	5.29	70	35
PM 10	Avg, ug/M3	6.68	5.79	9.40	6.81	300	150



20.8817, -156.677

20.8816, -156.6786

20.8808, -156.6754

20.877, -156.6774

Debris Removal

Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754



Daily Dust Monitoring Report: December 19, 2024

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Envizor 6 experienced a technical issue and was not transmitting data. The issue is under investigation.

Weather Summary

No weather data was collected today.


Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	6.92	4.86	--	6.99	70	35
PM 10	Avg, ug/M3	7.20	5.49	--	8.71	300	150



20.8817, -156.677

20.8816, -156.6786

20.8808, -156.6754

20.877, -156.6774

Debris Removal

Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754



Daily Dust Monitoring Report: December 26, 2024

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	14.43	15.08	12.69	14.61	70	35
PM 10	Avg, ug/M3	15.10	17.89	15.72	17.45	300	150



Debris Removal	
Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754



Daily Dust Monitoring Report: December 28, 2024

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	7.70	4.66	8.23	2.90	70	35
PM 10	Avg, ug/M3	8.83	6.00	10.62	3.87	300	150



Debris Removal	
Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754