



Daily Dust Monitoring Report: January 2, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	6.41	5.82	6.25	4.95	70	35
PM 10	Avg, ug/M3	6.71	7.24	7.45	6.40	300	150



Debris Removal	
Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754



Daily Dust Monitoring Report: January 4, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	23.22	25.58	20.61	21.14	70	35
PM 10	Avg, ug/M3	23.54	22.92	22.90	22.50	300	150



Debris Removal	
Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754



Daily Dust Monitoring Report: January 7, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	15.99	14.00	13.60	11.46	70	35
PM 10	Avg, ug/M3	16.31	15.00	15.11	12.61	300	150



Debris Removal	
Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754



Daily Dust Monitoring Report: January 9, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	9.95	5.94	6.23	6.48	70	35
PM 10	Avg, ug/M3	10.52	8.59	7.86	9.17	300	150



Debris Removal	
Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754



Daily Dust Monitoring Report: January 14, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	3.34	6.55	7.91	6.78	70	35
PM 10	Avg, ug/M3	4.21	7.93	11.39	8.28	300	150



Debris Removal	
Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754



Daily Dust Monitoring Report: January 16, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	11.89	11.21	11.74	12.34	70	35
PM 10	Avg, ug/M3	12.17	12.54	13.62	14.47	300	150



Debris Removal	
Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754



Daily Dust Monitoring Report: January 21, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.


Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	7.39	5.29	2.31	4.44	70	35
PM 10	Avg, ug/M3	7.64	6.25	4.48	5.47	300	150



Debris Removal	
Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754



Daily Dust Monitoring Report: January 23, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	8.47	14.85	3.94	7.58	70	35
PM 10	Avg, ug/M3	8.87	24.85	6.81	9.23	300	150



Debris Removal	
Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754



Daily Dust Monitoring Report: January 28, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	7.91	1.15	1.92	3.55	70	35
PM 10	Avg, ug/M3	8.35	1.15	2.41	4.44	300	150



Debris Removal	
Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754



Daily Dust Monitoring Report: January 30, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

		Envizor-4	Envizor- 5	Envizor-6	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	18.99	17.58	17.09	17.20	70	35
PM 10	Avg, ug/M3	19.36	17.62	17.68	19.65	300	150



Debris Removal	
Envizor-4	20.8816, -156.6786
Envizor- 5	20.877, -156.6774
Envizor-6	20.8817, -156.677
Envizor-10/SR	20.8808, -156.6754