



Daily Dust Monitoring Report: February 6, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

| | | Envizor-4 | Envizor- 5 | Envizor-6 | Envizor-10 | Exceedance Limit | Action Limit |
|--------|------------|-----------|------------|-----------|------------|------------------|--------------|
| PM 2.5 | Avg, ug/M3 | 14.89 | 13.01 | 10.66 | 10.48 | 70 | 35 |
| PM 10 | Avg, ug/M3 | 15.33 | 13.05 | 11.39 | 11.75 | 300 | 150 |



| Debris Removal | |
|----------------|--------------------|
| Envizor-4 | 20.8816, -156.6786 |
| Envizor- 5 | 20.877, -156.6774 |
| Envizor-6 | 20.8817, -156.677 |
| Envizor-10/SR | 20.8808, -156.6754 |



Daily Dust Monitoring Report: February 7, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

| | | Envizor-4 | Envizor- 5 | Envizor-6 | Envizor-10 | Exceedance Limit | Action Limit |
|--------|------------|-----------|------------|-----------|------------|------------------|--------------|
| PM 2.5 | Avg, ug/M3 | 14.53 | 12.50 | 9.78 | 10.84 | 70 | 35 |
| PM 10 | Avg, ug/M3 | 15.00 | 12.50 | 10.50 | 12.47 | 300 | 150 |



| Debris Removal | |
|----------------|--------------------|
| Envizor-4 | 20.8816, -156.6786 |
| Envizor- 5 | 20.877, -156.6774 |
| Envizor-6 | 20.8817, -156.677 |
| Envizor-10/SR | 20.8808, -156.6754 |



Daily Dust Monitoring Report: February 11, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

| | | Envizor-4 | Envizor- 5 | Envizor-6 | Envizor-10 | Exceedance Limit | Action Limit |
|--------|------------|-----------|------------|-----------|------------|------------------|--------------|
| PM 2.5 | Avg, ug/M3 | 10.63 | 8.62 | 4.85 | 7.24 | 70 | 35 |
| PM 10 | Avg, ug/M3 | 11.36 | 9.08 | 5.87 | 9.37 | 300 | 150 |



| Debris Removal | |
|----------------|--------------------|
| Envizor-4 | 20.8816, -156.6786 |
| Envizor- 5 | 20.877, -156.6774 |
| Envizor-6 | 20.8817, -156.677 |
| Envizor-10/SR | 20.8808, -156.6754 |



Daily Dust Monitoring Report: February 13, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

| | | Envizor-4 | Envizor- 5 | Envizor-6 | Envizor-10 | Exceedance Limit | Action Limit |
|--------|------------|-----------|------------|-----------|------------|------------------|--------------|
| PM 2.5 | Avg, ug/M3 | 15.61 | 19.68 | 11.12 | 13.99 | 70 | 35 |
| PM 10 | Avg, ug/M3 | 16.35 | 21.93 | 12.05 | 15.98 | 300 | 150 |



| Debris Removal | |
|----------------|--------------------|
| Envizor-4 | 20.8816, -156.6786 |
| Envizor- 5 | 20.877, -156.6774 |
| Envizor-6 | 20.8817, -156.677 |
| Envizor-10/SR | 20.8808, -156.6754 |



Daily Dust Monitoring Report: February 18, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

| | | Envizor-4 | Envizor- 5 | Envizor-6 | Envizor-10 | Exceedance Limit | Action Limit |
|--------|------------|-----------|------------|-----------|------------|------------------|--------------|
| PM 2.5 | Avg, ug/M3 | 7.85 | 8.76 | 2.69 | 4.52 | 70 | 35 |
| PM 10 | Avg, ug/M3 | 8.20 | 9.29 | 3.43 | 5.59 | 300 | 150 |



| Debris Removal | |
|----------------|--------------------|
| Envizor-4 | 20.8816, -156.6786 |
| Envizor- 5 | 20.877, -156.6774 |
| Envizor-6 | 20.8817, -156.677 |
| Envizor-10/SR | 20.8808, -156.6754 |



Daily Dust Monitoring Report: February 20, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

| | | Envizor-4 | Envizor- 5 | Envizor-6 | Envizor-10 | Exceedance Limit | Action Limit |
|--------|------------|-----------|------------|-----------|------------|------------------|--------------|
| PM 2.5 | Avg, ug/M3 | 9.32 | 10.17 | 4.67 | 5.35 | 70 | 35 |
| PM 10 | Avg, ug/M3 | 9.77 | 11.66 | 5.90 | 7.17 | 300 | 150 |



| Debris Removal | |
|----------------|--------------------|
| Envizor-4 | 20.8816, -156.6786 |
| Envizor- 5 | 20.877, -156.6774 |
| Envizor-6 | 20.8817, -156.677 |
| Envizor-10/SR | 20.8808, -156.6754 |



Daily Dust Monitoring Report: February 27, 2025

Lahaina Debris Removal Operation

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was collected today.

Station Location Summary:

Station 4, Station 5, Station 6, and Station 10+ Sensitive Receptor were set up around **Pioneer Mill** for continued debris removal air monitoring.

Station Data:

- Debris removal

| | | Envizor-4 | Envizor- 5 | Envizor-6 | Envizor-10 | Exceedance Limit | Action Limit |
|--------|------------|-----------|------------|-----------|------------|------------------|--------------|
| PM 2.5 | Avg, ug/M3 | 24.60 | 32.05 | 30.19 | 26.82 | 70 | 35 |
| PM 10 | Avg, ug/M3 | 25.06 | 34.13 | 32.39 | 28.33 | 300 | 150 |



| Debris Removal | |
|----------------|--------------------|
| Envizor-4 | 20.8816, -156.6786 |
| Envizor- 5 | 20.877, -156.6774 |
| Envizor-6 | 20.8817, -156.677 |
| Envizor-10/SR | 20.8808, -156.6754 |