



Daily Dust Monitoring Report: January 3, 2025 Temporary Disposal Site

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary


No weather data was transmitted today

Station Location Summary:

Station 11 and Station 16 + Sensitive Receptor were set up around the **Temporary Disposal Site** for continued debris removal air monitoring.

Station Data:

		Envizor-11	Envizor-16	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	5.61	7.27	70	35
PM 10	Avg, ug/M3	6.57	8.57	300	150



Temporary Disposal Site	
Envizor-11	20.8313, -156.6323
Envizor-16/SR	20.8271, -156.6327



Daily Dust Monitoring Report: January 10, 2025

Temporary Disposal Site

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was transmitted today

Station Location Summary:

Station 16 + Sensitive Receptor was set up around the **Temporary Disposal Site** for continued debris removal air monitoring.

Station Data:

		Envizor-16	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	9.17	70	35
PM 10	Avg, ug/M3	10.57	300	150



Temporary Disposal Site	
Envizor-11	20.8313, -156.6323
Envizor-16/SR	20.8271, -156.6327



Daily Dust Monitoring Report: January 15, 2025

Temporary Disposal Site

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary


No weather data was transmitted today

Station Location Summary:

Station 11 and Station 16 + Sensitive Receptor were set up around the **Temporary Disposal Site** for continued debris removal air monitoring.

Station Data:

		Envizor-11	Envizor-16	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	4.98	6.33	70	35
PM 10	Avg, ug/M3	5.53	7.16	300	150



Temporary Disposal Site	
Envizor-11	20.8313, -156.6323
Envizor-16/SR	20.8271, -156.6327



Daily Dust Monitoring Report: January 22, 2025

Temporary Disposal Site

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary


No weather data was transmitted today

Station Location Summary:

Station 11 and Station 16 + Sensitive Receptor were set up around the **Temporary Disposal Site** for continued debris removal air monitoring.

Station Data:

		Envizor-11	Envizor-16	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	6.06	5.59	70	35
PM 10	Avg, ug/M3	6.77	6.59	300	150



Temporary Disposal Site	
Envizor-11	20.8313, -156.6323
Envizor-16/SR	20.8271, -156.6327



Daily Dust Monitoring Report: January 29, 2025

Temporary Disposal Site

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was transmitted today

Station Location Summary:

Station 11 and Station 16 + Sensitive Receptor were set up around the **Temporary Disposal Site** for continued debris removal air monitoring.

Station Data:

		Envizor-11	Envizor-16	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	2.99	7.98	70	35
PM 10	Avg, ug/M3	3.52	8.66	300	150



Temporary Disposal Site	
Envizor-11	20.8313, -156.6323
Envizor-16/SR	20.8271, -156.6327



Daily Dust Monitoring Report: February 5, 2025

Temporary Disposal Site

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was transmitted today

Station Location Summary:

Station 11 and Station 16 + Sensitive Receptor were set up around the **Temporary Disposal Site** for continued debris removal air monitoring.

Station Data:

		Envizor-11	Envizor-16	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	3.81	4.61	70	35
PM 10	Avg, ug/M3	4.62	5.77	300	150



Temporary Disposal Site	
Envizor-11	20.8313, -156.6323
Envizor-16/SR	20.8271, -156.6327



Daily Dust Monitoring Report: February 12, 2025

Temporary Disposal Site

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary


No weather data was transmitted today

Station Location Summary:

Station 11 and Station 16 + Sensitive Receptor were set up around the **Temporary Disposal Site** for continued debris removal air monitoring.

Station Data:

		Envizor-11	Envizor-16	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	9.10	7.23	70	35
PM 10	Avg, ug/M3	9.20	8.48	300	150



Temporary Disposal Site	
Envizor-11	20.8313, -156.6323
Envizor-16/SR	20.8271, -156.6327



Daily Dust Monitoring Report: February 19, 2025

Temporary Disposal Site

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary


No weather data was transmitted today

Station Location Summary:

Station 10 and Station 16 + Sensitive Receptor were set up around the **Temporary Disposal Site** for continued debris removal air monitoring.

Station Data:

		Envizor-10	Envizor-16	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	3.24	6.17	70	35
PM 10	Avg, ug/M3	4.27	6.79	300	150



Temporary Disposal Site	
Envizor-10	20.8313, -156.6323
Envizor-16/SR	20.8271, -156.6327



Daily Dust Monitoring Report: March 12, 2025

Temporary Disposal Site

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary


No weather data was transmitted today

Station Location Summary:

Station 10 and Station 4 + Sensitive Receptor were set up around the **Temporary Disposal Site** for continued debris removal air monitoring.

Station Data:

		Envizor-04	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	7.06	1.90	70	35
PM 10	Avg, ug/M3	7.58	3.38	300	150





Daily Dust Monitoring Report: March 14, 2025 Temporary Disposal Site

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was transmitted today

Station Location Summary:

Station 10 and Station 4 + Sensitive Receptor were set up around the **Temporary Disposal Site** for continued debris removal air monitoring.

Station Data:

		Envizor-04	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	8.07	3.93	70	35
PM 10	Avg, ug/M3	8.74	5.28	300	150





Daily Dust Monitoring Report: March 21, 2025

Temporary Disposal Site

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was transmitted today

Station Location Summary:

Station 10 and Station 4 + Sensitive Receptor were set up around the **Temporary Disposal Site** for continued debris removal air monitoring.

Station Data:

		Envizor-04	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	11.79	3.97	70	35
PM 10	Avg, ug/M3	12.70	5.05	300	150





Daily Dust Monitoring Report: March 24, 2025

Temporary Disposal Site

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was transmitted today

Station Location Summary:

Station 10 and Station 4 + Sensitive Receptor were set up around the **Temporary Disposal Site** for continued debris removal air monitoring.

Station Data:

		Envizor-04	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	9.99	1.45	70	35
PM 10	Avg, ug/M3	10.47	1.98	300	150





Daily Dust Monitoring Report: March 26, 2025

Temporary Disposal Site

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was transmitted today

Station Location Summary:

Station 10 and Station 4 + Sensitive Receptor were set up around the **Temporary Disposal Site** for continued debris removal air monitoring.

Station Data:

		Envizor-04	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	8.81	1.99	70	35
PM 10	Avg, ug/M3	9.19	2.62	300	150





Daily Dust Monitoring Report: March 28, 2025

Temporary Disposal Site

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was transmitted today

Station Location Summary:

Station 10 and Station 4 + Sensitive Receptor were set up around the **Temporary Disposal Site** for continued debris removal air monitoring.

Station Data:

		Envizor-04	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	10.55	5.46	70	35
PM 10	Avg, ug/M3	11.41	6.77	300	150





Daily Dust Monitoring Report: March 31, 2025

Temporary Disposal Site

Summary:

The ECC field staff and field crews continued to follow the prescribed methods of dust suppression and notification procedures.

The crews continue to use water for dust suppression all day.

No exceedances occurred.

Weather Summary

No weather data was transmitted today

Station Location Summary:

Station 10 and Station 4 + Sensitive Receptor were set up around the **Temporary Disposal Site** for continued debris removal air monitoring.

Station Data:

		Envizor-04	Envizor-10	Exceedance Limit	Action Limit
PM 2.5	Avg, ug/M3	12.70	4.60	70	35
PM 10	Avg, ug/M3	13.54	5.58	300	150

