Office of Health Care Assurance

State Licensing Section

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

Facility's Name: Aloha House	CHAPTER 98
Address: 4593 Ike Drive, Makawao, Hawaii, 96768	Inspection Date: February 22, 2019

THIS PAGE MUST BE SUBMITTED WITH YOUR PLAN OF CORRECTION. IF IT IS NOT, YOUR PLAN OF CORRECTION WILL BE RETURNED TO YOU, UNREVIEWED.

YOUR PLAN OF CORRECTION MUST BE SUBMITTED WITHIN TEN (10) WORKING DAYS. IF IT IS NOT RECEIVED WITHIN TEN (10) DAYS, YOUR STATEMENT OF DEFICIENCIES WILL BE POSTED ONLINE, WITHOUT YOUR RESPONSE.

RULES (CRITERIA)	PLAN OF CORRECTION	Completion Date
§11-98-14 Physical facility. (c) Maintenance. Facilities shall be maintained in accordance with provisions of state and county zoning, building, fire, safety and health codes in the State. FINDINGS Dorm A – Broken window in bathroom.	DID YOU CORRECT THE DEFICIENCY? USE THIS SPACE TO TELL US HOW YOU CORRECTED THE DEFICIENCY A proposal to fix broken window was obtained.	4/17/19

RULES (CRITERIA)	PLAN OF CORRECTION	Completion Date
§11-98-14 Physical facility. (c) Maintenance. Facilities shall be maintained in accordance with provisions of state and county zoning, building, fire, safety and health codes in the State.	PART 2 <u>FUTURE PLAN</u>	
FINDINGS Dorm A – Broken window in bathroom.	USE THIS SPACE TO EXPLAIN YOUR FUTURE PLAN: WHAT WILL YOU DO TO ENSURE THAT IT DOESN'T HAPPEN AGAIN?	
	The broken window will be fixed and the property	ongoing
	will be inspected each quarter. The Satisfy	
	Officer, Ron Nelson, will	
	review safety inspection reports submitted by	
	Program Coordinator II,	
	Jr. Delas Santos.	- -
		M2v _0

·	Licensee's/Administrator's Signature:	anthony	araes in FT
		T	Arcuria
	Date:	4/30/19	