

RECEIVED MAY 17 2017 *Scan*



DEPARTMENT OF THE NAVY

COMMANDER
NAVY REGION HAWAII
850 TICONDEROGA ST STE 110
JBPHH, HAWAII 96860-5101

5090
Ser N45/0499
May 12, 2017

CERTIFIED NO: 7016 0910 0001 0899 9167

Mr. Richard Takaba
Hawaii State Department of Health
Environmental Management Division
Solid and Hazardous Waste Branch
Underground Storage Tank Section
919 Ala Moana Boulevard, Room 212
Honolulu, HI 96814

Dear Mr. Takaba:

SUBJECT: RED HILL TANK COMPLEX
SOIL VAPOR SAMPLING RESULTS FOR APRIL 2017
DOH FACILITY ID NO. 9-102271
DOH RELEASE ID NO. 990051, 010011, 020028, AND 140010

Soil vapor samples were collected from beneath all active and accessible Red Hill tanks on April 20, 2017.

Soil vapor VOC concentrations were measured in the field using a photo-ionization detector. The soil vapor sampling results are being submitted as Enclosure 1.

A conservative approach is to assess the integrity of the associated tank system if VOC concentrations exceed 280,000 ppbv in soil vapor monitoring points (SVMPs) beneath tanks containing JP-5 or JP-8, or 14,000 ppbv in SVMPs beneath tanks containing marine diesel fuel. These values are 50 percent of the calculated vapor concentration from fuel-saturated water.

At Tank 5, the concentrations of VOCs detected in the front, middle, and outer edge soil vapor monitoring probes were 59,747 ppbv, 8,923 ppbv, and 43,980 ppbv, respectively. Tank 5 was emptied in January 2014 and has not contained fuel since that time. VOC concentrations in all down-gradient soil vapor monitors were below 1,000 ppbv.

The Tank 7 outer edge soil vapor monitoring probe measurement was 112,600 ppbv, or 2 times below the action level. Causative research was conducted and confirmed there was no release to the environment.


All other VOC concentrations measured in April were about 20 to 875 times below the action levels, with no consistent trends observed. Possible reasons for the results are speculative and may include, but not be limited to, ongoing projects in the tunnel, groundwater level fluctuations, rainfall (or lack thereof), and fuel movement in the tanks and piping.

5090
Ser N45/0499
May 12, 2017

Soil vapor VOC concentration trends will continue to be monitored. The next soil vapor sampling event is scheduled for May 2017, and will include collecting samples from soil vapor monitoring probes beneath all active and accessible tanks.

If there are any questions regarding this matter, or if more information is needed, please contact Mr. Melvin Muraoka at (808) 471-3869.

Sincerely,




CORY K. WAKI
Acting Director
Regional Environmental Department
By direction of the
Commander

Enclosure: 1. Summary of Soil Vapor Sampling Results for Tanks 2 through 18 and 20 through Apr 2017 (18 pages)

Copy to: Mr. Bob Pallarino, U.S. EPA Region 9, Underground Storage Tank Program Office
Mr. John Floyd, NAVSUP FLC Pearl Harbor
Mr. Rockne Krill, DLA Energy Pacific

Figure 1
Soil Vapor Measurements
SV02



ENCLOSURE(1)

Figure 2
Soil Vapor Measurements
SV03




Figure 3
Soil Vapor Measurements
SV04




Figure 4
Soil Vapor Measurements
SV05




Figure 5
Soil Vapor Measurements
SV06




Figure 6
Soil Vapor Measurements
SV07




Figure 7
Soil Vapor Measurements
SV08




Figure 8
Soil Vapor Measurements
SV09




Figure 9
Soil Vapor Measurements
SV10




Figure 10
Soil Vapor Measurements
SV11




Figure 11
Soil Vapor Measurements
SV12




Figure 12
Soil Vapor Measurements
SV13




Figure 13
Soil Vapor Measurements
SV14




Figure 14
Soil Vapor Measurements
SV15




Figure 15
Soil Vapor Measurements
SV16




Figure 16
Soil Vapor Measurements
SV17




Figure 17
Soil Vapor Measurements
SV18




Figure 18
Soil Vapor Measurements
SV20

