

DEPARTMENT OF THE NAVY

COMMANDER NAVY REGION HAWAII 850 TICONDEROGA ST STE 110 JBPHH, HAWAII 96860-5101

> 5000-45A N45 August 16, 2021

CERTIFIED NO: 9489 0090 0027 6232 9871 60

Mr. Richard Takaba Hawaii State Department of Health Solid and Hazardous Waste Branch Underground Storage Tank Section 2827 Waimano Home Road #100 Pearl City, HI 96782

Dear Mr. Takaba:

SUBJECT: RED HILL TANK COMPLEX

SOIL VAPOR SAMPLING RESULTS FOR JUNE 2021

DOH FACILITY ID NO. 9-102271

DOH RELEASE ID NO. 990051, 010011, 020028, 140010, AND 210012

Monthly soil vapor samples were collected from beneath all active and accessible Red Hill tanks on June 16, 2021. Tanks 1 and 19 are inactive and not included in the sampling network.

Soil vapor VOC concentrations were measured in the field using a photo-ionization detector. The soil vapor sampling results are presented graphically in an enclosure.

A conservative approach to assess the integrity of the associated tank system is to establish action thresholds for VOC concentrations in soil vapor monitoring points (SVMPs) beneath tanks as 50 percent of the calculated vapor concentration from fuel-saturated water. These action thresholds for SVMPs beneath tanks containing F-24 or JP-5 is 280,000 ppbv and 14,000 ppbv in SVMPs beneath tanks containing marine diesel fuel.

At Tank 5, the concentrations of VOCs detected in the front, middle and outer edge soil vapor monitoring probes were 271, 676, and 251 ppbv, respectively. VOC concentrations measured in all down-gradient tank soil vapor monitoring probes were 15 to 164 ppbv.

Additional supplemental monitoring is ongoing in response to the May 6, 2021 pipeline breach that occurred in the tunnel. SVMPs at Tanks 17 through 20 are believed to have been impacted by clean-up activities, resulting in increases in soil vapor VOC concentrations observed during the May and June monthly monitoring events. Soil vapor VOC concentrations at Tanks 17 through 20 were below the action levels and will continue to be monitored through the supplemental monitoring program.

5000-45A N45 August 16, 2021

All VOC concentrations measured in June were below the action levels, with no consistent trends observed over time.

Regular monthly soil vapor VOC concentrations will continue to be reported in accordance with the Groundwater Protection Plan. Soil vapor samples were collected on July 16, 2021 from active and accessible tanks. Results will be submitted under a separate cover. The next monthly soil vapor sampling event is scheduled for August 20, 2021.

If there are any questions regarding this matter, or if more information is needed, please contact Ms. Susan Lohr at (808) 471-4619 or Ms. Dayna Fujimoto at (808) 471-4805.

Sincerely,

SHERRI R. ENG

Director

Regional Environmental Department

By direction of the

Commander

Enclosure: Graphical Summary of Soil Vapor Sampling Results for Tanks 2 - 18 and 20


Data represented through June 2021 (18 pages)

Copy to: Mr. John Floyd, NAVSUP FLC Pearl Harbor

Electronic Copies to: Ms. Gabriela Carvalho, U.S. EPA Region 9, Red Hill Coordinator


Mr. John Reed, DLA Energy Pacific

Mr. William Potter, DLA




F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76

^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.




F-24; Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76

^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.




F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76

^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.




F-24; Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76

^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.




F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76

^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.




F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76

^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.




F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76

^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.




F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76

^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.




F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76

^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank,




F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76

^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.



F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76


^{* *}M/D* monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.



F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76 JP-5: Jet Fuel, Propellant Number 5 ppbv; Parts Per Billion by Volume

Tank 13 is empty and inactive, undergoing clean, inspect & repair (CIR), but remains accessible for soil vapor monitoring events.

^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.




F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76

JP-5: Jet Fuel, Propellant Number 5 ppbv: Parts Per Billion by Volume


Tank 14 is empty and inactive, undergoing clean, inspect & repair (CIR), but remains accessible for soil vapor monitoring events.

^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.




F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76

^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.



F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76

^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.




F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76

JP-5: Jet Fuel, Propellant Number 5 ppbv: Parts Per Billion by Volume

Tank 17 is empty and inactive, undergoing clean, inspect & repair (CIR), but remains accessible for soil vapor monitoring events.


^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.



F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76 JP-5: Jet Fuel, Propellant Number 5 ppbv: Parts Per Billion by Volume

Tank 18 is empty and inactive, undergoing clean, inspect & repair (CIR), but remains accessible for soil vapor monitoring events.

^{* *}M/D* monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.



F-24: Jet Fuel, Fuel Number 24 F-76: Marine Diesel, Fuel Number 76

^{* &}quot;M/D" monitoring points were constructed to screen both middle & deep depth intervals along the respective underground storage tank.