

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/15/2024 – 01/19/2024



[P1060905.JPG] – RHMW01R Seal (Before Sampling) – 1/19/2024 – 0853



[P1060907.JPG] – RHMW01R Seal (After Sampling) – 1/19/2024 – 0955

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/15/2024 – 01/19/2024



[P1060908.JPG] – RHMW02 Seal (Before Sampling) – 1/19/2024 – 0958



[P1060909.JPG] – RHMW02 Seal (After Sampling) – 1/19/2024 – 1105

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/15/2024 – 01/19/2024



[P1060890.JPG] – RHMW03 Seal (Before Sampling) – 1/16/2024 – 0835



[P1060891.JPG] – RHMW03 Seal (After Sampling) – 1/16/2024 – 0937

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/15/2024 – 01/19/2024



[P1230467.JPG] – RHMW05 Seal (Before Sampling) – 1/16/2024 – 0953



[P1230468.JPG] – RHMW05 Seal (After Sampling) – 1/16/2024 – 1054

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/15/2024 – 01/19/2024



[P1230464.JPG] – RHP07 Seal (Before Sampling) – 1/16/2024 – 0854




[P1230465.JPG] – RHP07 Seal (After Sampling) – 1/16/2024 – 0947


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/15/2024 – 01/19/2024



[P1060899.JPG] – RHMW2254-01 – 1/16/2024 – 1237
No fuel product observed.




[P1060900.JPG] – RHMW2254-01 (under blacklight) – 1/16/2024 – 1237
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/15/2024 – 01/19/2024



[P1230461.JPG] – RHMW04 – 1/15/2024 – 0826
No fuel product observed.




[P1230463.JPG] – RHMW06 – 1/15/2024 – 1028
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/15/2024 – 01/19/2024



[P1010705.JPG] – RHMW08 – 1/15/2024 – 0955
No fuel product observed.




[P1010709.JPG] – RHMW09 – 1/16/2024 – 0804
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/15/2024 – 01/19/2024



[P1030886.JPG] – RHMW10 – 1/17/2024 – 1158
No fuel product observed.




[P1060893.JPG] – RHMW17 – 1/16/2024 – 1020
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/15/2024 – 01/19/2024



[P1030884.JPG] – RHMW18 – 1/17/2024 – 0844
No fuel product observed.




[P1010712.JPG] – RHMW19 – 1/16/2024 – 0952
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/15/2024 – 01/19/2024



[P1060904.JPG] – RHMW20 – 1/17/2024 – 0930
No fuel product observed.




[P1010714.JPG] – RHP06 – 1/17/2024 – 0825
No fuel product observed.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

01/15/2024 – 01/19/2024



[P1010704.JPG] – RHP08 – 1/15/2024 – 0803
No fuel product observed.