

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1060961.JPG] – RHMW01R Seal (Before Sampling) – 4/4/2024 – 0842



[P1060964.JPG] – RHMW01R Seal (After Sampling) – 4/4/2024 – 1123

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1060965.JPG] – RHMW02 Seal (Before Sampling) – 4/4/2024 – 1128



[P1060968.JPG] – RHMW02 Seal (After Sampling) – 4/4/2024 – 1357

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1060969.JPG] – RHMW03 Seal (Before Sampling) – 4/4/2024 – 1402



[P1060972.JPG] – RHMW03 Seal (After Sampling) – 4/4/2024 – 1540

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1040163.JPG] – RHMW05 Seal (Before Sampling) – 4/3/1024 – 1157



[P1040167.JPG] – RHMW05 Seal (After Sampling) – 4/3/1024 – 1332

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1040156.JPG] – RHP07 Seal (Before Sampling) – 4/2/2024 – 1304




[P1040160.JPG] – RHP07 Seal (After Sampling) – 4/2/2024 – 1429


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1040153.JPG] – RHMW2254-01 – 4/2/2024 – 1044
No fuel product observed.




[P1040155.JPG] – RHMW2254-01 (under blacklight) – 4/2/2024 – 1112
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1060963.JPG] – RHMW01R – 4/4/2024 – 0851
No fuel product observed.




[P1060967.JPG] – RHMW02 – 4/4/2024 – 1139
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1060970.JPG] – RHMW03 – 4/4/2024 – 1407
No fuel product observed.




[P1040176.JPG] – RHMW04 – 4/8/2024 – 0820
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1040165.JPG] – RHMW05 – 4/3/1024 – 1207
No fuel product observed.




[P1060959.JPG] – RHMW06 – 4/1/2024 – 1054
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1060958.JPG] – RHMW08 – 4/1/2024 – 0856
No fuel product observed.




[P1010749.JPG] – RHMW09 – 4/2/2024 – 0925
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1040173.JPG] – RHMW10 – 4/5/2024 – 0809
No fuel product observed.




[P1010758.JPG] – RHMW17 – 4/10/2024 – 1117
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1040197.JPG] – RHMW18 – 4/11/2024 – 1149
No fuel product observed.




[P1010750.JPG] – RHMW19 – 4/2/2024 – 1228
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1010760.JPG] – RHMW20 – 4/12/2024 – 1251
No fuel product observed.




[P1010748.JPG] – RHP01 – 4/1/2024 – 0819
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1040172.JPG] – RHP02 – 4/4/2024 – 1233
No fuel product observed.




[P1040170.JPG] – RHP03 – 4/4/2024 – 1045
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1040169.JPG] – RHP04A – 4/4/2024 – 0730
No fuel product observed.



[P1010753.JPG] – RHP05 – 4/5/2024 – 1131
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1010752.JPG] – RHP06 – 4/5/2024 – 0812
No fuel product observed.




[P1040159.JPG] – RHP07 – 4/2/2024 – 1310
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1040175.JPG] – RHP08 – 4/5/2024 – 1036
No fuel product observed.




[P1230527.JPG] – NMW24 – 4/10/2024 – 0836
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1230528.JPG] – NMW25 – 4/10/2024 – 1058
No fuel product observed.




[P1010754.JPG] – NMW26 – 4/9/2024 – 1204
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1040196.JPG] – NMW30 – 4/11/2024 – 0828
No fuel product observed.




[P1060974.JPG] – NMW32 – 4/11/2024 – 0827
No fuel product observed.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

04/01/2024 – 04/12/2024



[P1060976.JPG] – NMW33 – 4/11/2024 – 1055
No fuel product observed.



[P1010757.JPG] – NMW34 – 4/10/2024 – 0821
No fuel product observed.