

06/10/2024 - 6/14/2024



[100_0825.JPG] – RHMW04 – 6/11/2024 – 0846 No fuel product observed. Water observed is clear in the bailer sample.




[P1040346.JPG] – RHMW17 – 6/10/2024 – 1419 No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging Photos

AECOM

06/10/2024 - 6/14/2024




[P1230539.JPG] – RHMW18 – 6/13/2024 – 1221 No fuel product observed. Water observed is clear in the bailer sample.




[P1040366.JPG] – RHMW20 – 6/14/2024 – 1055 No fuel product observed. Water observed is clear in the bailer sample.

06/10/2024 - 6/14/2024




[P1230531.JPG] – NMW24 – 6/12/2024 – 0849 No fuel product observed. Water observed is clear in the bailer sample.




[P1230535.JPG] – NMW25 – 6/12/2024 – 1054 No fuel product observed. Water observed is clear in the bailer sample.

06/10/2024 - 6/14/2024




[P1010895.JPG] – NMW26 – 6/10/2024 – 0853 No fuel product observed. Water observed is clear with in the bailer sample.




[P1230538.JPG] – NMW30 – 6/13/2024 – 0842 No fuel product observed. Water observed is clear in the bailer sample.

06/10/2024 - 6/14/2024




[P1040353.JPG] - NMW32 - 6/13/2024 - 1037

No fuel product observed. Water observed is clear with minute, black sediment floating in the bailer sample.



[P1040350.JPG] – NMW33 – 6/13/2024 – 0851 No fuel product observed. Water observed is clear in the bailer sample.

06/10/2024 - 6/14/2024



[P1040349.JPG] – NMW34 – 6/11/2024 – 0909 No fuel product observed. Water observed is clear in the bailer sample.