


Red Hill – Monitoring Well Fuel Product Gauging Photos


AECOM

07/08/2024 – 07/12/2024



[P1230577.JPG] – RHMW04 – 7/9/2024 – 0847

No fuel product observed. Water observed is clear in the bailer sample.




[P1230574.JPG] – RHMW17 – 7/8/2024 – 1305

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging Photos

AECOM

07/08/2024 – 07/12/2024



[P1230587.JPG] – RHMW18 – 7/11/2024 – 0912
No fuel product observed. Water observed is clear in the bailer sample.




[P1040492.JPG] – RHMW20 – 7/09/2024 – 1120
No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging Photos


AECOM

07/08/2024 – 07/12/2024



[P1230579.JPG] – NMW24 – 7/10/2024 – 0907

No fuel product observed. Water observed is clear in the bailer sample.




[P1230583.JPG] – NMW25 – 7/10/2024 – 1042

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging Photos


AECOM

07/08/2024 – 07/12/2024



[P1040486.JPG] – NMW26 – 7/8/2024 – 0900

No fuel product observed. Water observed is clear in the bailer sample.




[P1230589.JPG] – NMW30 – 7/11/2024 – 1213

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging Photos


AECOM

07/08/2024 – 07/12/2024



[P1040501.JPG] – NMW32 – 7/11/2024 – 1039

No fuel product observed. Water observed is clear in the bailer sample.




[P1040496.JPG] – NMW33 – 7/11/2024 – 0827

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging Photos

AECOM

07/08/2024 – 07/12/2024



[P1040491.JPG] – NMW34 – 7/9/2024 – 0843

No fuel product observed. Water observed is clear in the bailer sample.