

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

08/19/2024 – 08/23/2024



[P1230708.JPG] – RHMW01R Seal (Before Sampling) – 8/22/2024 – 1339



[P1230712.JPG] – RHMW01R Seal (After Sampling) – 8/22/2024 – 1520

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

08/19/2024 – 08/23/2024



[P1230702.JPG] – RHMW02 Seal (Before Sampling) – 8/22/2024 – 1148



[P1230707.JPG] – RHMW02 Seal (After Sampling) – 8/22/2024 – 1336

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

08/19/2024 – 08/23/2024



[P1040581.JPG] – RHMW03 Seal (Before Sampling) – 8/20/2024 – 0913



[P1040586.JPG] – RHMW03 Seal (After Sampling) – 8/20/2024 – 1048

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

08/19/2024 – 08/23/2024



[P1040607.JPG] – RHMW05 Seal (Before Sampling) – 8/21/2024 – 1049



[P1040611.JPG] – RHMW05 Seal (After Sampling) – 8/21/2024 – 1223

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

08/19/2024 – 08/23/2024



[P1230697.JPG] – RHMW21 Seal (Before Sampling) – 8/22/2024 – 0923



[P1230701.JPG] – RHMW21 Seal (After Sampling) – 8/22/2024 – 1138


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

08/19/2024 – 08/23/2024



[P1040596.JPG] – RHP07 Seal (Before Sampling) – 8/21/2024 – 0902




[P1040606.JPG] – RHP07 Seal (After Sampling) – 8/21/2024 – 1038


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

08/19/2024 – 08/23/2024



[P1040595.JPG] – RHMW2254-01 – 8/20/2024 – 1155
No fuel product observed. Water observed is clear in the bailer sample.




[P1040591.JPG] – RHMW2254-01 (under blacklight) – 8/20/2024 – 1154
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

08/19/2024 – 08/23/2024



[P1230709.JPG] – RHMW01R – 8/22/2024 – 1346
No fuel product observed. Water observed is clear in the bailer sample.




[P1230704.JPG] – RHMW02 – 8/22/2024 – 1203
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

08/19/2024 – 08/23/2024



[P1040585.JPG] – RHMW03 – 8/20/2024 – 0925
No fuel product observed. Water observed is clear in the bailer sample.




[P1040610.JPG] – RHMW05 – 8/21/2024 – 1103
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

08/19/2024 – 08/23/2024



[P1020026.JPG] – RHMW06 – 8/22/2024 – 1540
No fuel product observed. Water observed is clear in the bailer sample.




[P1020014.JPG] – RHMW08 – 8/21/2024 – 1415
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

08/19/2024 – 08/23/2024



[P1230718.JPG] – RHMW09 – 8/23/2024 – 1101
No fuel product observed. Water observed is clear in the bailer sample.




[P1230717.JPG] – RHMW10 – 8/23/2024 – 0919
No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

08/19/2024 – 08/23/2024



[P1230713.JPG] – RHMW19 – 8/23/2024 – 0850

No fuel product observed. Water observed is clear in the bailer sample.




[P1230700.JPG] – RHMW21 – 8/22/2024 – 0949

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

08/19/2024 – 08/23/2024



[P1230690.JPG] – RHP01 – 8/20/2024 – 0841

No fuel product observed. Water observed is clear in the bailer sample.




[P1230693.JPG] – RHP02 – 8/20/2024 – 1206

No fuel product observed. Water observed is clear in the bailer sample. Photo has slight red tint from reflection of red pop up tent used by field team.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

08/19/2024 – 08/23/2024



[P1020015.JPG] – RHP03 – 8/22/2024 – 0935
No fuel product observed. Water observed is clear in the bailer sample.




[P1020022.JPG] – RHP04A – 8/22/2024 – 1158
No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

08/19/2024 – 08/23/2024



[P1230720.JPG] – RHP05 – 8/23/2024 – 1331

No fuel product observed. Water observed is clear in the bailer sample.




[P1230685.JPG] – RHP06 – 8/19/2024 – 0848

No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

08/19/2024 – 08/23/2024



[P1040602.JPG] – RHP07 – 8/21/2024 – 0916
No fuel product observed. Water observed is clear in the bailer sample.



[P1230686.JPG] – RHP08 – 8/19/2024 – 1105
No fuel product observed. Water observed is clear in the bailer sample.