




 $\label{eq:product} \mbox{[P1020129.JPG]} - \mbox{RHMW04} - 10/15/2024 - 0904$  No fuel product observed. Water observed is clear in the bailer sample.



[P1020127.JPG] - RHMW17 - 10/14/2024 - 0850No fuel product observed. Water observed is clear in the bailer sample.




[P1040780.JPG] - RHMW18 - 10/17/2024 - 0913 No fuel product observed. Water observed is clear in the bailer sample.




 $\label{eq:product} \hbox{[P1040776.JPG]}-\hbox{RHMW20}-\hbox{10/16/2024}-\hbox{1217}$  No fuel product observed. Water observed is clear in the bailer sample.

## Red Hill – Monitoring Well Fuel Product Gauging Photos AECOM




[P1040772.JPG] - NMW24 - 10/15/2024 - 0813 No fuel product observed. Water observed is clear in the bailer sample.




[P1040775.JPG] - NMW25 - 10/15/2024 - 1001No fuel product observed. Water observed is clear in the bailer sample.

10/14/2024 - 10/18/2024



[P1040767.JPG] - NMW26 - 10/14/2024 - 0916


No fuel product observed. Water observed is clear with minute pieces of organic matter in the bailer sample.




[P1040782.JPG] – NMW30 – 10/17/2024 – 1207

No fuel product observed. Water observed is clear in the bailer sample.

## Red Hill – Monitoring Well Fuel Product Gauging Photos AECOM




 $\label{eq:p1020135.JPG} [P1020135.JPG] - NMW32 - 10/17/2024 - 1051$  No fuel product observed. Water observed is clear in the bailer sample.



[P1020133.JPG] – NMW33 – 10/17/2024 – 0905 No fuel product observed. Water observed is clear in the bailer sample.

## Red Hill – Monitoring Well Fuel Product Gauging Photos AECOM



[P1020136.JPG] – NMW34 – 10/17/2024 – 1236 No fuel product observed. Water observed is clear in the bailer sample.