

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

10/21/2024 – 10/25/2024



[P1040784.JPG] – RHMW01R Seal (Before Sampling) – 10/21/2024 – 0929



[P1040789.JPG] – RHMW01R Seal (After Sampling) – 10/21/2024 – 1155

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

10/21/2024 – 10/25/2024



[P1040790.JPG] – RHMW02 Seal (Before Sampling) – 10/21/2024 – 1200



[P1040795.JPG] – RHMW02 Seal (After Sampling) – 10/21/2024 – 1422

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

10/21/2024 – 10/25/2024



[P1040796.JPG] – RHMW03 Seal (Before Sampling) – 10/22/2024 – 0909



[P1040801.JPG] – RHMW03 Seal (After Sampling) – 10/22/2024 – 1048

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

10/21/2024 – 10/25/2024



[P1040816.JPG] – RHMW05 Seal (Before Sampling) – 10/23/2024 – 1148



[P1040820.JPG] – RHMW05 Seal (After Sampling) – 10/23/2024 – 1341

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

10/21/2024 – 10/25/2024



[P1020144.JPG] – RHMW21 Seal (Before Sampling) – 10/21/2024 – 0950



[P1020148.JPG] – RHMW21 Seal (After Sampling) – 10/21/2024 – 1515

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

10/21/2024 – 10/25/2024



[P1040811.JPG] – RHP07 Seal (Before Sampling) – 10/23/2024 – 0936




[P1040815.JPG] – RHP07 Seal (After Sampling) – 10/23/2024 – 1140


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

10/21/2024 – 10/25/2024



[P1040808.JPG] – RHMW2254-01 – 10/22/2024 – 1139
No fuel product observed. Water observed is clear in the bailer sample.




[P1040809.JPG] – RHMW2254-01 (under blacklight) – 10/22/2024 – 1140
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

10/21/2024 – 10/25/2024



[P1040785.JPG] – RHMW01R – 10/21/2024 – 0939
No fuel product observed. Water observed is clear in the bailer sample.




[P1040792.JPG] – RHMW02 – 10/21/2024 – 1247
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

10/21/2024 – 10/25/2024



[P1040800.JPG] – RHMW03 – 10/22/2024 – 0920
No fuel product observed. Water observed is clear in the bailer sample.




[P1040819.JPG] – RHMW05 – 10/23/2024 – 1155
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

10/21/2024 – 10/25/2024



[P1230810.JPG] – RHMW06 – 10/24/2024 – 0950
No fuel product observed. Water observed is clear in the bailer sample.




[P1020143.JPG] – RHMW08 – 10/21/2024 – 0934
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

10/21/2024 – 10/25/2024



[P1040824.JPG] – RHMW09 – 10/25/2024 – 0844
No fuel product observed. Water observed is clear in the bailer sample.




[P1230818.JPG] – RHMW10 – 10/25/2024 – 1325
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

10/21/2024 – 10/25/2024



[P1040825.JPG] – RHMW19 – 10/25/2024 – 1131
No fuel product observed. Water observed is clear in the bailer sample.




[P1020146.JPG] – RHMW21 – 10/21/2024 – 1402
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

10/21/2024 – 10/25/2024



[P1040821.JPG] – RHP01 – 10/24/2024 – 1120
No fuel product observed. Water observed is clear in the bailer sample.




[P1040823.JPG] – RHP02 – 10/24/2024 – 1204
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

10/21/2024 – 10/25/2024



[P1230813.JPG] – RHP03 – 10/24/2024 – 1141
No fuel product observed. Water observed is clear in the bailer sample.




[P1020156.JPG] – RHP04A – 10/24/2024 – 0926
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

10/21/2024 – 10/25/2024



[P1230816.JPG] – RHP05 – 10/25/2024 – 0900
No fuel product observed. Water observed is clear in the bailer sample.




[P1020152.JPG] – RHP06 – 10/22/2024 – 1325
No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

10/21/2024 – 10/25/2024



[P1040814.JPG] – RHP07 – 10/23/2024 – 0945

No fuel product observed. Water observed is clear in the bailer sample.



[P1020151.JPG] – RHP08 – 10/22/2024 – 0947

No fuel product observed. Water observed is clear in the bailer sample.