



 $\label{eq:product} \mbox{[P1040832.JPG]} - \mbox{RHMW04} - 10/29/2024 - 0849$ No fuel product observed. Water observed is clear in the bailer sample.




[P1230819.JPG] – RHMW17 – 10/28/2024 – 0926 No fuel product observed. Water observed is clear in the bailer sample.




[P1230823.JPG] – RHMW18 – 10/30/2024 – 1153 No fuel product observed. Water observed is clear in the bailer sample.




 $\label{eq:product} \begin{tabular}{ll} [P1230827.JPG] - RHMW20 - 10/31/2024 - 1304 \\ No fuel product observed. Water observed is clear in the bailer sample. Green reflection on water surface is from the top of the bailer. \\ \end{tabular}$




 $\label{eq:p1020165.JPG} [P1020165.JPG] - NMW24 - 10/31/2024 - 1210$ No fuel product observed. Water observed is clear in the bailer sample.




 $\label{eq:p1020163.JPG} [P1020163.JPG] - NMW25 - 10/30/2024 - 1252$ No fuel product observed. Water observed is clear in the bailer sample.




[P1040829.JPG] - NMW26 - 10/28/2024 - 1137No fuel product observed. Water observed is clear in the bailer sample.



[P1230822.JPG] – NMW30 – 10/30/2024 – 0902 No fuel product observed. Water observed is clear in the bailer sample.




 $\label{eq:p1020157.JPG} [P1020157.JPG] - NMW32 - 10/29/2024 - 0853$ No fuel product observed. Water observed is clear in the bailer sample.



 $\label{eq:p1020161.JPG} [P1020161.JPG] - NMW33 - 10/29/2024 - 1502$ No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging Photos AECOM 10/28/2024 – 10/31/2024



[P1020159.JPG] – NMW34 – 10/29/2024 – 1203 No fuel product observed. Water observed is clear in the bailer sample.