


Red Hill – Monitoring Well Fuel Product Gauging Photos


AECOM

11/24/2024 – 11/29/2024



[P1040840.JPG] – RHMW04 – 11/26/2024 – 1149

No fuel product observed. Water observed is clear with small bubbles in the bailer sample.




[P1230855.JPG] – RHMW18 – 11/26/2024 – 1139

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging Photos


AECOM

11/24/2024 – 11/29/2024



[P1020290.JPG] – RHMW20 – 11/26/2024 – 1249

No fuel product observed. Water observed is clear in the bailer sample.




[P1020286.JPG] – NMW25 – 11/26/2024 – 0853

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging Photos


AECOM

11/24/2024 – 11/29/2024



[P1040838.JPG] – NMW26 – 11/25/2024 – 1140

No fuel product observed. Water observed is clear in the bailer sample.




[P1230853.JPG] – NMW30 – 11/26/2024 – 0928

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging Photos


AECOM

11/24/2024 – 11/29/2024



[P1020282.JPG] – NMW32 – 11/25/2024 – 1055

No fuel product observed. Water observed is clear with a small bubble and minute pieces of organic matter in the bailer sample.




[P1020279.JPG] – NMW33 – 11/25/2024 – 0912

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging Photos

AECOM

11/24/2024 – 11/29/2024



[P1040833.JPG] – NMW34 – 11/25/2024 – 0842

No fuel product observed. Water observed is clear with a minute piece of organic matter in the bailer sample.