


Red Hill – Monitoring Well Fuel Product Gauging Photos


AECOM

12/30/2024



[P1050010.JPG] – NMW26 – 12/30/2024 – 1306

No fuel product observed. Small organic material observed at surface of bailer water.



[P1050016.JPG] – NMW33 – 12/30/2024 – 1341

No fuel product observed. Water observed is clear in the bailer sample.