

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**

**AECOM**

**09/01/2025 – 09/05/2025**



[P1030005.JPG] – RHMW01R Seal (Before Sampling) – 9/3/2025 – 1112



[P1030009.JPG] – RHMW01R Seal (After Sampling) – 9/3/2025 – 1241

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**

**AECOM**

**09/01/2025 – 09/05/2025**



[P1030002.JPG] – RHMW02 Seal (Before Sampling) – 9/3/2025 – 0908



[P1050652.JPG] – RHMW21 Seal (Before Sampling) – 9/3/2025 – 0854

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**

**AECOM**

**09/01/2025 – 09/05/2025**



[P1050654.JPG] – RHMW21 Seal (After Sampling) – 9/3/2025 – 1015



[P1030015.JPG] – RHMW03 Seal (Before Sampling) – 9/4/2025 – 1055



**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**

**AECOM**

**09/01/2025 – 09/05/2025**



[P1030019.JPG] – RHMW03 Seal (After Sampling) – 9/4/2025 – 1228



[P1030011.JPG] – RHMW05 Seal (Before Sampling) – 9/4/2025 – 0925

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**

**AECOM**

**09/01/2025 – 09/05/2025**



[P1030014.JPG] – RHMW05 Seal (After Sampling) – 9/4/2025 – 1043



[P1050655.JPG] – RHP07 Seal (Before Sampling) – 9/4/2025 – 0907


**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**

**AECOM**

**09/01/2025 – 09/05/2025**



[P1050658.JPG] – RHP07 Seal (After Sampling) – 9/4/2025 – 1043




[P1240010.JPG] – RHP04A – 9/2/2025 – 1216

No fuel product observed. Water observed is clear in the bailer sample.

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**


**AECOM**

**09/01/2025 – 09/05/2025**



[P1240006.JPG] – RHP06 – 9/2/2025 – 0952

No fuel product observed. Water observed is clear in the bailer sample.



[P1240005.JPG] – RHP08 – 9/2/2025 – 0905


No fuel product observed. Water observed is clear in the bailer sample.



**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**


**AECOM**

**09/01/2025 – 09/05/2025**



[P1030001.JPG] – RHMW08 – 9/2/2025 – 1121

No fuel product observed. Water containing Rhodamine WT from February dye tracer study injection.



[P1020996.JPG] – RHMW09 – 9/2/2025 – 0911


No fuel product observed. Water observed is clear in the bailer sample.



**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**


**AECOM**

**09/01/2025 – 09/05/2025**



[P1050650.JPG] – RHP05 – 9/2/2025 – 0839

No fuel product observed. Water observed is clear in the bailer sample.




[P1030008.JPG] – RHMW01R – 9/3/2025 – 1125

No fuel product observed. Water observed is clear in the bailer sample.

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**


**AECOM**

**09/01/2025 – 09/05/2025**



[P1030004.JPG] – RHMW02 – 9/3/2025 – 0923

No fuel product observed. Water observed is clear in the bailer sample.




[P1050653.JPG] – RHMW21 – 9/3/2025 – 1133

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

09/01/2025 – 09/05/2025



[P1050627.JPG] – RHMW03 – 9/3/2025 – 1055

No fuel product observed. Water observed is clear in the bailer sample.




[P1030013.JPG] – RHMW05 – 9/4/2025 – 0933

No fuel product observed. Water observed is clear in the bailer sample.

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**


**AECOM**

**09/01/2025 – 09/05/2025**



[P1050656.JPG] – RHP07 – 9/4/2025 – 0916

No fuel product observed. Water observed is clear in the bailer sample.



[P1240021.JPG] – RHMW06 – 9/5/2025 – 1432


No fuel product observed. Water observed is clear in the bailer sample.



**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**


**AECOM**

**09/01/2025 – 09/05/2025**



[P1050661.JPG] – RHP01 – 9/5/2025 – 0812

No fuel product observed. Water observed is clear in the bailer sample.




[P1050661.JPG] – RHP02 – 9/5/2025 – 0955

No fuel product observed. Water observed is clear in the bailer sample.

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**


**AECOM**

**09/01/2025 – 09/05/2025**



[P1050664.JPG] – RHP03 – 9/5/2025 – 1144

No fuel product observed. Water observed is clear in the bailer sample.




[P1240012.JPG] – RHMW10 – 9/5/2025 – 0928

No fuel product observed. Water observed is clear in the bailer sample.

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**

**AECOM**

**09/01/2025 – 09/05/2025**



[P1240014.JPG] – RHMW19 – 9/5/2025 – 1145

No fuel product observed. Water observed is clear in the bailer sample.