

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

11/17/2025 – 11/21/2025



[P1050813.JPG] – RHMW01R Seal (Before Sampling) – 11/17/2025 – 0849



[P1050819.JPG] – RHMW01R Seal (After Sampling) – 11/17/2025 – 1023

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

11/17/2025 – 11/21/2025



[P1030164.JPG] – RHMW02 Seal (Before Sampling) – 11/17/2025 – 0907



[P1030168.JPG] – RHMW02 Seal (After Sampling) – 11/17/2025 – 1026

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

11/17/2025 – 11/21/2025



[P1030169.JPG] – RHMW21 Seal (Before Sampling) – 11/17/2025 – 1036



[P1030171.JPG] – RHMW21 Seal (After Sampling) – 11/17/2025 – 1200

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

11/17/2025 – 11/21/2025



[P1030180.JPG] – RHMW03 Seal (Before Sampling) – 11/19/2025 – 1028



[P1030182.JPG] – RHMW03 Seal (After Sampling) – 11/19/2025 – 1149

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

11/17/2025 – 11/21/2025



[P1030177.JPG] – RHMW05 Seal (Before Sampling) – 11/19/2025 – 0858



[P1030179.JPG] – RHMW05 Seal (After Sampling) – 11/19/2025 – 1016

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

11/17/2025 – 11/21/2025



[P1050825.JPG] – RHP07 Seal (Before Sampling) – 11/19/2025 – 0839




[P1050829.JPG] – RHP07 Seal (After Sampling) – 11/19/2025 – 1033

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

11/17/2025 – 11/21/2025



[P1050815.JPG] – RHMW01R – 11/17/2025 – 0903

No fuel product observed. Water observed is clear in the bailer sample.




[P1030166.JPG] – RHMW02 – 11/17/2025 – 0917

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

11/17/2025 – 11/21/2025



[P1030170.JPG] – RHMW21 – 11/17/2025 – 1048

No fuel product observed. Water observed is clear in the bailer sample.




[P1030174.JPG] – RHMW10 – 11/18/2025 – 0900

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

11/17/2025 – 11/21/2025



[P1030176.JPG] – RHMW19 – 11/18/2025 – 1127

No fuel product observed. Water observed is clear in the bailer sample.




[P1050821.JPG] – RHP05 – 11/18/2025 – 0807

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

11/17/2025 – 11/21/2025



[P1240096.JPG] – RHP06 – 11/18/2025 – 0858

No fuel product observed. Water observed is clear in the bailer sample.




[P1050823.JPG] – RHP08 – 11/18/2025 – 1015

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

11/17/2025 – 11/21/2025



[P1030181.JPG] – RHMW03 – 11/19/2025 – 1035

No fuel product observed. Water observed is clear in the bailer sample.




[P1030178.JPG] – RHMW05 – 11/19/2025 – 0907

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

11/17/2025 – 11/21/2025



[P1050828.JPG] – RHP07 – 11/19/2025 – 0855

No fuel product observed. Water observed is clear in the bailer sample.




[P1050833.JPG] – RHMW06 – 11/20/2025 – 1052

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

11/17/2025 – 11/21/2025



[P1050837.JPG] – RHMW18 – 11/20/2025 – 1313

No fuel product observed. Water observed is clear in the bailer sample.




[P1240098.JPG] – RHP01 – 11/20/2025 – 0845

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

11/17/2025 – 11/21/2025



[P1240103.JPG] – RHP02 – 11/20/2025 – 1111

No fuel product observed. Water observed is clear in the bailer sample.




[P1240100.JPG] – RHP03 – 11/20/2025 – 0913

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

11/17/2025 – 11/21/2025



[P1030186.JPG] – RHMW08 – 11/20/2025 – 1114

No fuel product observed. Water containing Rhodamine WT from February dye tracer study injection.




[P1030185.JPG] – RHMW09 – 11/20/2025 – 0856

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

11/17/2025 – 11/21/2025



[P1240106.JPG] – RHP04A – 11/20/2025 – 1140

No fuel product observed. Water observed is clear in the bailer sample.




[P1030188.JPG] – RHMW17 – 11/21/2025 – 0945

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

11/17/2025 – 11/21/2025



[P1240114.JPG] – RHMW04 – 11/21/2025 – 1405

No fuel product observed. Water observed is clear in the bailer sample.




[P1240107.JPG] – NMW24 – 11/21/2025 – 0900

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

11/17/2025 – 11/21/2025



[P1240112.JPG] – NMW24 – 11/21/2025 – 1056

No fuel product observed. Water observed is clear in the bailer sample.



[P1050840.JPG] – RHMW20 – 11/21/2025 – 1136

No fuel product observed. Water observed is clear in the bailer sample.