

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**

**AECOM**

**12/01/2025 – 12/05/2025**



[P1030194.JPG] – RHMW01R Seal (Before Sampling) – 12/01/2025 – 0951



[P1030198.JPG] – RHMW01R Seal (After Sampling) – 12/01/2025 – 1154

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**

**AECOM**

**12/01/2025 – 12/05/2025**



[P1050845.JPG] – RHMW02 Seal (Before Sampling) – 12/01/2025 – 0857



[P1050849.JPG] – RHMW02 Seal (After Sampling) – 12/01/2025 – 1055

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**

**AECOM**

**12/01/2025 – 12/05/2025**



[P1050850.JPG] – RHMW21 Seal (Before Sampling) – 12/01/2025 – 1101



[P1050853.JPG] – RHMW21 Seal (After Sampling) – 12/01/2025 – 1322



**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**

**AECOM**

**12/01/2025 – 12/05/2025**



[P1030206.JPG] – RHMW03 Seal (Before Sampling) – 12/03/2025 – 1110



[P1030209.JPG] – RHMW03 Seal (After Sampling) – 12/03/2025 – 1239

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**

**AECOM**

**12/01/2025 – 12/05/2025**



[P1030202.JPG] – RHMW05 Seal (Before Sampling) – 12/03/2025 – 0928



[P1030205.JPG] – RHMW05 Seal (After Sampling) – 12/03/2025 – 1059

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**

**AECOM**

**12/01/2025 – 12/05/2025**



[P1050860.JPG] – RHP07 Seal (Before Sampling) – 12/03/2025 – 0912




[P1050864.JPG] – RHP07 Seal (After Sampling) – 12/03/2025 – 1054



**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**


**AECOM**

**12/01/2025 – 12/05/2025**



[P1030197.JPG] – RHMW01R – 12/01/2025 – 1014

No fuel product observed. Water observed is clear in the bailer sample.




[P1050847.JPG] – RHMW02 – 12/01/2025 – 0909

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

12/01/2025 – 12/05/2025



[P1050851.JPG] – RHMW21 – 12/01/2025 – 1152

No fuel product observed. Water observed is clear in the bailer sample.



[P1050858.JPG] – RHMW10 – 12/02/2025 – 1237


No fuel product observed. Water observed is clear in the bailer sample.



Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

12/01/2025 – 12/05/2025



[P1050856.JPG] – RHMW19 – 12/02/2025 – 0919

No fuel product observed. Water observed is clear in the bailer sample.




[P1240122.JPG] – RHP05 – 12/02/2025 – 1119

No fuel product observed. Water observed is clear in the bailer sample.

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**


**AECOM**

**12/01/2025 – 12/05/2025**



[P1030199.JPG] – RHP06 – 12/02/2025 – 1129

No fuel product observed. Water observed is clear in the bailer sample.




[P1240120.JPG] – RHP08 – 12/02/2025 – 0853

No fuel product observed. Water observed is clear in the bailer sample.

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**


**AECOM**

**12/01/2025 – 12/05/2025**



[P1030207.JPG] – RHMW03 – 12/03/2025 – 1117

No fuel product observed. Water observed is clear in the bailer sample.



[P1030203.JPG] – RHMW05 – 12/03/2025 – 0938


No fuel product observed. Water observed is clear in the bailer sample.



**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**


**AECOM**

**12/01/2025 – 12/05/2025**



[P1050862.JPG] – RHP07 – 12/03/2025 – 0929

No fuel product observed. Water observed is clear in the bailer sample.




[P1240125.JPG] – RHMW06 – 12/04/2025 – 1205

No fuel product observed. Water observed is clear in the bailer sample.

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**


**AECOM**

**12/01/2025 – 12/05/2025**



[P1030211.JPG] – RHP01 – 12/04/2025 – 0835

No fuel product observed. Water observed is clear in the bailer sample.




[P1030212.JPG] – RHP02 – 12/04/2025 – 1008

No fuel product observed. Water observed is clear in the bailer sample.

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**


**AECOM**

**12/01/2025 – 12/05/2025**



[P1050865.JPG] – RHP03 – 12/04/2025 – 1233

No fuel product observed. Water observed is clear in the bailer sample.



[P1050873.JPG] – RHMW08 – 12/05/2025 – 1031


No fuel product observed. Water containing Rhodamine WT from February dye tracer study injection.



**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**


**AECOM**

**12/01/2025 – 12/05/2025**



[P1050869.JPG] – RHMW09 – 12/05/2025 – 0813

No fuel product observed. Water observed is clear in the bailer sample.




[P1030213.JPG] – RHMW18 – 12/05/2025 – 0844

No fuel product observed. Water observed is clear in the bailer sample.

**Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos**

**AECOM**

**12/01/2025 – 12/05/2025**



[P1030215.JPG] – RHP04A – 12/05/2025 – 1104

No fuel product observed. Water observed is clear in the bailer sample.