

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

03/16/2026 – 03/20/2026



[P1030422.JPG] – RHMW01R Seal (Before Sampling) – 03/16/2026 – 0905



[P1030426.JPG] – RHMW01R Seal (After Sampling) – 03/16/2026 – 1112

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

03/16/2026 – 03/20/2026



[P1060122.JPG] – RHMW02 Seal (Before Sampling) – 03/16/2026 – 0836



[P1060124.JPG] – RHMW02 Seal (After Sampling) – 03/16/2026 – 0955

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

03/16/2026 – 03/20/2026



[P1060125.JPG] – RHMW21 Seal (Before Sampling) – 03/16/2026 – 1000



[P1060128.JPG] – RHMW21 Seal (After Sampling) – 03/16/2026 – 1125

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

03/16/2026 – 03/20/2026



[P1030448.JPG] – RHMW03 Seal (Before Sampling) – 03/18/2026 – 1152



[P1030453.JPG] – RHMW03 Seal (After Sampling) – 03/18/2026 – 1336

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

03/16/2026 – 03/20/2026



[P1060135.JPG] – RHMW05 Seal (Before Sampling) – 03/18/2026 – 0944



[P1060140.JPG] – RHMW05 Seal (After Sampling) – 03/18/2026 – 1137

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

03/16/2026 – 03/20/2026



[P1030440.JPG] – RHP07 Seal (Before Sampling) – 03/18/2026 – 0946




[P1030446.JPG] – RHP07 Seal (After Sampling) – 03/18/2026 – 1132


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

03/16/2026 – 03/20/2026



[P1030424.JPG] – RHMW01R – 03/16/2026 – 0954  
No fuel product observed. Water observed is clear in the bailer sample.




[P1060123.JPG] – RHMW02 – 03/16/2026 – 0842  
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

03/16/2026 – 03/20/2026



[P1060126.JPG] – RHMW21 – 03/16/2026 – 1007  
No fuel product observed. Water observed is clear in the bailer sample.




[P1030431.JPG] – RHMW19 – 03/17/2026 – 0907  
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

03/16/2026 – 03/20/2026



[P1030436.JPG] – RHMW10 – 03/17/2026 – 1252  
No fuel product observed. Water observed is clear in the bailer sample.




[P1060130.JPG] – RHP05 – 03/17/2026 – 0846  
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

03/16/2026 – 03/20/2026



[P1060133.JPG] – RHP06 – 03/17/2026 – 1158  
No fuel product observed. Water observed is clear in the bailer sample.




[P1030449.JPG] – RHMW03 – 03/18/2026 – 1207  
No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

03/16/2026 – 03/20/2026



[P1060136.JPG] – RHMW05 – 03/18/2026 – 1006  
No fuel product observed. Water observed is clear in the bailer sample.




[P1030442.JPG] – RHP07 – 03/18/2026 – 0957  
No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

03/16/2026 – 03/20/2026




[P1030459.JPG] – RHMW06 – 03/19/2026 – 1115

No fuel product observed. Water observed is clear in the bailer sample.




[P1030454.JPG] – RHP08 – 03/19/2026 – 0854

No fuel product observed. Water observed is clear in the bailer sample.



[P1240186.JPG] – RHP01 – 03/19/2026 – 1301  
No fuel product observed. Water observed is clear in the bailer sample.




[P1240185.JPG] – RHP02 – 03/19/2026 – 1108  
No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos


AECOM

03/16/2026 – 03/20/2026



[P1240184.JPG] – RHP03 – 03/19/2026 – 0915

No fuel product observed. Water observed is clear in the bailer sample.




[P1030460.JPG] – RHMW08 – 03/20/2026 – 0920

No fuel product observed. Water containing Rhodamine WT from February dye tracer study injection.


Red Hill – Monitoring Well Fuel Product Gauging and Mat Seal Verification Photos

AECOM

03/16/2026 – 03/20/2026



[P1060141.JPG] – RHMW09 – 03/20/2026 – 0844  
No fuel product observed. Water observed is clear in the bailer sample.



[P1030461.JPG] – RHMW20 – 03/20/2026 – 1137  
No fuel product observed. Water observed is clear in the bailer sample.