


Red Hill – Monitoring Well Fuel Product Gauging Photos


AECOM

04/27/2026 – 05/01/2026



[P1030534.JPG] – RHMW04 – 04/27/2026 – 0903

No fuel product observed. Water observed is clear in the bailer sample.




[P1240211.JPG] – RHMW17 – 04/28/2026 – 1127

No fuel product observed. Water observed is clear in the bailer sample.


Red Hill – Monitoring Well Fuel Product Gauging Photos

AECOM

04/27/2026 – 05/01/2026



[P1060213.JPG] – NMW24 – 04/28/2026 – 0804
No fuel product observed. Water observed is clear in the bailer sample.




[P1060214.JPG] – NMW25 – 04/28/2026 – 1005
No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging Photos


AECOM

04/27/2026 – 05/01/2026



[P1030536.JPG] – NMW26 – 04/29/2026 – 1149

No fuel product observed. Water observed is clear in the bailer sample. Small pieces of green debris from bailer floating at the water surface.




[P1240214.JPG] – NMW33 – 04/29/2026 – 0908

No fuel product observed. Water observed is clear in the bailer sample. Small pieces of organic debris at the water surface.

Red Hill – Monitoring Well Fuel Product Gauging Photos


AECOM

04/27/2026 – 05/01/2026



[P1240217.JPG] – NMW34 – 04/29/2026 – 1212

No fuel product observed. Water observed is clear in the bailer sample.




[P1060216.JPG] – NMW30 – 04/29/2026 – 0819

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Product Gauging Photos


AECOM

04/27/2026 – 05/01/2026



[P1240221.JPG] – RHMW20 – 04/30/2026 – 1155

No fuel product observed. Water observed is clear in the bailer sample.



[P1060218.JPG] – NMW32 – 04/30/2026 – 0821

No fuel product observed. Water observed is clear in the bailer sample.