

Red Hill – Monitoring Well Fuel Production Gauging Photos

AECOM

06/01/2026 - 06/05/2026



[P1030584.JPG] RHMW01R Seal (Before Sampling) – 06/01/2026 – 0847



[P1030587.JPG] RHMW01R Seal (After Sampling) – 06/01/2026 – 1045

Red Hill – Monitoring Well Fuel Production Gauging Photos

AECOM

06/01/2026 - 06/05/2026



[P1060299.JPG] RHMW02 Seal (Before Sampling) – 06/01/2026 – 0841



[P1060306.JPG] RHMW02 Seal (After Sampling) – 06/01/2026 – 1126

Red Hill – Monitoring Well Fuel Production Gauging Photos

AECOM

06/01/2026 - 06/05/2026



[P1030588.JPG] RHMW21 Seal (Before Sampling) – 06/01/2026 – 1100



[P1060310.JPG] RHMW21 Seal (After Sampling) – 06/01/2026 – 1239

Red Hill – Monitoring Well Fuel Production Gauging Photos

AECOM

06/01/2026 - 06/05/2026



[P1240252.JPG] RHMW03 Seal (Before Sampling) – 06/03/2026 – 0827



[P1240262.JPG] RHMW03 Seal (After Sampling) – 06/03/2026 – 1225

Red Hill – Monitoring Well Fuel Production Gauging Photos

AECOM

06/01/2026 - 06/05/2026



[P1240253.JPG] RHMW05 Seal (Before Sampling) – 06/03/2026 – 0844



[P1060315.JPG] RHMW05 Seal (After Sampling) – 06/03/2026 – 1133

Red Hill – Monitoring Well Fuel Production Gauging Photos

AECOM

06/01/2026 - 06/05/2026



[P1240254.JPG] RHP07 Seal (Before Sampling) – 06/03/2026 – 0849




[P1240256.JPG] RHP07 Seal (After Sampling) – 06/03/2026 – 1030

Red Hill – Monitoring Well Fuel Production Gauging Photos


AECOM

06/01/2026 - 06/05/2026



[P1030586.JPG] RHMW01R – 06/01/2026 – 0902

No fuel product observed. Water observed is clear in the bailer sample.




[P1060304.JPG] RHMW02 – 06/01/2026 – 0852

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Production Gauging Photos


AECOM

06/01/2026 - 06/05/2026



[P1060309.JPG] RHMW21 – 06/01/2026 – 1140

No fuel product observed. Water observed is clear in the bailer sample.




[P1240249.JPG] RHMW10 – 06/02/2026 – 0816

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Production Gauging Photos


AECOM

06/01/2026 - 06/05/2026



[P1240250.JPG] RHMW19 – 06/02/2026 – 1012

No fuel product observed. Water observed is clear in the bailer sample.




[P1030589.JPG] RHP05 – 06/02/2026 – 0805

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Production Gauging Photos


AECOM

06/01/2026 - 06/05/2026



[P1030592.JPG] RHP06 – 06/02/2026 – 0956

No fuel product observed. Water observed is clear in the bailer sample.




[P1060311.JPG] RHP08 – 06/02/2026 – 0816

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Production Gauging Photos

AECOM

06/01/2026 - 06/05/2026



[P1240261.JPG] RHMW03 – 06/03/2026 – 1117

No fuel product observed. Water observed is clear in the bailer sample.




[P1060313.JPG] RHMW05 – 06/03/2026 – 1007

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Production Gauging Photos


AECOM

06/01/2026 - 06/05/2026



[P1240255.JPG] RHP07 – 06/03/2026 – 0854

No fuel product observed. Water observed is clear in the bailer sample.




[P1060319.JPG] – RHMW06 – 06/04/2026 – 0950

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Production Gauging Photos


AECOM

06/01/2026 - 06/05/2026



[P1030599.JPG] RHP01 – 06/04/2026 – 1025

No fuel product observed. Water observed is clear in the bailer sample.




[P1030595.JPG] RHP02 – 06/04/2026 – 0918

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Production Gauging Photos


AECOM

06/01/2026 - 06/05/2026



[P1030594.JPG] RHP03 – 06/04/2026 – 0801

No fuel product observed. Water observed is clear in the bailer sample. Yellow color near water surface due to reflective PPE clothing.




[P1030603.JPG] RHMW09 – 06/05/2026 – 1033

No fuel product observed. Water observed is clear in the bailer sample.

Red Hill – Monitoring Well Fuel Production Gauging Photos

AECOM


06/01/2026 - 06/05/2026



RHMW18
6/5/26

[P1030601.JPG] RHMW18 – 06/05/2026 – 0826

No fuel product observed. Water observed is clear in the bailer sample.



RHMW08
6/5/26


[P1060324.JPG] RHMW08 – 06/05/2026 – 0943

No fuel product observed. Water containing Rhodamine WT from February 2025 dye tracer study injection.

Red Hill – Monitoring Well Fuel Production Gauging Photos

AECOM

06/01/2026 - 06/05/2026



[P1060322.JPG] RHP04A – 06/05/2026 – 0755

No fuel product observed. Water observed is clear in the bailer sample.